



HONDA



report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | HONDA          |
| Model               | ACCORD VTEC S  |
| Colour              | Red            |
| Year of manufacture | -              |
| Top speed           | 127 mph        |
| 0 - 60 mph          | 10.4 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 136 BHP             |
| Max. torque             | 175 Nm at 4.800 rpm |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 25.0 mpg            |
| Consumption extra urban | 40.4 mpg            |
| Consumption combined    | 33.2 mpg            |



LABEL UNKNOWN



## MOT history

|                  |   |
|------------------|---|
| MOT #22          | 2021-02-10 10:51  |
| MOT test number  | 831243746585  |
| Result           | ✓ Passed  |
| Next expiry date | 2022-02-09  |
| Advice           | Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))   |
| Advice           | Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))      |
| Advice           | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice           | Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))    |
| Advice           | Nearside Front Play in steering rack inner joint(s)                         |

|                         |   |
|-------------------------|---|
| MOT #21                 | 2021-02-10 10:51  |
| MOT test number         | 882927787426  |
| Result                  | ✗ Failed  |
| Pass with rectification | Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Advice                  | Rear Registration plate deteriorated but not likely to be misread (0.1 (b))   |
| Advice                  | Nearside Front Play in steering rack inner joint(s)                           |
| Advice                  | Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))      |
| Pass with rectification | Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))  |
| Advice                  | Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))     |
| Advice                  | Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))        |

|                 |   |
|-----------------|---|
| MOT #20         | 2020-01-07 12:16  |
| MOT test number | 714805848997  |
| Result          | ✓ Passed  |
| Minor           | Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) |
| Minor           | Offside Headlamp lens slightly defective (4.1.1 (b) (i))  |

**MOT #19**

2020-01-07 10:44

**MOT test number**

830663265371

**Result****✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))
- Fail** Offside Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #18**

2018-11-20 16:43

**MOT test number**

234934831427

**Result****✓ Passed**

- Advice** Nearside Front Fog lamp not working.
- Advice** Power steering component has slight seepage from a component Steering rack. (2.1.5 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Weep from large clip area. (6.1.7 (g) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Headlamp lens slightly defective Both lamps (4.1.1 (b) (i))

**MOT #17**

2018-11-20 11:01

**MOT test number**

486199501690

**Result****✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Front Headlamp lens slightly defective Both lamps (4.1.1 (b) (i))
- Fail** Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively Both wipers (3.4 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Fog lamp not working.
- Advice** Power steering component has slight seepage from a component Steering rack. (2.1.5 (a))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated Weep from large clip area. (6.1.7 (g) (i))

**MOT #16**

2017-11-09 15:01

**MOT test number**

771807979111

**Result****✓ Passed**

- Advice** Offside Front Inner Constant velocity boot leaking grease out from behind clamp, suspect clamp not tight enough.
- Advice** Rear registration plate deteriorated but not likely to be misread Advise replacement. (6.3.1d)
- Advice** Nearside Front Wiper blade split and lightly smearing screen, advise new.
- Advice** Offside Front Wiper blade lightly smearing screen.
- Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)

**MOT #15**

2017-11-09 15:01

**MOT test number**

436128401269

**Result****✗ Failed****Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Front Wiper blade lightly smearing screen.**Advice** Rear registration plate deteriorated but not likely to be misread Advise replacement. (6.3.1d)**Advice** Offside Front Inner Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Wiper blade split and lightly smearing screen, advise new.**Advice** Offside Front Inner Constant velocity boot leaking grease out from behind clamp, suspect clamp not tight enough.**MOT #14**

2016-11-14 10:58

**MOT test number**

724979824196

**Result****✓ Passed****Advice** Offside inner CV boot leaking slight grease**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #13**

2016-11-12 12:25

**MOT test number**

305172371579

**Result****✗ Failed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside inner CV boot leaking slight grease**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



|                        |                  |
|------------------------|------------------|
| <b>MOT #12</b>         | 2015-10-24 09:55 |
| <b>MOT test number</b> | 954169882934     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #11</b>         | 2014-11-15 09:35 |
| <b>MOT test number</b> | 437219614339     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #10</b>         | 2013-11-11 14:57 |
| <b>MOT test number</b> | 956655513353     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #9</b>          | 2012-11-09 13:51 |
| <b>MOT test number</b> | 906754112384     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #8</b>          | 2011-11-09 16:15 |
| <b>MOT test number</b> | 878383011324     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #7</b>          | 2010-11-04 12:59 |
| <b>MOT test number</b> | 270598800373     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #6</b>          | 2009-11-11 14:46 |
| <b>MOT test number</b> | 420195119442     |
| <b>Result</b>          | ✓ Passed         |
| <b>MOT #5</b>          | 2008-11-07 11:03 |
| <b>MOT test number</b> | 352382218314     |
| <b>Result</b>          | ✓ Passed         |



|  |                  |
|--|------------------|
| MOT #4   | 2007-11-12 16:14 |
| MOT test number  | 523816417395     |
| Result   | ✓ Passed         |
| MOT #3   | 2006-11-07 14:34 |
| MOT test number  | 592811316321     |
| Result   | ✓ Passed         |
| MOT #2   | 2005-11-17 14:24 |
| MOT test number  | 112431625359     |
| Result   | ✓ Passed         |
| <div>Notice Front tyre profiles different to rear.</div>                           |                  |
| MOT #1   | 2005-11-16 10:29 |
| MOT test number  | 523120125351     |
| Result   | ✗ Failed         |
| <div>Fail Nearside Rear Brake cable has a seized clevis joint pivot (3.5.1c)</div> |                  |



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this HONDA had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | X665FDD    |
| Plate since          | 2019-03-29 |
| Current registration | X665FDD    |
| Plate since          | 2019-03-29 |

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 23                       |
| First mileage registration | 2000-09-29               |
| Last registration          | 2021-02-10               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2000-09-29 | 10 mi     |
| Registration #2  | 2005-11-16 | 28.289 mi |
| Registration #3  | 2005-11-17 | 28.289 mi |
| Registration #4  | 2006-11-07 | 29.044 mi |
| Registration #5  | 2007-11-12 | 29.722 mi |
| Registration #6  | 2008-11-07 | 30.173 mi |
| Registration #7  | 2009-11-11 | 30.808 mi |
| Registration #8  | 2010-11-04 | 31.612 mi |
| Registration #9  | 2011-11-09 | 32.106 mi |
| Registration #10 | 2012-11-09 | 32.618 mi |
| Registration #11 | 2013-11-11 | 32.830 mi |
| Registration #12 | 2014-11-15 | 33.050 mi |
| Registration #13 | 2015-11-15 | 33.050 mi |
| Registration #14 | 2016-11-15 | 33.050 mi |
| Registration #15 | 2017-11-15 | 33.050 mi |
| Registration #16 | 2018-11-15 | 33.050 mi |
| Registration #17 | 2019-11-15 | 33.050 mi |
| Registration #18 | 2020-11-15 | 33.050 mi |
| Registration #19 | 2021-02-10 | 33.050 mi |
| Registration #20 |            |           |
| Registration #21 |            |           |
| Registration #22 |            |           |
| Registration #23 |            |           |

More info >



Safety ratings

|             |                                 |
|-------------|---------------------------------|
| NCAP rating | ★★★★☆                           |
| Video       | <a href="#">see crash video</a> |



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1750 mm |
| Height      | 1430 mm |
| Length      | 4595 mm |
| Kerb weight | 1380 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 65 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 4                     |
| Number of axles    | 2                     |
| Engine number      | F18B2E124888          |