





report date: 2024-03-28

General information

Make	MAZDA
Model	5 D TS2 7STR
Colour	Silver
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/17



MOT history

MOT expiry date	2021-03-10
MOT pass rate	50 %
MOT passed	11
Failed MOT tests	11
Total advice items	68
Total items failed	39

MOT #22		2020-03-09 16:49
MOT test	number	963089836206
Result		✓ Passed
Next expi	ry date	2021-03-10
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Corrosion to all under the body and suspensions components	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))		
Advice	O/s/r and o/s/f wheels arch corroded	
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice	Both side sill panels cover fitted obscuring some components	

CarCheck.co.uk page 2/17



report date: 2024-03-28

MOT #21 2020-03-06 12:45

MOT test number 236675037036

Result X Failed

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice O/s/r and o/s/f wheels arch corroded

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Fail Offside Headlamp lens seriously defective (4.1.1 (b) (ii))

Advice Both side sill panels cover fitted obscuring some components

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Offside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Fail Nearside Headlamp aim not tested (4.1.2 (b))

Advice Corrosion to all under the body and suspensions components

Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Fail Nearside Rear Lower Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

Fail Offside Front Lower Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

CarCheck.co.uk page 3/17



Advice

Offside Rear Fuel Pipe/s corroded

SC56RXU

report date: 2024-03-28

MOT #20

MOT test number

238853853595

Result

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Rear Coil spring corroded X2 (5.3.1 (b) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #19 2019-03-08 17:06 **MOT test number** 429260126325 Result ★ Failed Fail Supplementary restraint system warning lamp indicates a fault (7.1.6 (a)) Fail Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Fail 205/50 17 (5.2.3 (d) (i)) Advice Front Oil leak, but not excessive (8.4.1 (a) (i)) Advice Rear Coil spring corroded X2 (5.3.1 (b) (i)) Advice Offside Rear Fuel Pipe/s corroded Electronic stability control switch not functioning correctly DSC (7.12 (d)) Fail Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50 17 (5.2.3 (d) (i)) Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 205/50 17 (5.2.3 (d) (i)) Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

CarCheck.co.uk page 4/17



report date: 2024-03-28

MOT #18 2019-03-08 10:04

MOT test number 973807950659

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge has sidewall damage recommend replace ASAP (5.2.3 (e))

Fail Offside Front Oil leaking excessively from engine dripping & contaminating susp, bushes (8.4.1 (a) (i))

Advice Rear Lower vehicle has corrosion all over under body

Advice Offside Front Tyre worn close to legal limit/worn on edge has sidewall damage recommend replace ASAP (5.2.3 (e))

Fail Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt spraying grease (6.1.7 (g) (ii))

MOT #17 2018-03-02 14:38

MOT test number 534777459014

Result

Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Metered smoke emissions high

MOT #16 2018-03-02 08:04

MOT test number 233200988517

Result ★ Failed

Advice Metered smoke emissions high

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 5/17



report date: 2024-03-28

MOT test number

Result

Advice Exhaust system corroded

Advice Engine oil leak

Advice Underside of vehicle becoming corroded

MOT #14 2017-02-03 11:53 **MOT** test number 701455719692 Result × Failed **Advice** Underside of vehicle becoming corroded Fail Nearside Front Front position lamp(s) not working (1.1.A.3b) Fail Nearside Rear Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt Also has slight play (2.4.G.2) Advice Exhaust system corroded Fail Offside Front Headlamp not working on dipped beam (1.7.5a) Advice Engine oil leak

MOT #13		2016-02-04 13:50
MOT test	number	326664286089
Result		✓ Passed
Advice	ADVISE ENGINE OIL LEAKS	
Advice	ADVISE BRAKE PEDAL RUBBER CONDITION	
Advice	CORROSION ON UNDERSIDE TO SILLS CHASSIS, SUSPENSION AND EXHAUST	
Advice	ADVISE BATTERY CARRIER SEEMS A LITTLE LOOSE	
Advice	ADVISE BOTH FRONT TYRES BALD ON INNER EDGES, ESPECIALLY NEARSIDE	

CarCheck.co.uk page 6/17



report date: 2024-03-28

MOT #12 2016-02-04 11:53

MOT test number 731900958277

Result X Failed

Fail Offside Front Front position lamp(s) not working SIDE LAMP NOT WORKING (1.1.A.3b)

Advice ADVISE ENGINE OIL LEAKS

Advice ADVISE BRAKE PEDAL RUBBER CONDITION

Fail Offside Front Brake pipe inadequately clipped FLEXI BRAKE PIPE NOT SECURE (3.6.B.1)

Advice CORROSION ON UNDERSIDE TO SILLS CHASSIS, SUSPENSION AND EXHAUST

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Advice ADVISE BATTERY CARRIER SEEMS A LITTLE LOOSE

Advice ADVISE BOTH FRONT TYRES BALD ON INNER EDGES, ESPECIALLY NEARSIDE

MOT #11 2015-01-29 15:49

MOT test number 388069225076

Result

Passed

CarCheck.co.uk page 7/17



report date: 2024-03-28

MOT #10 2015-01-23 14:42 346043725004 **MOT** test number Result **★** Failed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Advice Front Brake pad(s) wearing thin (3.5.1g) Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2) Fail

MOT #9	2014-01-15 14:53
MOT test number	189715314458
Result	✓ Passed
Notice Oil leak	

MOT #8		2013-02-21 15:28
MOT test	number	235822153010
Result		✓ Passed
Notice	Exhaust system slightly deteriated	
Notice	Nearside front tyre outer sidewall slightly dam aged	
Notice	Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 8/17



report date: 2024-03-28

MOT #7 2013-02-18 16:16 **MOT** test number 695269743067 Result × Failed **Notice** Nearside front tyre outer sidewall slightly dam aged Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c) Notice Child seat fitted not allowing full inspection of adult belt Nearside Front position lamp(s) not working (1.1.A.3b) Fail Fail Nearside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) **Notice** Exhaust system slightly deteriated Fail Offside Front Headlamp not working on dipped beam (1.7.5a)

MOT #6

MOT test number

168429842433

Result

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)

MOT #5 2012-02-08 14:55 **MOT** test number 219149432090 X Failed Result Fail Nearside Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2) Fail Offside Headlamp not working on dipped beam (1.7.5a) **Advice** Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1) Fail Nearside Rear Suspension arm has excessive play in a pin/bush (2.4.G.2) Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

CarCheck.co.uk page 9/17



SC56RXU

report date: 2024-03-28

MOT #4	2011-01-20 15:39
MOT test number	637170521037
Result	✓ Passed
MOT #3	2011-01-20 11:38
MOT test number	339430121084
Result	× Failed
Fail Horn not working (1.6.2a)	
Fail Offside Headlamp aim too low (1.8)	
Fail Nearside Headlamp aim too low (1.8)	
Fail Brakes imbalanced across an axle (3.7.B.5b)	

MOT #2	2010-01-28 10:25	
MOT test number	503638520008	
Result	✓ Passed	
MOT #1	2010-01-28 09:49	
MOT test number	692768620088	
Result	× Failed	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)		
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		

CarCheck.co.uk page 10/17



Tax & MOT check





Expired: 10 March 2021

Tax status	Expired at 6 January 2021
Days left	1209 days too late
MOT expiry date	10 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 11/17



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-01-31
Last registration	2020-03-09
Complete history	See info



Registration #1	2007-01-31	28 mi
Registration #2	2010-01-28	51.620 mi
Registration #3	2010-01-28	51.620 mi
Registration #4	2011-01-20	67.849 mi
Registration #5	2011-01-20	67.849 mi
Registration #6	2012-02-08	79.293 mi
Registration #7	2012-02-18	79.293 mi
Registration #8	2013-02-18	89.246 mi
Registration #9	2013-02-21	89.246 mi
Registration #10	2014-01-15	102.753 mi
Registration #11	2015-01-23	118.501 mi
Registration #12	2015-01-29	118.598 mi
Registration #13		11.177 es
Registration #14		71.777 es
Registration #15		71.777 66
Registration #16		77,777 46
Registration #17		11.177 es
Registration #18		71.777 es
Registration #19		71.777 66
Registration #20		11.777 46
Registration #21		11.771 46
Registration #22		0.074
Registration #23		77.777 es


More info >

CarCheck.co.uk page 16/17



Safety ratings

NCAP rating	****



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1645 kg
Max. allowed weight	2225 kg

Additional information

· · · · · · · · · · · · · · · · · · ·	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 261439

CarCheck.co.uk page 17/17