



TOYOTA

EN53CXA

report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX 280 EX MWB 4WD DCB P/U
Colour	Green
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	999 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-10-20
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2022-03-13
-----------------	------------

MOT pass rate	60 %
---------------	------

MOT passed	15
------------	----

Failed MOT tests	10
------------------	----

Total advice items	75
--------------------	----

Total items failed	36
--------------------	----

MOT #25	2021-07-19 12:05
---------	------------------

MOT test number	133477344365
-----------------	--------------

Result	✗ Failed
--------	----------

**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**Fail** Central Prop shaft bearing excessively worn (6.1.7 (b) (i))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Fail** Exhaust has a major leak of exhaust gases Centre box (6.1.2 (a))

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Rear Wheel bearing slightly noisy (5.1.3 (b) (i))

**Advice** Rear Shock absorbers has a reduced damping effect (5.3.2 (d))

**Advice** Oil leak, but not excessive Sump (8.4.1 (a) (i))

**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

**MOT #24** 2021-03-11 16:48**MOT test number** 940629503923**Result** ✓ Passed

- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Oil leak, but not excessive Sump (8.4.1 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material To load valve (1.1.11 (c))

**MOT #23** 2021-03-05 16:20**MOT test number** 138459948265**Result** ✗ Failed

- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Oil leak, but not excessive Sump (8.4.1 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material To load valve (1.1.11 (c))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Fail** Steering box has excessive free play detected at the steering wheel (steering box fitted) (2.3 (a) (i))
- Fail** Offside Rear Leaf spring fractured (5.3.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #22** 2020-03-11 08:56**MOT test number** 115023760649**Result** ✓ Passed

**MOT #21**

2020-03-06 13:39

**MOT test number**

435164504635

**Result**

✗ Failed

- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Nearside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #20**

2019-03-08 12:19

**MOT test number**

834155682668

**Result**

✓ Passed

- Advice** Offside Rear Shock absorbers has a slightly worn bush top and bottom (5.3.2 (c))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush top and bottom (5.3.2 (c))
- Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Rear diff bearings very noisy
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #19**

2019-03-05 10:09

**MOT test number**

146405737489

**Result****✗ Failed****Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Rear diff bearings very noisy**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis (5.3.6 (a) (i))**Fail** Nearside Rear Leaf spring shackle pin or bush excessively worn at rear (5.3.4 (a) (i))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Nearside Rear Shock absorbers has a slightly worn bush top and bottom (5.3.2 (c))**Fail** Nearside Headlamp insecure (4.1.1 (c))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Fail** Offside Rear Leaf spring shackle pin or bush excessively worn at rear (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Shock absorbers has a slightly worn bush top and bottom (5.3.2 (c))



MOT #18	2018-02-21 14:05
MOT test number	777892452027
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Offside Rear Inner Steering component mounting prescribed area is corroded but not considered excessive sill (2.2.C.1h)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #17	2018-02-21 14:05
MOT test number	423965157297
Result	✗ Failed
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Items removed from driver's view prior to test
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Advice	Offside Rear Inner Steering component mounting prescribed area is corroded but not considered excessive sill (2.2.C.1h)
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #16

2017-03-14 15:25

MOT test number

720228637238

Result

✓ Passed

- Advice

Rear Exhaust has a minor leak of exhaust gases box (7.1.2)
- Advice

Front propshaft front joint slight play
- Advice

Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice

Nearside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement rear bush (2.4.B.2)
- Advice

Supplementary Restraint System warning lamp does not illuminate (5.4.2)
- Advice

Brake pipe slightly corroded all around rear comp valve (3.6.B.2c)
- Advice

Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice

Nearside battery slightly insecure
- Advice

Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice

Offside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement rear bush (2.4.B.2)
- Advice

Nearside Rear Brake pipe slightly corroded on axle (3.6.B.2c)



**MOT #15**

2017-03-14 10:12

**MOT test number**

344223426978

**Result****✗ Failed****Fail** Rear fog lamp tell tale not working (1.3.1b)**Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement rear bush (2.4.B.2)**Advice** Supplementary Restraint System warning lamp does not illuminate (5.4.2)**Advice** Brake pipe slightly corroded all around rear comp valve (3.6.B.2c)**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Nearside battery slightly insecure**Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Offside Rear Leaf spring has a slightly deteriorated shackle pin rubber bush not resulting in excessive movement rear bush (2.4.B.2)**Advice** Nearside Rear Brake pipe slightly corroded on axle (3.6.B.2c)**Advice** Front propshaft front joint slight play**Advice** Rear Exhaust has a minor leak of exhaust gases box (7.1.2)**MOT #14**

2017-02-23 11:02

**MOT test number**

317588657226

**Result****✗ Failed****Fail** Offside Rear fog lamp not working (1.3.2b)

**MOT #13** 2016-03-02 11:44**MOT test number** 147040174334**Result** ✓ Passed**MOT #12** 2015-02-26 16:23**MOT test number** 816157555054**Result** ✓ Passed**MOT #11** 2014-02-07 15:12**MOT test number** 279588934036**Result** ✓ Passed**MOT #10** 2013-02-11 16:02**MOT test number** 686152043014**Result** ✓ Passed**Notice** Prop-shaft universal joint worn**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2012-02-03 17:22**MOT test number** 998164232086**Result** ✓ Passed**Advice** Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front uj joint slightly worn

**MOT #8**

2012-02-01 11:45

**MOT test number**

296272932053

**Result**

✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear Leaf spring has excessive wear in a shackle pin and/or bush (2.4.B.2)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear Leaf spring has excessive wear in a shackle pin and/or bush (2.4.B.2)
- Fail** Offside Rear Braking system leaking (3.6.A.1)

**MOT #7**

2011-02-07 14:12

**MOT test number**

938448331012

**Result**

✓ Passed

- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #6**

2011-01-31 11:41

**MOT test number**

998751431069

**Result**

✗ Failed

- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front constant velocity joint gaiter split (2.5.C.1a)
- Fail** Offside Rear reflector missing (1.5.1a)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Offside Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)
- Advice** Centre Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Nearside Headlamp aim too high (1.8)



<b>MOT #5</b>	2010-01-29 16:57
---------------	------------------

<b>MOT test number</b>	593789620047
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2010-01-29 16:57
---------------	------------------

<b>MOT test number</b>	354309320052
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

<b>Pass with rectification</b>	Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)
--------------------------------	--

<b>MOT #3</b>	2009-01-14 14:42
---------------	------------------

<b>MOT test number</b>	313444319017
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #2</b>	2008-01-16 12:30
---------------	------------------

<b>MOT test number</b>	732426218063
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2006-12-12 13:26
---------------	------------------

<b>MOT test number</b>	461556346400
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Tax & MOT check

✕  
Untaxed

Tax expired:  
6 July 2021

✕  
MOT

Expired:  
13 March 2022

Tax status	Expired at 6 July 2021
Days left	1027 days too late
MOT expiry date	13 March 2022
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-01-05
Last registration	2021-07-19
Complete history	<a href="#">See info</a>



Registration #1	2004-01-05	26 mi
Registration #2	2006-12-12	67.224 mi
Registration #3	2008-01-16	86.620 mi
Registration #4	2009-01-14	103.454 mi
Registration #5	2010-01-29	134.662 mi
Registration #6	2011-01-31	152.984 mi
Registration #7	2011-02-07	152.985 mi
Registration #8	2012-02-01	165.783 mi
Registration #9	2012-02-03	165.812 mi
Registration #10	2013-02-11	174.709 mi
Registration #11	2014-02-07	181.510 mi
Registration #12	2015-02-26	119.175 mi
Registration #13	2016-03-02	202.192 mi
Registration #14	2016-03-02	202.192 mi
Registration #15	2016-03-02	202.192 mi
Registration #16	2016-03-02	202.192 mi
Registration #17	2016-03-02	202.192 mi
Registration #18	2016-03-02	202.192 mi
Registration #19	2016-03-02	202.192 mi
Registration #20	2016-03-02	202.192 mi
Registration #21	2016-03-02	202.192 mi
Registration #22	2016-03-02	202.192 mi
Registration #23	2016-03-02	202.192 mi
Registration #24	2016-03-02	202.192 mi
Registration #25	2016-03-02	202.192 mi
Registration #26	2016-03-02	202.192 mi

**More info** >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1700 mm
Height	1785 mm
Length	4785 mm
Kerb weight	1715 kg
Max. allowed weight	2780 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	6
Number of axles	2
Engine number	2KD1072178