



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SE
Colour	Silver
Year of manufacture	-
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg





Internet history

Entry 1

Date	2021-08-08
Pictures	21
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history****MOT #19** 2022-08-04 09:47**MOT test number** 433007702772**Result** ✗ Failed

**Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner and outer sill (5.3.6 (a) (i))

**Advice** General corrosion under vehicle

**Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

**Advice** Pas pump noisy

**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

**MOT #18** 2021-07-31 13:40**MOT test number** 604456193190**Result** ✓ Passed**MOT #17** 2021-07-30 11:13**MOT test number** 103712288716**Result** ✗ Failed

**Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Offside Front Driver's side mirror loose

**Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Nearside Front Suspension arm pin or bush excessively worn wish bone arm bush (5.3.4 (a) (i))

**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Advice** Offside Front Suspension arm pin or bush excessively worn wish bone arm bush (5.3.4 (a) (i))

**MOT #16**

2021-06-28 10:57

**MOT test number**

626056073896

**Result****✗ Failed**

**Fail** Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Fail** Offside Front Suspension arm pin or bush excessively worn wish bone arm bush (5.3.4 (a) (i))

**Fail** Nearside Front Suspension arm pin or bush excessively worn wish bone arm bush (5.3.4 (a) (i))

**MOT #15**

2020-06-23 14:53

**MOT test number**

836721931169

**Result****✓ Passed**

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced both (5.3.3 (b) (i))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2020-06-23 12:39

**MOT test number**

546169090561

**Result****✗ Failed**

**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced both (5.3.3 (b) (i))

**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**Fail** Offside Rear Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))



MOT #13	2019-06-17 12:41
MOT test number	690759357685
Result	✓ Passed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #12	2019-06-14 10:12
MOT test number	527328650402
Result	✗ Failed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Position lamp not working (4.2.1 (a))
Fail	Offside Rear Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))
Fail	Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Nearside Rear Anti-roll bar ball joint likely to become detached (5.3.4 (a) (ii))
Fail	Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #11** 2018-06-26 11:32**MOT test number** 198880346115**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Nail in tyre**Advice** High level stop lamp inop.**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10** 2017-05-23 11:24**MOT test number** 109783163839**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #9** 2016-05-25 09:29**MOT test number** 582014063016**Result** ✓ Passed**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Front Front suspension ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #8** 2015-06-01 11:13**MOT test number** 497512355168**Result** ✓ Passed

**MOT #7** 2015-06-01 11:13**MOT test number** 577822755132**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**MOT #6** 2014-06-23 11:36**MOT test number** 978214474145**Result** ✓ Passed**MOT #5** 2013-06-28 10:19**MOT test number** 309759873171**Result** ✓ Passed**Advice** Offside Outer Rear Anti-roll bar linkage worn but not seriously weakened (2.4.G.1)**MOT #4** 2012-07-17 14:37**MOT test number** 128339092164**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Brake pedal has slight travel.**MOT #3** 2011-07-19 09:53**MOT test number** 126940701240**Result** ✓ Passed**Notice** Nearside front and offside front tyre sidewalls slightly perished (cracking). ..**MOT #2** 2010-08-02 15:11**MOT test number** 473584210235**Result** ✓ Passed



MOT #1	2009-07-28 14:09
MOT test number	371419909458
Result	✓ Passed





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-07-29
Last registration	2022-08-04
Complete history	<a href="#">See info</a>



Registration #1	2005-07-29	17 mi
Registration #2	2009-07-28	14.159 mi
Registration #3	2010-08-02	19.177 mi
Registration #4	2011-07-19	23.440 mi
Registration #5	2012-07-17	28.355 mi
Registration #6	2013-06-28	33.090 mi
Registration #7	2014-06-23	37.585 mi
Registration #8	2015-06-01	42.230 mi
Registration #9	2016-05-25	46.309 mi
Registration #10	2017-05-23	50.653 mi
Registration #11	2018-05-23	55.000 mi
Registration #12	2019-05-23	59.347 mi
Registration #13	2020-05-23	63.694 mi
Registration #14	2021-05-23	68.041 mi
Registration #15	2022-05-23	72.388 mi
Registration #16	2023-05-23	76.735 mi
Registration #17	2024-05-23	81.082 mi
Registration #18	2025-05-23	85.429 mi
Registration #19	2026-05-23	89.776 mi
Registration #20	2027-05-23	94.123 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1457 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	K20A91004116