



**H266JPD**

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TDI HT
Colour	Blue
Year of manufacture	1991
Gearbox	-Manual

Engine & fuel consumption

Power	107 BHP
Engine capacity	2.495 cc
Cylinders	4
Fuel type	Diesel





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-28
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	57 %
MOT passed	17
Failed MOT tests	13
Total advice items	79
Total items failed	47

MOT #30	2023-10-27 07:48
MOT test number	793247516453
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #29**

2023-10-24 10:44

**MOT test number**

581395650392

**Result****✗ Failed**

- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- MAJOR** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))
- MAJOR** Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))
- MAJOR** Central Front Seat belt missing (7.1.2 (a))
- MAJOR** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- MAJOR** Offside Rear Brake drum contaminated (1.1.14 (b))
- MAJOR** Nearside Front Direction indicator not working (4.4.1 (a) (ii))
- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

**MOT #28**

2022-10-31 13:08

**MOT test number**

551739057389

**Result****✓ Passed**

- Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))

**MOT #27**

2022-10-28 16:18

**MOT test number**

820805833322

**Result****✗ Failed**

- Advice** Steering box has slight free play detected at steering wheel (2.3 (a) (i))
- MAJOR** Nearside Front Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))

**MOT #26**

2021-12-09 14:30

**MOT test number**

266793335116

**Result**

✓ Passed

**Advice**

Underside coated in underseal not allowing full inspection.

**MOT #25**

2021-01-20 16:36

**MOT test number**

700974722257

**Result**

✓ Passed

**Advice**

Steering damper leaking

**Advice**

Nearside Front Track rod end ball joint has slight play Rear (2.1.3 (b) (i))

**MOT #24**

2021-01-15 11:31

**MOT test number**

518646349138

**Result**

✗ Failed

**MAJOR** Nearside Upper Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MAJOR** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MAJOR** Nearside Rear Upper Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Advice**

Steering damper leaking

**MAJOR** Offside Upper Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MAJOR** Nearside Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**Advice**

Nearside Front Track rod end ball joint has slight play Rear (2.1.3 (b) (i))

**MAJOR** Offside Front Inner Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MAJOR** Offside Upper Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))

**MOT #23** 2020-01-24 17:16**MOT test number** 385445634295**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #22** 2020-01-10 09:37**MOT test number** 497431397533**Result** ✗ Failed

**MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))

**MAJOR** Steering box has excessive free play detected at the steering wheel (steering box fitted) (2.3 (a) (i))

**Advice** Steering linkage ball joint has slight play steering arm off steering box (2.1.3 (b) (i))

**Minor** Steering box leaking oil (2.1.1 (e) (i))

**MOT #21** 2019-01-24 11:40**MOT test number** 526705314456**Result** ✓ Passed

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Advice** Note has had weld repairs to chassis

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))



MOT #20	2017-06-05 12:04
MOT test number	119357789480
Result	✓ Passed
Advice	Nearside Rear Bump stop missing
Advice	Chassis is heavily coated with underseal / waxoil , not allowing full inspection of welded repairs
Advice	Nearside Front Track rod end ball joint has slight play (2.2.B.1f)
Advice	Offside Rear Bump stop missing

**MOT #19**

2017-05-24 10:37

**MOT test number**

167230552632

**Result****✗ Failed**

**Fail** Offside Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt On drop arm of steering box (2.2.C.1c)

**Advice** Offside Rear Bump stop missing

**Fail** Offside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings Above new outrigger (6.1.B.2)

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Offside Rear Suspension component mounting prescribed area is inadequately repaired (2.4.A.3)

**Fail** Nearside Front Brake pipe excessively corroded On top of chassis rail under bonnet (3.6.B.2c)

**Advice** Nearside Rear Bump stop missing

**Fail** Offside Front Axle swivel joint has excessive play in a swivel pin (2.5.A.3b)

**Fail** Nearside Headlamp aim too low (1.8)

**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)

**Advice** Chassis is heavily coated with underseal / waxoil , not allowing full inspection of welded repairs

**Fail** Nearside Rear Suspension component mounting prescribed area is inadequately repaired (2.4.A.3)

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Fail** Offside Headlamp aim too high (1.8)

**Fail** Offside Front Axle swivel joint has excessive play (2.5.A.3b)



**MOT #18**

2016-08-17 08:59

**MOT test number**

332211758860

**Result**

✗ Failed

- Fail** Offside Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings chassis (6.1.B.2)
- Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)
- Fail** Fuel system component leaking under bonnet (7.2.3)
- Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings x member (6.1.B.2)
- Fail** Rear Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)
- Fail** Emissions not tested tail pipe missing (7.3.A.1)
- Advice** Nearside Front Vehicle structure has slight corrosion (6.1.B.2)
- Fail** Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

**MOT #17**

2015-08-19 09:56

**MOT test number**

747221035207

**Result**

✓ Passed

**MOT #16**

2014-07-22 12:33

**MOT test number**

378883804207

**Result**

✓ Passed

- Advice** Offside Rear Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Ball joint has slight play (2.2.B.1f)
- Advice** Offside Front Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

**MOT #15**

2013-03-28 12:33

**MOT test number**

859027483095

**Result**

✓ Passed

**MOT #14**

2013-02-20 17:11

**MOT test number**

498341653094

**Result****✗ Failed****Fail** Nearside Rear Mechanical brake component has restricted free movement (3.5.1k)**Notice** Both front brake calipers corroded**Notice** Near side stepping board bracket broken**Notice** Off side front wheel bearing play**Fail** Ball joint has excessive play (2.2.B.1f)**Fail** Nearside Outer Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** Front & rear suspension coil springs corroded**Notice** Under side corrosion throughout chassis frame**Notice** Front brake disc corroded**Fail** Steering box has a significant oil leak (2.2.D.2e)**Notice** Oil leak**Fail** Fuel system component leaking (7.2.3)**MOT #13**

2012-02-27 15:43

**MOT test number**

126138152421

**Result****✓ Passed****Advice** Front Ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**MOT #12**

2011-02-01 15:10

**MOT test number**

698882031012

**Result****✓ Passed**

**MOT #11**

2011-02-01 12:14

**MOT test number**

419332531023

**Result**

✗ Failed

**Fail** Power steering component(s) leaking from a failed seal (2.3.3b)**Fail** Nearside rear brake binding (3.7.B.1)**MOT #10**

2010-02-05 14:05

**MOT test number**

620926630062

**Result**

✓ Passed

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Chassis is rusty all over**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight play in drop arm ball joint**MOT #9**

2010-02-04 17:05

**MOT test number**

522435930081

**Result**

✗ Failed

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Chassis is rusty all over**Fail** Nearside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight play in drop arm ball joint**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #8**

2010-01-18 13:37

**MOT test number**

100878610023

**Result**

✗ Failed

- Fail** Nearside Rear Brake back plate(s) securing device excessively deteriorated (3.5.1j)
- Notice** Nearside floor corroded
- Fail** Offside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Nearside Rear Vehicle structure has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
- Fail** Power steering component(s) leaking (2.3.3b)
- Notice** Offside front wheel bearing slight play
- Fail** Nearside Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Offside Front Vehicle structure has an unsatisfactory modification, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)
- Fail** Rear Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #7**

2009-01-13 08:12

**MOT test number**

124213119459

**Result**

✓ Passed

- Notice** Rear exhaust box corroded

**MOT #6** 2009-01-08 09:37**MOT test number** 100748609049**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Nearside rear chassis corroded**Fail** Centre Front Parking brake is not capable of being maintained in operation by direct mechanical action only (3.1.2)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Notice** Rear exhaust box corroded**MOT #5** 2008-01-02 16:54**MOT test number** 310752208002**Result** ✓ Passed**Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**MOT #4** 2007-01-02 16:26**MOT test number** 954602007090**Result** ✓ Passed**MOT #3** 2007-01-02 09:15**MOT test number** 354762607066**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**MOT #2** 2006-01-04 13:47**MOT test number** 100994306435**Result** ✓ Passed



MOT #1 2006-01-03 15:22

MOT test number 792443406005

Result ✗ Failed

- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Notice** Offside rear brake slight binding
- Fail** Nearside Front Headlamp aim too low when the centre of the headlamp is below 850mm from the ground (1.6.C3)
- Notice** Slight oil leak from off side front hub seal
- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
30 October 2024

<b>Tax status</b>	Valid until 1 December
-------------------	------------------------

<b>Days left</b>	215
------------------	-----

<b>MOT expiry date</b>	30 October 2024
------------------------	-----------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	32
First mileage registration	1991-01-15
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	1991-01-15	14 mi
Registration #2	2006-01-03	37.499 mi
Registration #3	2006-01-04	37.499 mi
Registration #4	2007-01-02	38.958 mi
Registration #5	2007-01-02	38.958 mi
Registration #6	2008-01-02	40.163 mi
Registration #7	2009-01-08	41.603 mi
Registration #8	2009-01-13	41.603 mi
Registration #9	2010-01-18	43.185 mi
Registration #10	2010-02-04	43.209 mi
Registration #11	2010-02-05	43.227 mi
Registration #12	2011-02-01	44.696 mi
Registration #13	2011-02-01	44.700 mi
Registration #14	2012-02-27	46.233 mi
Registration #15	2013-02-20	47.518 mi
Registration #16	2013-03-28	47.579 mi
Registration #17	2013-03-28	47.579 mi
Registration #18	2013-03-28	47.579 mi
Registration #19	2013-03-28	47.579 mi
Registration #20	2013-03-28	47.579 mi
Registration #21	2013-03-28	47.579 mi
Registration #22	2013-03-28	47.579 mi
Registration #23	2013-03-28	47.579 mi
Registration #24	2013-03-28	47.579 mi
Registration #25	2013-03-28	47.579 mi
Registration #26	2013-03-28	47.579 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442
Registration #32	2025-25-25	25,252,442

More info >



Additional information

Fuel delivery	Direct Injection
Engine number	11L08713A