



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Black
Year of manufacture	-
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-12
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #22	2021-09-27 13:37
MOT test number	630065491415
Result	✓ Passed
Next expiry date	2022-09-30
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21	2021-09-27 13:37
MOT test number	592064342801
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Nearside Rear Inner Position lamp not working (4.2.1 (a) (ii))
Advice	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

MOT #20	2020-10-01 13:08
MOT test number	270869982360
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge bald (5.2.3 (e))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #19** 2020-09-25 08:07**MOT test number** 932920201675**Result** ✗ Failed**Advice** Brake pipe corroded, covered in grease or other material main front to rear (1.1.11 (c))**Fail** Brake pipe excessively corroded main front to rear (1.1.11 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge bald (5.2.3 (e))**MOT #18** 2019-09-25 13:41**MOT test number** 959192806232**Result** ✓ Passed**MOT #17** 2019-09-24 13:42**MOT test number** 311259579248**Result** ✗ Failed**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #16** 2018-09-19 09:18**MOT test number** 700187071964**Result** ✓ Passed**MOT #15** 2018-09-14 15:59**MOT test number** 544031751770**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a))

**MOT #14** 2017-09-11 14:41**MOT test number** 439678515253**Result** ✓ Passed

- Advice** Offside Front brake pipe badly corroded
- Advice** Nearside Front tyre wearing inner edge off
- Advice** Offside Brake pipe slightly corroded front to rear rear section (3.6.B.2c)
- Advice** Offside Front tyre inner edge is bald

MOT #13 2016-05-10 13:52**MOT test number** 403449770114**Result** ✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Brake pipe slightly corroded Abs pump along chassis leg (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #12 2015-05-11 11:59**MOT test number** 638041435169**Result** ✓ Passed

- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Notice** Both front wipers split

**MOT #11**

2015-05-01 15:35

MOT test number

247601725459

Result

✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Notice** Both front wipers split
- Advice** Offside Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Brake pipe excessively corroded (3.6.B.2c)
- Fail** Offside Rear Tie bar/rod ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)

MOT #10

2014-04-24 10:08

MOT test number

608594214104

Result

✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2014-04-24 10:08**MOT test number** 108464514120**Result** ✗ Failed**Pass with rectification** Front Bonnet retaining device insecure (8.4.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**MOT #8** 2013-05-03 11:21**MOT test number** 137973323152**Result** ✓ Passed**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #7** 2012-04-19 10:03**MOT test number** 888040512123**Result** ✓ Passed**MOT #6** 2011-03-29 16:58**MOT test number** 615768581018**Result** ✓ Passed**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Notice** Front and rear discs pitted**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



MOT #5	2010-04-23 13:04
---------------	------------------

MOT test number	443143710162
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-05-27 11:25
---------------	------------------

MOT test number	871047949166
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-03-31 11:41
---------------	------------------

MOT test number	331511598042
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2008-03-31 11:41
---------------	------------------

MOT test number	781681198074
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	--

Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
--------------------------------	---

MOT #1	2007-03-22 10:42
---------------	------------------

MOT test number	611271087029
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-09-30
Last registration	2021-09-27
Complete history	See info



Registration #1	2003-09-30	7 mi
Registration #2	2007-03-22	29.470 mi
Registration #3	2008-03-31	38.423 mi
Registration #4	2009-05-27	53.890 mi
Registration #5	2010-04-23	70.192 mi
Registration #6	2011-03-29	84.542 mi
Registration #7	2012-04-19	95.139 mi
Registration #8	2013-05-03	97.682 mi
Registration #9	2014-04-24	98.482 mi
Registration #10	2015-05-01	100.719 mi
Registration #11	2015-05-11	100.734 mi
Registration #12	2016-05-20	101.217 mi
Registration #13	2017-05-20	101.217 mi
Registration #14	2018-05-20	101.217 mi
Registration #15	2019-05-20	101.217 mi
Registration #16	2020-05-20	101.217 mi
Registration #17	2021-05-20	101.217 mi
Registration #18	2022-05-20	101.217 mi
Registration #19	2023-05-20	101.217 mi
Registration #20	2024-05-20	101.217 mi
Registration #21	2025-05-20	101.217 mi
Registration #22	2026-05-20	101.217 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	335539378FB