



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Silver
Year of manufacture	2007
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Engine capacity	1.975 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg
CO2 emission	193 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-25
Pictures	10
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT expiry date</b>	2022-09-12
<b>MOT pass rate</b>	60 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	8
<b>Total advice items</b>	50
<b>Total items failed</b>	13

<b>MOT #20</b>	2021-09-13 09:53
----------------	------------------

<b>MOT test number</b>	590993036596
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Next expiry date</b>	2022-09-12
-------------------------	------------

- Advice** Front Exhaust mounting defective (6.1.2 (a))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Offside Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2021-09-10 10:00

**MOT test number**

137248833371

**Result****✗ Failed****Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #18**

2020-09-03 14:17

**MOT test number**

851230235528

**Result****✓ Passed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge bald, close to cords. (5.2.3 (e))

**MOT #17**

2020-09-03 09:45

**MOT test number**

882497476582

**Result****✗ Failed****Fail** Nearside Rear Inner Tyre has ply or cords exposed sidewall. (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Drive belt worn, but not excessively air cond. (6.1.7 (c) (i))**Fail** Nearside Front Outer Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge bald, close to cords. (5.2.3 (e))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #16**

2019-09-12 15:20

**MOT test number**

717590552900

**Result****✓ Passed****Advice** Drive belt worn, but not excessively Air conditioner belt. (6.1.7 (c) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Bonnet shocks weak.**MOT #15**

2019-09-12 10:00

**MOT test number**

570166004623

**Result****✗ Failed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Bonnet shocks weak.**Advice** Drive belt worn, but not excessively Air conditioner belt. (6.1.7 (c) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14** 2018-08-22 13:47**MOT test number** 771779007137**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #13** 2018-08-21 12:17**MOT test number** 720624758139**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #12** 2017-09-06 13:40**MOT test number** 203067069333**Result** ✓ Passed**Advice** Nearside Front Valve stem slightly damaged (4.1.D.1e)**Advice** Nearside Front tyre on 3mm**Advice** Offside Front Valve stem slightly damaged (4.1.D.1e)**Advice** Offside Front tyre on 3mm**Advice** Offside Front Inner Steering arm play**MOT #11** 2016-09-13 14:34**MOT test number** 820746522145**Result** ✓ Passed**Advice** Offside Rear drop link play

**MOT #10** 2015-09-03 00:00**MOT test number** 819530245706**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** ENGINE COVERS FITTED NOT ALLOWING FULL INSPECTION OF SOME COMPONENTS
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front TYRE SPLITTING ON SIDEWALLS
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #9** 2015-09-03 00:00**MOT test number** 796983112150**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** ENGINE COVERS FITTED NOT ALLOWING FULL INSPECTION OF SOME COMPONENTS
- Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front TYRE SPLITTING ON SIDEWALLS
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #8** 2014-08-05 13:26**MOT test number** 367297114260**Result** ✓ Passed

**MOT #7** 2014-08-05 11:40**MOT test number** 618827214223**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #6** 2013-08-21 16:26**MOT test number** 598243833227**Result** ✓ Passed**MOT #5** 2012-08-23 15:35**MOT test number** 496546032238**Result** ✓ Passed**MOT #4** 2012-08-23 15:35**MOT test number** 638526032285**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2011-03-09 16:42**MOT test number** 447398961076**Result** ✓ Passed**MOT #2** 2011-03-09 11:33**MOT test number** 348358061088**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)





MOT #1	2010-03-08 11:36
MOT test number	710637960030
Result	✓ Passed
<div>Notice</div> Rear tyres starting to wear on sides	



Tax & MOT check

✕  
Untaxed

Tax expired:  
12 December 2021

✕  
MOT

Expired:  
12 September 2022

Tax status	Expired at 12 December 2021
Days left	869 days too late
MOT expiry date	12 September 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>RV07JFZ</b>
Plate since	2024-03-29
Current registration	<b>RV07JFZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-03-08
Last registration	2021-09-13
Complete history	<a href="#">See info</a>



Registration #1	2007-03-08	26 mi
Registration #2	2010-03-08	63.459 mi
Registration #3	2011-03-09	80.128 mi
Registration #4	2011-03-09	80.128 mi
Registration #5	2012-08-23	97.809 mi
Registration #6	2013-08-21	110.223 mi
Registration #7	2014-08-05	120.273 mi
Registration #8	2014-08-05	120.273 mi
Registration #9	2015-09-03	138.081 mi
Registration #10	2015-09-03	138.081 mi
Registration #11	2016-09-13	151.477 mi
Registration #12	2016-09-13	151.477 mi
Registration #13	2016-09-13	151.477 mi
Registration #14	2016-09-13	151.477 mi
Registration #15	2016-09-13	151.477 mi
Registration #16	2016-09-13	151.477 mi
Registration #17	2016-09-13	151.477 mi
Registration #18	2016-09-13	151.477 mi
Registration #19	2016-09-13	151.477 mi
Registration #20	2016-09-13	151.477 mi
Registration #21	2016-09-13	151.477 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1312 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6749744