





General information

| Make | VOLKSWAGEN |
|---------------------|------------------------------------|
| Model | SHARAN SPORT TDI 4-MOTION (130BHP) |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 127 mph |
| 0 - 60 mph | 10.4 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 310 Nm at 1.900 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 43.5 mpg |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-09-03 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| MOT #24 | 2021-06-18 09:01 |
|------------------|------------------|
| MOT test number | 253952230177 |
| Result | ✓ Passed |
| Next expiry date | 2022-06-17 |

| MOT #23 | 2021-05-19 15:42 |
|-----------------|------------------|
| MOT test number | 992989263353 |
| Result | 🗙 Failed |
| | |

Fail Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength Front outrigger (5.3.6 (a) (i))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect Bulb looks incorrectly fitted (4.1.2 (c))

Fail Offside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength Front outrigger (5.3.6 (a) (i))

| MOT #22 | 2020-05-27 12:01 |
|---------------|---|
| MOT test | number 253258902590 |
| Result | ✓ Passed |
| Minor (i)) | Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) |
| Minor | Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Advice | Slight steering oil weep from rack |
| Advice | Rear Suspension arm corroded but not seriously weakened both sides (5.3.3 (b) (i)) |
| Minor | Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i)) |
| Advice | Rear both wheel arches |
| Advice | Front both strut top mounts have slight play |
| Advice | Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c)) |





| MOT #21 | | 2019-05-15 09:52 |
|---|---|------------------|
| MOT test | number | 292714986967 |
| Result | | ✓ Passed |
| Advice | Slight play in front suspension top mounts | |
| Advice | N/s and o/s sills starting to corrode | |
| | | |
| MOT #20 | | 2018-05-02 09:53 |
| MOT test | number | 816956983964 |
| Result | | ✓ Passed |
| Advice | Slight play in front suspension top mounts | |
| Advice | Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) | |
| Advice Offside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2) | | |
| Advice | N/s and o/s sills slightly corroded | |
| Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2) | | |
| | | |

Advice Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

| MOT #19 | 2017-05-16 14:08 |
|---|------------------|
| MOT test number | 506123908727 |
| Result | ✓ Passed |
| Advise Nearcide Front Lower Suspension arm hall joint dust sover deterior | |

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

| MOT #18 | 2017-05-16 10:01 |
|-----------------|------------------|
| MOT test number | 817018864818 |
| Result | × Failed |

Advice Nearside Front Lower Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc and slight play in n/s/f outer joint (2.5.C.1a)



MOT #17

| YG53 | GFY |
|--------------|------------|
| report date: | 2024-03-29 |

| 2016-05-24 | 17.01 |
|------------|----------|
| 2010 05 24 | T. 1.0 T |

| MOT test | number | 816653921740 |
|----------|---|--------------|
| Result | | ✓ Passed |
| Advice | Exhaust heat shield loose | |
| Advice | Rear brake ferrels corrding | |
| Advice | Brake warning light on | |
| Advice | Rear brake pipes starting to corrode | |
| Advice | N/s/f tyre starting to wear on outer edge | |

| MOT #16 | 2016-05-24 13:10 |
|--|------------------|
| MOT test number | 543022911504 |
| Result | 🗙 Failed |
| Advice N/s/f tyre starting to wear on outer edge | |
| Advice Brake warning light on | |
| Fail Offside rear parking brake recording little or no effort (3.7.8.6a) | |
| Advice Rear brake pipes starting to corrode | |
| Advice Rear brake ferrels corrding | |
| Fail Parking brake: efficiency below requirements (3.7.B.7) | |
| Advice Exhaust heat shield loose | |
| Fail Nearside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c | :) |



MOT #15

| YG53GFY |
|-------------------------|
| report date: 2024-03-29 |
| |
| |
| 2015-05-22 15:38 |

| MOT test | number | 889372645196 |
|----------|---|--------------|
| Result | | ✓ Passed |
| Notice | Rear exhaust heat sheild loose | |
| Advice | Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) | |
| Advice | Rear Brake pipe slightly corroded (3.6.B.2c) | |

2015-05-22 11:32 MOT #14 237552645470 **MOT test number** Result × Failed Parking brake: efficiency below requirements (3.7.B.7) Fail Advice Rear Brake hose has slight corrosion to ferrules (3.6.B.4e) Nearside rear parking brake recording little or no effort (3.7.B.6a) Fail Advice Rear Brake pipe slightly corroded (3.6.B.2c) Rear exhaust heat sheild loose Notice Fail Offside Indicator tell tale inoperative (1.4.A.2a)

| MOT #13 | | 2014-05-23 15:16 |
|----------|---|------------------|
| MOT test | number | 416503444177 |
| Result | | Passed |
| Advice | Centre Brake pipe slightly corroded (3.6.B.2c) | |
| Advice | Centre Rear Exhaust has a minor leak of exhaust gases (7.1.2) | |



| MOT #12 | | 2013-05-09 13:06 |
|---------------------|---|----------------------------|
| MOT test numbe | er | 976859923138 |
| Result | | Passed |
| Notice Exhau | ust tail pipe rotton | |
| Advice Rear | Brake pad(s) wearing thin (3.5.1g) | |
| | Service brake: service brake efficiency only just met. It would a adjustment or repair. (3.7.B.7) | appear that the braking |
| Notice Engin | ne covers fitted obscuring some components in the engine bay | |
| Advice Brake | e pipe slightly corroded (3.6.B.2c) | |
| | ng brake: parking brake efficiency only just met. It would appea ent or repair. (3.7.B.7) | ar that the braking system |
| Notice Unde | r-trays fitted obscuring some underside components | |

| MOT #11 | 2012-05-15 17:42 |
|--|------------------|
| MOT test number | 445446232161 |
| Result | ✓ Passed |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |

| MOT #10 | 2012-05-15 10:02 |
|---|------------------------|
| MOT test number | 407036132192 |
| Result | × Failed |
| Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g) | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Brake pipe slightly corroded (3.6.B.2c) | |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice Parking brake: parking brake efficiency only just met. It would appear the requires adjustment or repair. (3.7.B.7) | nat the braking system |



YG53GFY

report date: 2024-03-29





| MOT #9 | | 2011-05-23 11:45 |
|----------|---|------------------|
| MOT test | number | 288603741155 |
| Result | | ✓ Passed |
| Notice | Hand brake cable return spring in-op | |
| Notice | Offside indicator telltell light in op audio sound only | |

| MOT #8 | | 2010-05-27 10:01 |
|------------|---|------------------|
| MOT test i | number | 353347240102 |
| Result | | ✓ Passed |
| Advice | Brake disc slightly pitted (3.5.1h) | |
| Advice | Nearside Rear Brake pipe slightly corroded (3.6.B.2c) | |

| MOT #7 | 2009-09-17 11:27 |
|-----------------|------------------|
| MOT test number | 242680569284 |
| Result | ✓ Passed |

| MOT #6 | | 2009-09-16 10:37 |
|---|---|------------------|
| MOT test number | | 670789759260 |
| Result | | 🗙 Failed |
| Fail Nearside Front Tyre | e tread depth below requirements of 1.6mm (4.1.E.1) | |
| Pass with rectification | Front Windscreen washer provides insufficient washer liquid | (8.2.3) |
| Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) | | |

| MOT #5 | 2008-09-15 09:46 |
|-----------------------------|------------------|
| MOT test number | 933079158212 |
| Result | ✓ Passed |
| Notice Brake fault light on | |





| MOT #4 | 2008-09-15 09:46 |
|---|------------------|
| MOT test number | 313289558468 |
| Result | 🗙 Failed |
| Pass with rectification Offside Rear Stop lamp not working (1.2.1b) Notice Brake fault light on | |
| MOT #3 | 2007-08-30 09:32 |
| MOT test number | 281402747201 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2006-09-18 10:17 |
| MOT test number | 330231766298 |
| Result | Passed |
| | |
| MOT #1 | 2006-08-14 10:25 |
| MOT test number | 774046626213 |
| Result | ✓ Passed |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FETTOR |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| Date | OLE . |
| Category | AM |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ********* | |
| | |
| | |
| ********** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| | |
| Plate since | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 25 |
| First mileage registration | 2003-09-01 |
| Last registration | 2021-06-18 |
| Complete history | See info |



| Registration #1 | 2003-09-01 | 9 mi |
|------------------|------------|------------|
| Registration #2 | 2006-08-14 | 48.681 mi |
| Registration #3 | 2006-09-18 | 49.419 mi |
| Registration #4 | 2007-08-30 | 62.405 mi |
| Registration #5 | 2008-09-15 | 79.722 mi |
| Registration #6 | 2009-09-16 | 95.655 mi |
| Registration #7 | 2009-09-17 | 95.655 mi |
| Registration #8 | 2010-05-27 | 101.844 mi |
| Registration #9 | 2011-05-23 | 109.991 mi |
| Registration #10 | 2012-05-15 | 117.950 mi |
| Registration #11 | 2012-05-15 | 117.952 mi |
| Registration #12 | 2013-05-09 | 126.227 mi |
| Registration #13 | 2014-05-23 | 134.454 mi |
| Registration #14 | | 11.117 esi |
| Registration #15 | | 11.777 esi |
| Registration #16 | | 11.777 esi |
| Registration #17 | | 11.777 esi |
| Registration #18 | | 11.777 esi |
| Registration #19 | | 11.777 esi |
| Registration #20 | | 11.177 est |
| Registration #21 | | 11.777 mi |
| Registration #22 | | 11.117 est |
| Registration #23 | | 11.777 mi |
| Registration #24 | | 11.177 mi |
| Registration #25 | | 11.777 esi |
| | | |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|------------------------|------------------|
| Width | 1746 mm |
| Height | 1462 mm |
| Length | 4703 mm |
| Wheel base | 2703 mm |
| Kerb weight | 1695 kg |
| Additional information | |
| Fuel tank capacity | 62 I |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Engine number | AVF 325827 |
| CarCheck.co.uk | page 15/1 |