



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CDX
Colour	Silver
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	99 Nm at 3.200 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg





Internet history

Entry 1

Date	2021-06-19
Pictures	8
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #16	2020-09-22 13:10
MOT test number	628239537443
Result	✓ Passed
Next expiry date	2021-09-21
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2019-04-29 12:53
MOT test number	748719210917
Result	✓ Passed

MOT #14	2019-04-29 11:08
MOT test number	447188745255
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13	2018-04-30 10:02
MOT test number	283367951327
Result	✓ Passed

MOT #12	2017-04-28 10:15
MOT test number	216555940832
Result	✓ Passed



MOT #11	2017-04-28 10:15
MOT test number	605906928382
Result	✗ Failed
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively both (8.2.2)

MOT #10	2016-04-29 10:32
MOT test number	134182601440
Result	✓ Passed
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #9	2016-04-29 10:32
MOT test number	529361496568
Result	✗ Failed
Advice	Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Pass with rectification	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Advice	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Centre Stop lamp not working (1.2.1b)
Advice	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #8** 2015-04-29 10:23**MOT test number** 198989815167**Result** ✓ Passed**Advice** Centre Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #7** 2014-07-14 09:32**MOT test number** 217125494166**Result** ✓ Passed**MOT #6** 2013-10-03 10:38**MOT test number** 225416673228**Result** ✓ Passed**MOT #5** 2013-02-04 14:06**MOT test number** 267365033063**Result** ✓ Passed**MOT #4** 2011-09-05 16:35**MOT test number** 109338641216**Result** ✓ Passed**MOT #3** 2011-07-07 16:20**MOT test number** 546868881187**Result** ✓ Passed**Notice** Nearside front tyre worn on outer edge**MOT #2** 2010-06-05 11:28**MOT test number** 272186650140**Result** ✓ Passed



MOT #1	2009-06-03 11:18
MOT test number	570554359173
Result	✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BJ06VKT
Plate since	2024-03-28
Current registration	BJ06VKT
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-29
Last registration	2020-09-22
Complete history	See info



Registration #1	2006-06-29	26 mi
Registration #2	2009-06-03	20.511 mi
Registration #3	2010-06-05	25.120 mi
Registration #4	2011-07-07	26.606 mi
Registration #5	2011-09-05	26.612 mi
Registration #6	2013-02-04	45.425 mi
Registration #7	2013-10-03	50.146 mi
Registration #8	2014-07-14	53.962 mi
Registration #9	2015-04-29	57.239 mi
Registration #10	2016-06-29	58.377 mi
Registration #11	2017-06-29	58.377 mi
Registration #12	2018-06-29	58.377 mi
Registration #13	2019-06-29	58.377 mi
Registration #14	2020-06-29	58.377 mi
Registration #15	2021-06-29	58.377 mi
Registration #16	2022-06-29	58.377 mi
Registration #17	2023-06-29	58.377 mi
Registration #18	2024-06-29	58.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1440 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4HG6096333