





report date: 2024-03-29

### General information

Make	MERCEDES
Model	S-Class S320 CDI
Colour	Grey
Year of manufacture	2006
Top speed	149 mph
0 - 60 mph	7.5 seconds
Gearbox	7 speed automatic

## Engine & fuel consumption

Power	231 BHP
Max. torque	540 Nm at 1.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.0 mpg
CO2 emission	225 g/km
CO2 label	K



CarCheck.co.uk page 1/14



report date: 2024-03-29

## Internet history

### Entry 2

Date 2021-09-04

Pictures 17

Listing price View report









source: autotrader.co.uk

Entry 1

Date	2021-09-04
Pictures	17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

## MOT history

MOT expiry date	2024-01-26
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	25
Total items failed	18

MOT #22	2023-01-11 13:09
MOT test number	454791338284
Result	✓ Passed
Next expiry date	2024-01-26

MOT #21	2022	-01-27 15:26
MOT test	number 77	4837680297
Result		✓ Passed
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #20	2020-12-18 16:23
MOT test number	819319947654
Result	<b>✓</b> Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Offside Front Lower Suspension arm ball joint dust cover severely dete	riorated (front) (5.3.4 (b) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #19** 2020-12-16 15:29 **MOT test number** 502437924105 Result × Failed Fail Offside Front Lower Suspension arm ball joint excessively worn (rear) (5.3.4 (a) (i)) Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (front) (5.3.4 (b) (i)) Minor Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Fail Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18		2020-01-10 16:53
MOT test	number	247675167670
Result		✓ Passed
Advice	Nearside Front Tyre side wall cut no cords showing	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Tyre side wall cut no cords showing	
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

CarCheck.co.uk page 4/14



(5.2.3 (d) (i))

**CE56DKV** 

report date: 2024-03-29

**MOT #17** 2020-01-10 10:42 670017458354 **MOT** test number Result **X** Failed Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d)) **Advice** Nearside Front Tyre side wall cut no cords showing Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Fail Electronic parking brake warning indicates a malfunction (1.1.6 (e)) Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) Fail **Advice** Nearside Front Tyre side wall cut no cords showing

MOT #16 2019-01-11 16:46

MOT test number 650928584140

Result ✓ Passed

MOT #15

MOT test number

696063385783

Result

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords

CarCheck.co.uk page 5/14



report date: 2024-03-29

**MOT #14** 2017-12-13 12:10

**MOT test number** 517434454719

**Result** ✓ Passed

**Advice** Offside Rear Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Slight play in tie rod ends

**Advice** Nearside Rear Lower Front suspension has slight play in a lower suspension ball joint just acceptable (2.5.B.1a)

**MOT #13** 2016-12-16 15:19

**MOT test number** 456148079835

**Advice** Rear Tyre worn close to the legal limit BOTH (4.1.E.1)

**MOT #12** 2016-12-15 12:09

**MOT test number** 836671067952

**Result** X Failed

**Advice** Rear Tyre worn close to the legal limit BOTH (4.1.E.1)

**Fail** Offside Front Lower Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #11** 2015-12-15 11:26

MOT test number 401391466237

Result 

Passed

**Advice** Offside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**MOT #10** 2014-12-12 16:41

**MOT test number** 406146344417

Result J Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #9	2014-11-07 15:58
MOT test number	539921514380
Result	✓ Passed
MOT #8	2013-09-18 15:26
MOT test number	266721463294
Result	✓ Passed
MOT #7	2013-09-10 11:21
MOT test number	465393753290
Result	<b>×</b> Failed
Fail Nearside Rear Tyre tread depth below requirements	of 1.6mm (4.1.E.1)
Fail Offside Rear Tyre tread depth below requirements of	f 1.6mm (4.1.E.1)

MOT #6	2012-08-22 11:45
MOT test number	355445232483
Result	✓ Passed
MOT #5	2011-08-25 14:33
MOT test number	385597531431
Result	✓ Passed
MOT #4	2011-08-24 13:18
MOT test number	287886331293
Result	<b>X</b> Failed

Result

Fail Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Offside front brake application uneven (3.7.B.2)

Fail Offside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)

Fail Brakes imbalanced across an axle (3.7.B.5b)

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #3 2010-10-25 11:09
MOT test number 104528990204

**Result** ✓ Passed

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

MOT #2 2010-10-12 12:44

MOT test number 311915280211

Result × Failed

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #1** 2009-09-08 12:31

MOT test number 970691059260

Result 

Passed

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

CarCheck.co.uk page 8/14



CE56DKV report date: 2024-03-29

### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Data	

Date
Category

Type



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



CE56DKV report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloaner.	
***************************************	
***********	
***************************************	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	TIK UK
Plate since	
Current registration	UK WIP
Plate since	
	More info >

CarCheck.co.uk page 11/14



CE56DKV report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 12/14



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-09-29
Last registration	2023-01-11
Complete history	See info



Registration #1	2006-09-29	28 mi
Registration #2	2009-09-08	21.501 mi
Registration #3	2010-10-12	28.460 mi
Registration #4	2010-10-25	28.674 mi
Registration #5	2011-08-24	34.346 mi
Registration #6	2011-08-25	34.344 mi
Registration #7	2012-08-22	38.565 mi
Registration #8	2013-09-10	47.759 mi
Registration #9	2013-09-18	48.046 mi
Registration #10	2014-11-07	51.699 mi
Registration #11	2014-12-12	51.723 mi
Registration #12	2015-12-15	58.635 mi
Registration #13	2016-12-15	65.146 mi
Registration #14		11.777 es
Registration #15		9.77 es
Registration #16		11.777 es
Registration #17		9.77 es
Registration #18		11.777 es
Registration #19		9.70 es
Registration #20		11.777 es
Registration #21		9.70 es
Registration #22		11.77 44
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 46



CE56DKV report date: 2024-03-29

Safety ratings

NCAP rating	***
11 02 11 1 01 011119	

**Video** <u>see crash video</u>



# Dimensions & weight

Width	1872 mm
Height	1473 mm
Length	5076 mm
Wheel base	3035 mm
Kerb weight	1965 kg
Max. allowed weight	2550 kg

## Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64293040182632

CarCheck.co.uk page 14/14