



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	AMICA CDX
Colour	Silver
Year of manufacture	2006
Top speed	86 mph
0 - 60 mph	18.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	62 BHP
Max. torque	98 Nm at 3.000 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	145 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-06-16
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	62 %
MOT passed	16
Failed MOT tests	10
Total advice items	66
Total items failed	13

MOT #26	2024-02-27 16:18
MOT test number	912089016017
Result	✓ Passed
Next expiry date	2025-02-26
Advice	Front windscreen cracked however not within swept area

MOT #25	2024-02-26 12:19
MOT test number	109509498395
Result	✗ Failed
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively rubber blade perished (3.4 (b) (ii))
MAJOR	Nearside Parking brake inoperative on one side (1.4.1 (a))
Advice	Front windscreen cracked however not within swept area
MAJOR	Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #24**

2023-02-27 13:54

MOT test number

742016217796

Result

✓ Passed

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Inner Suspension component mounting repair covered in underseal sill (5.3.6 (a) (i))**Advice** Nearside Rear Inner Suspension component mounting repair covered in underseal sill (5.3.6 (a) (i))**MOT #23**

2023-02-21 14:55

MOT test number

247678759425

Result

✗ Failed

MAJOR Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Rear Inner Suspension component mounting repair covered in underseal sill (5.3.6 (a) (i))**Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Inner Suspension component mounting repair covered in underseal sill (5.3.6 (a) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MOT #22**

2022-02-25 16:08

MOT test number

545706814169

Result

✓ Passed

Advice Underneath of vehicle in a rusty condition

**MOT #21** 2022-02-25 12:17**MOT test number** 665915713678**Result** ✗ Failed

- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Underneath of vehicle in a rusty condition
- MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #20 2022-02-02 15:13**MOT test number** 281959072524**Result** ✗ Failed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Offside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Advice** Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear brake shoes sticking to the drum
- MAJOR** Nearside Rear Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting (6.2.2 (d) (i))
- Advice** Front Coil spring corroded both (5.3.1 (b) (i))

**MOT #19**

2021-01-08 16:42

MOT test number

128612126564

Result

✓ Passed

- Advice** Nearside Rear Monitor corrosin around the N/S/R AXLE BEAM
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake shoes sticking to the drum
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing Casing severely corroded (5.3.2 (b))
- Advice** Nearside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #18

2021-01-06 14:08

MOT test number

975718736560

Result

✗ Failed

- MAJOR** Rear Parking brake inoperative on one side Both sides (1.4.1 (a))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing Casing severely corroded (5.3.2 (b))
- Advice** Nearside Rear Brake shoes sticking to the drum
- Advice** Nearside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Monitor corrosin around the N/S/R AXLE BEAM

**MOT #17** 2020-11-26 10:39**MOT test number** 258166485892**Result** ✗ Failed**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Rear Monitor corrosin around the N/S/R AXLE BEAM**Advice** Nearside Rear Shock absorbers has slight external damage to the casing Casing sevierly corroded (5.3.2 (b))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Front Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement cracking pesent (5.3.4 (a) (i))**Advice** Nearside Rear Brake shoes sticking to the drum**Advice** Rear REAR PARKING BRAKE INOPERATIVE**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #16** 2019-11-29 10:38**MOT test number** 702091354689**Result** ✓ Passed**MOT #15** 2019-03-07 12:43**MOT test number** 341079709297**Result** ✓ Passed**MOT #14** 2018-03-19 14:19**MOT test number** 373490888471**Result** ✓ Passed

**MOT #13** 2018-03-19 10:09**MOT test number** 112054906169**Result** ✗ Failed**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #12** 2017-03-15 13:35**MOT test number** 496532045765**Result** ✓ Passed**MOT #11** 2016-03-16 11:32**MOT test number** 432747075311**Result** ✓ Passed**Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Advice** Nearside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**MOT #10** 2016-03-16 11:32**MOT test number** 147668514686**Result** ✗ Failed**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Lower Bonded suspension unit deteriorated but can function as intended (2.4.F.3)



MOT #9	2015-03-04 10:57
MOT test number	365213465018
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8	2014-03-11 10:27
MOT test number	905990074090
Result	✓ Passed
Notice	Full exhaust system worn and welded at various parts. secure and no leaks detected
Notice	Both front tyres scrubbing on inner edges! replace tyres and check tracking!!

MOT #7	2013-03-06 14:33
MOT test number	879155863068
Result	✓ Passed

MOT #6	2013-03-05 11:54
MOT test number	185654563456
Result	✗ Failed
Fail	Front Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Nearside front brake juddering severely (3.7.A.2b)
Fail	Front Exhaust has a major leak of exhaust gases (7.1.2)
Fail	Emissions not tested (7.0)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #5** 2012-03-02 11:52**MOT test number** 177212562038**Result** ✓ Passed**Advice** Offside Rear Direction indicators slightly discoloured (1.4.A.2f)**Notice** Rear wiper blade torn**Notice** All exhaust worn/ cat heatshield insecure**MOT #4** 2011-03-05 11:24**MOT test number** 596984461048**Result** ✓ Passed**MOT #3** 2010-03-30 12:14**MOT test number** 403149580008**Result** ✓ Passed**Notice** N/s/f tyre on limit.**MOT #2** 2010-03-29 13:25**MOT test number** 763208880060**Result** ✗ Failed**Notice** N/s/f tyre on limit.**Fail** Offside Front Headlamp aim too high (1.8)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2009-03-09 09:59**MOT test number** 840568769063**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 February 2025

Tax status	Valid until 1 June
Days left	32
MOT expiry date	26 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 SD06TLU
Plate since	2019-03-28
Current registration	 SD06TLU
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2006-03-31
Last registration	2024-02-27
Complete history	See info



Registration #1	2006-03-31	27 mi
Registration #2	2009-03-09	19.707 mi
Registration #3	2010-03-29	25.549 mi
Registration #4	2010-03-30	25.549 mi
Registration #5	2011-03-05	29.355 mi
Registration #6	2012-03-02	35.133 mi
Registration #7	2013-03-05	40.348 mi
Registration #8	2013-03-06	40.348 mi
Registration #9	2014-03-11	45.500 mi
Registration #10	2015-03-04	49.489 mi
Registration #11	2016-03-16	53.156 mi
Registration #12	2016-03-16	53.156 mi
Registration #13	2017-03-15	55.528 mi
Registration #14	2018-03-19	58.879 mi
Registration #15	2019-03-20	61.217 mi
Registration #16	2019-03-20	61.217 mi
Registration #17	2019-03-20	61.217 mi
Registration #18	2019-03-20	61.217 mi
Registration #19	2019-03-20	61.217 mi
Registration #20	2019-03-20	61.217 mi
Registration #21	2019-03-20	61.217 mi
Registration #22	2019-03-20	61.217 mi
Registration #23	2019-03-20	61.217 mi
Registration #24	2019-03-20	61.217 mi
Registration #25	2019-03-20	61.217 mi
Registration #26	2019-03-20	61.217 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1525 mm
Height	1570 mm
Length	3565 mm
Wheel base	2380 mm
Kerb weight	1021 kg
Max. allowed weight	1336 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Engine number	G4HG5M729578