



report date: 2024-03-29

General information

Make	SUZUKI
Model	SX4 GLX
Colour	Silver
Year of manufacture	2008
Top speed	112 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-05
Pictures	2
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-09-17
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	40
Total items failed	3

MOT #20	2023-09-18 16:49
MOT test number	846994808174
Result	✓ Passed
Next expiry date	2024-09-17
Advice	Under side undersealed
Advice	Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

MOT #19	2022-09-06 10:06
MOT test number	205535415956
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #18**

2022-08-30 14:06

MOT test number

769933322169

Result**✗ Failed****Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MAJOR** Offside Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #17**

2021-09-14 16:03

MOT test number

991913998112

Result**✓ Passed****MOT #16**

2021-09-13 14:03

MOT test number

306346173564

Result**✗ Failed****MAJOR** Parking brake lever inoperative (1.1.6 (d))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))**MOT #15**

2020-08-19 12:20

MOT test number

961422616870

Result**✓ Passed****Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #14**

2020-08-12 08:22

MOT test number

684948352267

Result**✗ Failed**

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Brake slack adjuster incorrectly adjusted no reserve travel (1.1.18 (a))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn bonding failed (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #13

2019-08-29 13:21

MOT test number

819926275230

Result**✓ Passed**

**MOT #12** 2019-08-27 08:52**MOT test number** 849915813282**Result** ✗ Failed

DANGEROUS Offside Rear Hydraulic brake cylinder leaking and braking performance affected (1.1.16 (b) (ii))

MAJOR Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

MAJOR Offside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

MAJOR Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MAJOR Service brake efficiency below requirements (1.2.2 (a) (i))

MOT #11 2018-08-21 15:00**MOT test number** 765402862497**Result** ✓ Passed**MOT #10** 2017-06-26 15:07**MOT test number** 705399407152**Result** ✓ Passed

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #9 2016-06-24 13:19**MOT test number** 999064457746**Result** ✓ Passed**MOT #8** 2015-06-29 11:36**MOT test number** 679570785129**Result** ✓ Passed

**MOT #7** 2015-06-29 11:36**MOT test number** 725620885100**Result** ✗ Failed**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2014-06-17 16:39**MOT test number** 615468664121**Result** ✓ Passed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2014-06-17 16:39**MOT test number** 229278964104**Result** ✗ Failed**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-07-24 10:25**MOT test number** 199825603296**Result** ✓ Passed**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2013-07-24 08:41**MOT test number** 497425503290**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Battery insecure (1.9.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #2	2012-07-25 13:58
MOT test number	229847202217
Result	✓ Passed
MOT #1	2011-07-26 09:12
MOT test number	617597601211
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 September 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	17 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 SH58VHN
Plate since	2024-03-29
Current registration	 SH58VHN
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-12-30
Last registration	2023-09-18
Complete history	See info



Registration #1	2008-12-30	12 mi
Registration #2	2011-07-26	17.698 mi
Registration #3	2012-07-25	33.192 mi
Registration #4	2013-07-24	54.091 mi
Registration #5	2013-07-24	54.091 mi
Registration #6	2014-06-17	70.754 mi
Registration #7	2015-06-29	78.511 mi
Registration #8	2016-06-24	86.238 mi
Registration #9	2017-06-26	94.986 mi
Registration #10	2018-08-21	103.985 mi
Registration #11	2019-09-20	113.277 mi
Registration #12	2020-09-20	123.277 mi
Registration #13	2021-09-20	133.277 mi
Registration #14	2022-09-20	143.277 mi
Registration #15	2023-09-18	153.277 mi
Registration #16	2024-03-29	163.277 mi
Registration #17	2024-03-29	173.277 mi
Registration #18	2024-03-29	183.277 mi
Registration #19	2024-03-29	193.277 mi
Registration #20	2024-03-29	203.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1605 mm
Length	4235 mm
Wheel base	2500 mm
Kerb weight	1205 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1352003