





General information

Make	LAND ROVER
Model	DISCOVERY TD5 ES
Colour	Black
Year of manufacture	2000
Top speed	91 mph
0 - 60 mph	17.2 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	136 BHP
Max. torque	265 Nm at 1.800 rpm
Engine capacity	2.487 cc
Cylinders	5
Fuel type	Diesel
Consumption city	22.2 mpg
Consumption extra urban	31.4 mpg
Consumption combined	27.4 mpg



Internet history	
Entry 1	
Date	2021-10-19
Pictures	0
Listing price	View report

source: heycar.co.uk



MOT history

MOT expiry date	2024-11-01
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	34
Total items failed	5

МОТ #23	2023-10-30 14:06
MOT test number	628659359182
Result	✓ Passed
Next expiry date	2024-11-01
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1	.1.11 (c))
Advice Front Coil spring corroded both (5.3.1 (b) (i))	
Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))	
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced both chassis rail (6.1.1 (c) (i))	
Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated	(5.3.4 (b) (i))

MOT #22		2022-10-22 10:01
MOT test	number	997474710349
Result		✓ Passed
Advice	Rear Vehicle structure is corroded but structural rigidity is not significantly	/ reduced (6.1.1 (c) (i))
Advice	Front Coil spring corroded both (5.3.1 (b) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1	11 (c))



MOT #21	2021-11-02 17:52
MOT test number	482819295471
Result	✓ Passed
Advice Front Coil spring corroded both (5.3.1 (b) (i))	
Advice Rear Brake pad(s) wearing thin both (1.1.13 (a) (ii))	
Advice Rear Vehicle structure is corroded but structural rigidity is not significantly chassis rails (6.1.1 (c) (i))	reduced both rear
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive bush (5.3.4 (a) (i))	ve movement trail arm
Advice Rear Brake pipe corroded, covered in grease or other material both to flexi	pipes (1.1.11 (c))

MOT #20	2020-10-08 12:22	
MOT test number	933628227565	
Result	✓ Passed	
Minor Front Suspension arm ball joint dust cover severely deteriorated BOTH (5.3.4 (b) (i))		
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))		

MOT #19	2019-10-21 12:09
MOT test number	303535996883
Result	✓ Passed
Minor Front Suspension arm ball joint dust cover severely deteriorated both (5.3.4	(b) (i))
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))	

PRZ9889

report date: 2024-03-28





MOT #18	2019-10-03 13:22	
MOT test	number 910562384172	
Result	× Failed	
MAJOR	Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))	
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MAJOR (5.3.4 (b) (
MAJOR	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
MAJOR	Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Handbrake high	
MAJOR dirt (5.3.4	Nearside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of (b) (ii))	
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #17	2018-10-09 10:23
MOT test number	484146307113
Result	✓ Passed
Advice Nearside Rear Vehicle structure is corroded but structural rigidity is not (6.1.1 (c) (i))	significantly reduced
Advice Oil leak, but not excessive gearbox (8.4.1 (a) (i))	
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Offside Front Macpherson strut pin or bush worn but not resulting in ex (a) (i))	cessive movement (5.3.4

MOT #16	2017-10-23 13:03
MOT test number	815934265690
Result	✓ Passed





MOT test number	130134420677
Result	🗙 Failed
Pass with rectification Registration plate lamp not working (1.1.C.1d)	
MOT #14	2016-09-30 15:56
MOT test number	125815983585
Result	🗸 Passed
Advice Offside Rear Body has slight corrosion (6.1.B.2)	

MOT #13	2016-09-30 15:56
MOT test number	691843943841
Result	× Failed
Pass with rectification	Offside Front Shock absorber has an excessively worn bush (2.7.4)
Advice Offside Rear Body has slight corrosion (6.1.B.2)	

MOT #12	2015-10-09 15:04
MOT test number	324818521473
Result	✓ Passed

MOT #11		2014-10-13 10:17
MOT test	number	507136184258
Result		✓ Passed
Advice	Offside Front Shock absorber has a slightly worn bush (2.7.4)	
Advice	Nearside Front Shock absorber has a slightly worn bush (2.7.4)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	





MOT #10		2013-10-14 16:04
MOT test number		779227483221
Result		✓ Passed
MOT #9		2013-10-14 16:04
MOT test number		576517383212
Result		🗙 Failed
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Offside Stop lamp not working (1.2.1b)	
MOT #8		2012-09-20 16:32
MOT test number		375164762254

🗸 Passed

MOT #7	2011-10-13 10:26
MOT test number	386326381453
Result	✓ Passed

МОТ #6	2010-10-14 11:41
MOT test number	322617180206
Result	✓ Passed

MOT #5	2009-10-16 12:00
MOT test number	490139489247
Result	✓ Passed

MOT #4	2008-10-16 11:13
MOT test number	740300098227
Result	✓ Passed

Result





MOT #3	2008-10-16 11:13
MOT test number	474550898211
Result	× Failed
Pass with rectification (1.2.4a)	Nearside Headlamp not in good working order adversely affecting beam image
MOT #2	2007-10-17 10:38
MOT test number	830050397283
Result	✓ Passed
MOT #1	2006-10-16 13:19
MOT test number	731399386201
Result	✓ Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 July 2024	Expires: 1 November 2024
Tax status	Valid until 1 July
Days left	64
MOT expiry date	1 November 2024
Full MOT history	See MOT history





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
	MP1E
Category	ter .
Туре	

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2000-10-16
Last registration	2023-10-30
Complete history	See info



2000-10-16	14 mi
2006-10-16	39.673 mi
2007-10-17	42.810 mi
2008-10-16	45.837 mi
2009-10-16	48.095 mi
2010-10-14	51.467 mi
2011-10-13	56.354 mi
2012-09-20	59.779 mi
2013-10-14	69.490 mi
2014-10-13	77.531 mi
2015-10-09	88.389 mi
2016-09-30	99.877 mi
	11.777 esi
	11.777 esi
	11.777 mi
	10.000 est
	00.000 est 0.000 est 00.000 est
	00.000 est 0.000 est 00.000 est 00.000 est
	00.000 est 0.000 est 00.000 est 00.000 est 00.000 est
	00.000 e6 0.000 e6 0.000 e6 0.000 e6 0.000 e6 0.000 e6
	00.000 e6 0.000 e6 0.000 e6 0.000 e6 0.000 e6 0.000 e6 0.000 e6
	0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es 0.000 es
	2006-10-16 2007-10-17 2008-10-16 2009-10-16 2010-10-14 2011-10-13 2012-09-20 2013-10-14 2014-10-13 2014-10-13 2015-10-09 2016-09-30

More info >



Dimensions & weight

Width	2190 mm
Height	1940 mm
Length	4705 mm
Wheel base	2540 mm
Kerb weight	1935 kg
Additional information	

Fuel tank capacity89 IFuel deliveryDirect InjectionNumber of doors5Engine number10PA46910