



report date: 2024-03-29

General information

Make	MAZDA
Model	MX-5 I
Colour	Silver
Year of manufacture	2003
Top speed	127 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	162 Nm at 4.500 rpm
Engine capacity	1.840 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.8 mpg
CO2 emission	210 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-08-24
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	50
Total items failed	12

MOT #24 2023-08-25 14:51

MOT test number 413880294634

Result ✓ Passed

Next expiry date 2024-08-24

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Front Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

MOT #23 2022-03-25 12:01

MOT test number 671032018204

Result ✓ Passed

MOT #22 2021-03-10 12:55

MOT test number 929342898066

Result ✓ Passed

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #21**

2020-06-24 08:12

**MOT test number**

896047500052

**Result****✗ Failed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Headlamp lens slightly defective N/S & O/S (4.1.1 (b) (i))**MAJOR** Brake fluid contaminated (1.8 (a))**Minor** Front Lower Suspension arm ball joint dust cover severely deteriorated N/S & O/S (5.3.4 (b) (i))**MAJOR** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Minor** Front Upper Suspension arm ball joint dust cover severely deteriorated N/S & O/S (5.3.4 (b) (i))**MAJOR** Nearside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced (7.1.1 (a) (i))**MOT #20**

2019-04-04 12:08

**MOT test number**

343990309534

**Result****✓ Passed****Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated upper and lower (5.3.4 (b) (i))**Advice** Nearside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated upper and lower (5.3.4 (b) (i))**Advice** Under trays fitted obscuring some parts

**MOT #19**

2019-04-04 11:16

**MOT test number**

299360064377

**Result****✗ Failed****DANGEROUS** Nearside Rear Valve stem seriously damaged (5.2.3 (j))**Advice** Under trays fitted obscuring some parts**Advice** Nearside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated upper and lower (5.3.4 (b) (i))**DANGEROUS** Offside Rear Valve stem seriously damaged (5.2.3 (j))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated upper and lower (5.3.4 (b) (i))**MOT #18**

2018-03-29 12:55

**MOT test number**

417421236116

**Result****✓ Passed****Advice** Undertrays fitted obscuring some components**Advice** Front Headlamp deteriorated but light output not reduced N/S/F & O/S/F (1.7.5a)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt Upper & Lower (2.4.G.2)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Both tyre valves starting to perish**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt Upper and Lower (2.4.G.2)**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

**MOT #17** 2017-03-30 09:26**MOT test number** 833542246281**Result** ✓ Passed**MOT #16** 2016-04-14 12:35**MOT test number** 844096775790**Result** ✓ Passed**MOT #15** 2016-04-11 10:55**MOT test number** 580989351792**Result** ✗ Failed

**Fail** Nearside Rear Outer Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings sill (6.1.B.2)

**Advice** Offside Rear Outer Vehicle structure has slight corrosion sill (6.1.B.2)

**MOT #14** 2015-03-19 12:57**MOT test number** 718458475018**Result** ✓ Passed**MOT #13** 2015-03-19 09:20**MOT test number** 969458475063**Result** ✗ Failed

**Pass with rectification** Offside Headlamp aim too high (1.8)

**Fail** Offside front brake excessively fluctuating (3.7.B.3)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

**Fail** Nearside front brake excessively fluctuating (3.7.B.3)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #12** 2014-03-21 15:29**MOT test number** 176830984071**Result** ✓ Passed**MOT #11** 2014-03-21 15:29**MOT test number** 807980384012**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2013-04-06 11:07**MOT test number** 386196593035**Result** ✓ Passed**MOT #9** 2012-03-20 10:27**MOT test number** 189890182475**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Front number plate poor**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Exhaust rear box noisy**MOT #8** 2011-03-25 14:03**MOT test number** 215784981049**Result** ✓ Passed

**MOT #7** 2011-03-25 10:14**MOT test number** 977864381050**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside front brake binding (3.7.B.1)**MOT #6** 2010-05-05 09:26**MOT test number** 530955220188**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2009-04-01 12:04**MOT test number** 774041799073**Result** ✓ Passed**Advice** Front brake disc slightly pitted (3.5.1h)**Notice** Surface corrosion on suspension arms**MOT #4** 2008-04-08 13:06**MOT test number** 652049498087**Result** ✓ Passed**MOT #3** 2007-03-20 12:09**MOT test number** 782689177021**Result** ✓ Passed





MOT #2	2007-03-20 09:03
MOT test number	394059077020
Result	✗ Failed
Fail	Offside Front brake disc excessively pitted (3.5.1h)
Advice	Nearside Front brake disc slightly pitted (3.5.1h)

MOT #1	2006-03-21 10:32
MOT test number	691350786047
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
24 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	279
<b>MOT expiry date</b>	24 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-03-31
Last registration	2023-08-25
Complete history	<a href="#">See info</a>



Registration #1	2003-03-31	6 mi
Registration #2	2006-03-21	26.073 mi
Registration #3	2007-03-20	32.344 mi
Registration #4	2007-03-20	32.344 mi
Registration #5	2008-04-08	35.486 mi
Registration #6	2009-04-01	37.840 mi
Registration #7	2010-05-05	40.482 mi
Registration #8	2011-03-25	42.611 mi
Registration #9	2011-03-25	42.613 mi
Registration #10	2012-03-20	44.783 mi
Registration #11	2013-04-06	46.062 mi
Registration #12	2014-03-21	48.203 mi
Registration #13	2015-03-19	51.511 mi
Registration #14	2016-03-20	55.557 mi
Registration #15	2016-03-20	55.557 mi
Registration #16	2016-03-20	55.557 mi
Registration #17	2016-03-20	55.557 mi
Registration #18	2016-03-20	55.557 mi
Registration #19	2016-03-20	55.557 mi
Registration #20	2016-03-20	55.557 mi
Registration #21	2016-03-20	55.557 mi
Registration #22	2016-03-20	55.557 mi
Registration #23	2016-03-20	55.557 mi
Registration #24	2016-03-20	55.557 mi
Registration #25	2016-03-20	55.557 mi



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1680 mm
Height	1225 mm
Length	3975 mm
Wheel base	2265 mm
Kerb weight	1065 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	BP 538310