





General information

Make	VOLKSWAGEN
Model	POLO E (55BHP)
Colour	Blue
Year of manufacture	2007
Top speed	94 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2024-05-09
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	34
Total items failed	24

MOT #21		2023-05-10 09:31
MOT test	number	735467214386
Result		🗸 Passed
Next expire	ry date	2024-05-09
Advice (b))	Offside Front Headlamp has a product on the lens but not seriously reduci	ng light output (4.1.4
Advice (b))	Nearside Front Headlamp has a product on the lens but not seriously redu	cing light output (4.1.4

MOT #20	2021-11-16 13:56
MOT test number	200459626444
Result	✓ Passed

MOT #19	2020-07-30 07:44
MOT test number	219463677520
Result	✓ Passed

MOT #18	2020-07-28 15:42
MOT test number	655247585540
Result	🗙 Failed
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2)	.1.2 (b))
Advice Items removed from driver's view prior to test	





MOT #17		2019-07-23 10:02
MOT test number		865080705690
Result		✓ Passed
Advice Offside Front Tyr	re worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #16		2018-07-18 14:18
MOT test number		776279751753
Result		✓ Passed
MOT #15		2018-07-18 14:18
MOT test number		839616526491
Result		🗙 Failed
Pass with rectification	Bonnet primary retaining device ineffective seized (3.1 (c))	

MOT #14	2017-07-21 09:08
MOT test number	760156887543
Result	✓ Passed
Advice Exhaust Flexi Pipe Broken (Passed Emmisions Test)	

MOT #13	2017-07-19 12:25
MOT test number	749968736366
Result	× Failed
Fail Nearside Rear Rear wheel bearing rough when rotated (2.6.1)	
Advice Brake Pad Warning Light On	
Fail Windscreen washer provides insufficient washer liquid (8.2.3)	
Advice Exhaust Flexi Pipe Broken (Passed Emmisions Test)	





MOT #12	2016-07-13 13:10
MOT test number	516849906059
Result	✓ Passed
Advice Non obligatory mirror damaged	
Advice Engine management light on	
MOT #11	2016-07-13 08:54
MOT test number	540726407256
Result	🗙 Failed
Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3	8.D.3)
Advice Engine management light on	

Kesu	IT I I I I I I I I I I I I I I I I I I	× Falled
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)	
Adv	Engine management light on	
Fail	Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)	
Adv	Non obligatory mirror damaged	
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)	

MOT #10		2015-07-14 13:47
MOT test	number	749875895107
Result		✓ Passed
Notice	Non obligatory mirror damaged	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Notice	Engine management warning light on	
Notice	Offside front tyre worn to 3mm	





MOT #9	2015-07-14 13:47	
MOT test number	637355095111	
Result	× Failed	
Pass with rectification	Offside Headlamp aim too high (1.8)	
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Notice Non obligatory mirror damaged		
Pass with rectification	Nearside Headlamp aim too high (1.8)	
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Parking brake lever has little reserve travel (3.1.6b)		
Notice Engine management warning light on		
Pass with rectification Offside Headlamp not working on dipped beam (1.7.5a)		
Notice Offside front tyre worn to 3mm		

MOT #8	2014-06-16 12:43	
MOT test number	247127064160	
Result	✓ Passed	
MOT #7	2014-06-06 11:43	
MOT test number	778547154134	
Result	🗙 Failed	
Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)		
Notice N/s rear tyre worn on inner edge and on 2mm.		
Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)		
Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)		
Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.	D.3)	

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)





МОТ #6	2013-07-15 16:19	
MOT test number	437906393198	
Result	✓ Passed	
Notice Slight bind o/s / n/s front brakes		
MOT #5	2013-07-12 09:35	
MOT test number	749733593174	
Result	🗙 Failed	
Notice Slight bind o/s / n/s front brakes		
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structu	ıre (4.1.D.1b)	
Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)		
Notice Engine light on in vehicle		
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D	.3)	

MOT #4		2012-07-12 09:12
MOT test	number	205484292121
Result		✓ Passed
Notice	Engine warning light on in vehicle	
Notice	O/s / n/s rear tyres perishing in treads	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2011-07-12 13:38
MOT test number	646933791170
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	
Notice Front wiperblades worn	





MOT #2	2011-07-11 14:12	
MOT test number	339602691113	
Result	🗙 Failed	
Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessiv	re movement (2.4.G.2)	
Fail Nearside Front Tyre incorrectly seated on the wheel rim (4.1.D.1d)		
Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)		
Notice Front wiperblades worn		
Fail Nearside Front Road wheel bead rim badly distorted (4.2.A.1a)		
Advice Parking brake lever has little reserve travel (3.1.6b)		

MOT #1		2010-10-04 14:57
MOT test	number	902297770236
Result		✓ Passed
Advice (2.4.G.2)	Offside Front Radius arm rubber bush deteriorated but not resulting in exc	cessive movement
Advice (2.4.G.2)	Nearside Front Radius arm rubber bush deteriorated but not resulting in e	xcessive movement





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-11-22
Last registration	2023-05-10
Complete history	See info



Registration #1	2007-11-22	26 mi
Registration #2	2010-10-04	24.571 mi
Registration #3	2011-07-11	25.924 mi
Registration #4	2011-07-12	25.932 mi
Registration #5	2012-07-12	34.632 mi
Registration #6	2013-07-12	43.293 mi
Registration #7	2013-07-15	43.293 mi
Registration #8	2014-06-06	49.254 mi
Registration #9	2014-06-16	49.269 mi
Registration #10	2015-07-14	55.789 mi
Registration #11	2016-07-13	64.597 mi
Registration #12		11.777 est
Registration #13		11.707 esi
Registration #14		11.777 est
Registration #15		11.707 esi
Registration #16		11.777 est
Registration #17		11.707 esi
Registration #18		11.777 esi
Registration #19		11.707 mi
Registration #20		01.777 est
Registration #21		10.000 est

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1650 mm Height 1467 mm Length 3916 mm Wheel base 2466 mm Kerb weight 1186 kg Max. allowed weight 1570 kg Additional information **Fuel tank capacity** 45 I **Fuel delivery Multi-Point Injection** Number of doors 3

Number of seats	5
Number of axles	2
Engine number	BMD194531