





## General information

Make	VOLVO
Model	XC90 D5 S
Colour	Silver
Year of manufacture	-
Top speed	116 mph
Gearbox	5 speed Semi-Automatic

# Engine & fuel consumption

Power	161 BHP	0 < 101 A
Max. torque	340 Nm at 1.750 rpm	101 - 120 B
Cylinders	5	121 - 140 P
Fuel type	Diesel	141 - 165 F
Consumption city	23.7 mpg	166 - 185 H
Consumption extra urban	37.7 mpg	186 - 225 J
Consumption combined	31.0 mpg	225+ L



# MOT history

MOT #24	2021-01-29 12:39
MOT test number	647206488209
Result	✓ Passed
Next expiry date	2022-02-08
Minor Nearside Rear Registration plate lamp missing in the case of multiple la (b) (i))	mps or light sources (4.7.1
Advice Offside Front Brake pipe corroded, covered in grease or other material	(1.1.11 (c))
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #23		2020-02-05 15:54
MOT test	number	794075210447
Result		✓ Passed
Advice	Nearside Front Brake fluid close to minimum mark (1.1.10 (d) (ii))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Central Rear Registration plate insecure but not likely to fall off (0.1 (a))	
<b>Advice</b> (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not significant	tly reduced (6.1.1





MOT #22		2020-02-05 11:47
MOT test	number	543239296265
Result		🗙 Failed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Central Rear Registration plate insecure but not likely to fall off (0.1 (a))	
<b>Advice</b> (c) (i))	Offside Rear Vehicle structure is corroded but structural rigidity is not significan	tly reduced (6.1.1
<b>MAJOR</b> (5.3.4 (b)	Nearside Front Lower Suspension arm ball joint dust cover no longer prevents th (ii))	ne ingress of dirt
MAJOR	Rear Registration plate lamp inoperative in the case of a single lamp or all lamp	os (4.7.1 (b) (ii))
Advice	Nearside Front Brake fluid close to minimum mark (1.1.10 (d) (ii))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
MAJOR	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #21		2019-02-09 12:12
MOT test	number	579370928532
Result		🗸 Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
Advice illuminated	Rear Registration plate has an alternative light source LED strip less than 50% w d sufficiently	orking but
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.25 mm remaining in t	read (5.2.3 (e))
Advice	Covers fitted to vehicle	



SAO3NDE report date: 2024-03-29

MOT #20		2019-02-08 10:53
MOT test	number	469590750568
Result		🗙 Failed
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
MAJOR	Exhaust has a major leak of exhaust gases Backbox section (6.1.2 (a))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e	))
Advice illuminated	Rear Registration plate has an alternative light source LED strip less than 50% d sufficiently	working but
MAJOR	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 2.25 mm remaining in	tread (5.2.3 (e))
DANGER	OUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (i	i))
Advice	Covers fitted to vehicle	

МОТ #19	2018-02-07 09:18
MOT test number	622064665027
Result	✓ Passed
AdviceBrake pad(s) wearing thin n/s/r outer pad (3.5.1g)AdviceParking brake effort 18 percent legal limit 16 percent	

MOT #18	2017-02-09 15:24
MOT test number	529872906167
Result	Passed
Advice Some rusting to rear underside and sub frame	



S	A	0	3	Ν	D	Ε
I	repo	ort d	late	: 202	24-0	3-29

MOT #17		2017-02-09 15:24
MOT test number		979262346576
Result		🗙 Failed
Advice Some rusting to	rear underside and sub frame	
Pass with rectification	Direction indicator incorrect colour o/s/r (1.4.A.2f)	

MOT #16	2016-09-13 12:39
MOT test number	324949043790
Result	✓ Passed

MOT #15	2015-12-01 17:16
MOT test number	285709673195
Result	✓ Passed

MOT #:	14	2015-11-24 15:14
MOT te	st number	669903331835
Result		🗙 Failed
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)	
Fail	Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)	
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)	





MOT #13	2014-11-25 14:30
MOT test	number 417439624349
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b> (2.4.G.2)	Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
Notice	Both rear tyres slight perishing.
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
<b>Advice</b> (2.4.G.2)	Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement

MOT #12	2014-11-21 15:26
MOT test number	456545024386
Result	🗙 Failed
<b>Notice</b> Both rear tyres slight perishing.	
<b>Fail</b> Nearside rear parking brake recording little or no effort (3.7.B.6a)	
Fail Parking brake: efficiency below requirements (3.7.B.7)	
Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (	(3.5.1i)
Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excest (2.4.G.2)	ssive movement
<b>Fail</b> Offside rear parking brake recording little or no effort (3.7.B.6a)	
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened	d (3.5.1i)
Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in exc. (2.4.G.2)	essive movement

MOT #11	2013-10-07 16:04
MOT test number	528760483218
Result	✓ Passed





MOT #3	10	2013-10-01 12:43
MOT te	st number	667404873287
Result		🗙 Failed
Fail	Nearside Registration plate lamp not illuminating the registration plate (1.1.C.1e)	
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Nearside Front Front suspension has excessive play in a lower suspension ball joint	(2.5.B.1a)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)	

МОТ #9	2012-10-02 09:18
MOT test number	275596372251
Result	✓ Passed

MOT #8	2011-10-07 09:05
MOT test number	119100981224
Result	✓ Passed
Advice Offside Front Ball joint has slight play (2.2.B.1f)	

MOT #7	2011-10-06 15:44
MOT test number	329449571222
Result	🗙 Failed
FailParking brake: efficiency below requirements (3.7.B.7)AdviceOffside Front Lower Ball joint has slight play (2.2.B.1f)	

МОТ #6	2010-05-14 13:41
MOT test number	181924030114
Result	✓ Passed



-00-		report date: 2024-03-29
MOT #5		2010-05-14 09:16
MOT tes	st number	991094030153
Result		🗙 Failed
Fail	Parking brake: efficiency below requirements (3.7.C.1b)	
Fail	Registration plate lamp not working (1.1.C.1d)	

MOT #4	2008-11-24 15:29
MOT test number	252659728301
Result	✓ Passed

MOT #3	3	2008-11-24 13:21
MOT te	st number	511209528386
Result		× Failed
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Fail	I Nearside Front Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)	
Fail	Parking brake: efficiency below requirements (3.7.B.7)	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #2		2007-11-26 13:26
MOT test	number	471970037437
Result		✓ Passed
Advice	Offside Rear wheel bearing has slight play (2.6.2)	
Advice	Nearside Rear wheel bearing has slight play (2.6.2)	

MOT #1	2006-11-27 11:56
MOT test number	444061936328
Result	✓ Passed

SA03NDE





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	1. E
Category	 AMP
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
*********	
********	
******	
*********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2003-03-22
Last registration	2021-01-29
Complete history	See info



Registration #1	2003-03-22	19 mi
Registration #2	2006-11-27	50.976 mi
Registration #3	2007-11-26	61.452 mi
Registration #4	2008-11-24	70.254 mi
Registration #5	2008-11-24	70.254 mi
Registration #6	2010-05-14	78.918 mi
Registration #7	2010-05-14	78.918 mi
Registration #8	2011-10-06	87.329 mi
Registration #9	2011-10-07	87.337 mi
Registration #10	2012-10-02	95.451 mi
Registration #11	2013-10-01	101.518 mi
Registration #12	2013-10-07	101.549 mi
Registration #13	2014-11-21	106.093 mi
Registration #14		11.117 esi
Registration #15		11.777 est
Registration #16		11.117 esi
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi
Registration #22		11.177 mi
Registration #23		11.777 mi
Registration #24		11.117 est
Registration #25		11.777 mi





### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Max. allowed weight	2735 kg
Additional information	
Fuel tank capacity	72
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 14/14