



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2003
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-08-07
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-03-26
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	70
Total items failed	16

MOT #24	2024-03-27 15:27
MOT test number	701285984147
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Front Brake pipe corroded, covered in grease or other material greased (1.1.11 (c))

MOT #23	2022-11-22 11:10
MOT test number	964132243792
Result	✓ Passed
Advice	Sump rusty
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	When was cambelt change
Minor	Windscreen wiper blade defective (3.4 (b) (i))
Advice	Front subframe rusty
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))

**MOT #22**

2021-11-02 12:39

**MOT test number**

800237373416

**Result**

✓ Passed

**Advice** Engine sump rusty and weeping oil**MOT #21**

2021-10-27 15:15

**MOT test number**

742709556315

**Result**

✗ Failed

**Advice** Engine sump rusty and weeping oil**MAJOR** Exhaust has a major leak of exhaust gases (6.1.2 (a))**MAJOR** Rear Brake pipe excessively corroded x2 (1.1.11 (c))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Front Brake pipe excessively corroded to rear (1.1.11 (c))**MOT #20**

2020-10-08 07:52

**MOT test number**

435417456113

**Result**

✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Engine sump corroded**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer / inner sill and lower wheel arch corroded (5.3.6 (a) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2020-10-08 07:52

**MOT test number**

579078029825

**Result****✗ Failed**

- Advice** Engine sump corroded
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive outer / inner sill and lower wheel arch corroded (5.3.6 (a) (i))
- Pass with rectification** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18**

2019-04-25 08:12

**MOT test number**

880873721660

**Result****✓ Passed**

- Advice** All metal brake pipes have some corrosion may need att before next test

**MOT #17**

2019-04-25 08:12

**MOT test number**

664058027059

**Result****✗ Failed**

- Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** All metal brake pipes have some corrosion may need att before next test

**MOT #16**

2018-05-01 07:52

**MOT test number**

437885889141

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Front tyre has weather cracking but no canvas showing
- Advice** Oil leak slight engine oil leak
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Sub-frame corroded but not seriously weakened front sub frame has some surface corrosion (2.4.G.1)

**MOT #15**

2017-04-25 09:54

**MOT test number**

338418769476

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Power steering ram(s) has slight seepage from a seal (2.3.3b)
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Nearside Front tyre weather cracks
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (1.7.5a)

**MOT #14**

2016-04-19 09:53

**MOT test number**

458366449300

**Result**

✓ Passed

- Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Engine oil leak
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Exhaust has a minor leak of exhaust gases on front pipe where bracket is welded on (7.1.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #13**

2016-04-18 08:06

**MOT test number**

707054359185

**Result**

✗ Failed

- Fail** Rear registration plate deteriorated (6.3.1d)
- Pass with rectification** Offside Headlamp aim too high (1.8)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Exhaust has a minor leak of exhaust gases on front pipe where bracket is welded on (7.1.2)
- Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Nearside Headlamp aim too high (1.8)
- Advice** Engine oil leak
- Fail** Engine mounting deteriorated resulting in excessive movement (6.1.D.1a)
- Advice** Offside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

**MOT #12** 2015-04-30 11:48**MOT test number** 709930425151**Result** ✓ Passed**MOT #11** 2014-05-02 10:58**MOT test number** 446612724196**Result** ✓ Passed**MOT #10** 2014-05-02 10:58**MOT test number** 637672124194**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2013-04-29 16:22**MOT test number** 246399213151**Result** ✓ Passed**Notice** Both rear tyres cracking**Advice** Power steering pipe(s) or hose(s) slightly corroded (2.3.2)**MOT #8** 2011-11-23 11:46**MOT test number** 916507121309**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Offside front wiper split

**MOT #7** 2010-11-30 17:39**MOT test number** 591064430361**Result** ✓ Passed**MOT #6** 2010-11-30 10:18**MOT test number** 422124530447**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**MOT #5** 2009-11-26 11:03**MOT test number** 383830539352**Result** ✓ Passed**MOT #4** 2008-11-25 09:25**MOT test number** 842840738392**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear number plate starting to deteriorate.**MOT #3** 2008-11-25 09:25**MOT test number** 233010438392**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear number plate starting to deteriorate.**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



MOT #2	2007-11-23 16:21
MOT test number	973427027344
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2006-11-23 13:16
MOT test number	483557026431
Result	✓ Passed
Notice	Offside and nearside front tyres wearing on inner edges.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
26 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	26 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history


Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EY53CVG
Plate since	2019-03-28
Current registration	EY53CVG
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-11-22
Last registration	2024-03-27
Complete history	<a href="#">See info</a>



Registration #1	2003-11-22	10 mi
Registration #2	2006-11-23	28.247 mi
Registration #3	2007-11-23	36.270 mi
Registration #4	2008-11-25	43.258 mi
Registration #5	2009-11-26	51.212 mi
Registration #6	2010-11-30	60.875 mi
Registration #7	2010-11-30	60.876 mi
Registration #8	2011-11-23	70.265 mi
Registration #9	2013-04-29	78.891 mi
Registration #10	2014-05-02	86.508 mi
Registration #11	2015-04-30	91.536 mi
Registration #12	2016-04-18	94.432 mi
Registration #13	2016-04-18	94.432 mi
Registration #14	2016-04-18	94.432 mi
Registration #15	2016-04-18	94.432 mi
Registration #16	2016-04-18	94.432 mi
Registration #17	2016-04-18	94.432 mi
Registration #18	2016-04-18	94.432 mi
Registration #19	2016-04-18	94.432 mi
Registration #20	2016-04-18	94.432 mi
Registration #21	2016-04-18	94.432 mi
Registration #22	2016-04-18	94.432 mi
Registration #23	2016-04-18	94.432 mi
Registration #24	2016-04-18	94.432 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	G4HD3700955