



report date: 2024-03-29

General information

Make	VAUXHALL
Model	AGILA ENVOY 12V
Colour	Green
Year of manufacture	2000
Top speed	93 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	82 Nm at 2.800 rpm
Engine capacity	973 cc
Cylinders	3
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.2 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-27
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-11-25
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	53
Total items failed	8

MOT #21 2021-11-20 11:34

MOT test number 873475491787

Result ✓ Passed

Next expiry date 2022-11-25

Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i))

Advice Brake pipe corroded, covered in grease or other material front to rear pipes in various places (1.1.11 (c))

Advice Front Tyre slightly damaged/cracking or perishing nearside and offside (5.2.3 (d) (ii))

Advice Oil leak, but not excessive pressure switch area (8.4.1 (a) (i))

**MOT #20**

2020-10-27 12:21

MOT test number

477093811233

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear exhaust outer skin corroded
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive Spring (5.3.6 (a) (i))
- Advice** Direction indicator slightly discoloured Both front and Offside rear (4.4.3 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive spring (5.3.6 (a) (i))
- Advice** Oil leak around engine area

MOT #19

2019-11-25 15:59

MOT test number

433274302132

Result

✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #18**

2018-11-07 11:04

MOT test number

641384609740

Result

✓ Passed

- Advice** Oil leak, but not excessive Recommend attention soon (8.4.1 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material Central x2 (1.1.11 (c))
- Advice** Direction indicator slightly discoloured Both front and offside rear (4.4.3 (a))
- Advice** Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive Near Anti-roll bar mounting (5.3.6 (a) (i))
- Advice** Both front top suspension mounts have very slight wear. Exhaust deteriorated in places. Offside rear tyre starting to perish.

MOT #17

2017-11-21 08:19

MOT test number

775764099530

Result

✓ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Oil leak

MOT #16

2016-11-16 10:33

MOT test number

384106034368

Result

✓ Passed

**MOT #15**

2015-11-24 11:43

MOT test number

964093913147

Result

✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Front Valve stem slightly damaged (4.1.D.1e)

Advice Osr nsr radius arm bushes splitting and deteriorating

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #14

2014-11-24 12:21

MOT test number

147388324385

Result

✓ Passed

Advice Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Notice Nearside front tyre perishing

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Notice Exhaust corroded

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #13

2013-11-20 10:01

MOT test number

819694023356

Result

✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #12

2013-11-20 10:01

MOT test number

107864923392

Result

✗ Failed

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #11	2012-11-21 15:14
----------------	------------------

MOT test number	687266722370
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #10	2011-11-21 11:16
----------------	------------------

MOT test number	716065021338
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #9	2011-11-21 11:16
---------------	------------------

MOT test number	216045621339
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Rear Brake load sensing valve linkage seized (3.6.E.3)
--------------------------------	--

MOT #8	2010-11-19 11:21
---------------	------------------

MOT test number	693623620360
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2009-11-26 14:32
---------------	------------------

MOT test number	824380839377
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Inner Headlamp aim too high (1.8)
--------------------------------	-----------------------------------

Notice	O/s rear wheel slight binding
---------------	-------------------------------

MOT #6	2009-11-26 14:32
---------------	------------------

MOT test number	633270339338
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	O/s rear wheel slight binding
---------------	-------------------------------

**MOT #5** 2008-11-25 14:57**MOT test number** 164670338330**Result** ✓ Passed**Notice** Wheel trims fitted restricting inspection**Notice** Note:- chip windscreen outside zones**MOT #4** 2008-11-25 10:29**MOT test number** 182020738351**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Notice** Wheel trims fitted restricting inspection**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Note:- chip windscreen outside zones**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2007-11-20 12:10**MOT test number** 331904827337**Result** ✓ Passed**Advice** Nearside Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Shock absorber has a light misting of oil (2.7.3)**MOT #2** 2006-11-15 17:30**MOT test number** 202799716368**Result** ✓ Passed



MOT #12006-11-15 16:39

MOT test number672779616319

Result

Failed

- Fail

Nearside Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice

Offside Shock absorber has a light misting of oil (2.7.3)
- Notice

Both front tyres age cracking and down to 3mm
- Fail

Nearside Tyre has ply or cords exposed (4.1.D.1b)
- Advice

Nearside Shock absorber has a light misting of oil (2.7.3)
- Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2000-09-29
Last registration	2021-11-20
Complete history	See info



Registration #1	2000-09-29	26 mi
Registration #2	2006-11-15	35.686 mi
Registration #3	2006-11-15	35.686 mi
Registration #4	2007-11-20	40.594 mi
Registration #5	2008-11-25	45.563 mi
Registration #6	2008-11-25	45.563 mi
Registration #7	2009-11-26	49.914 mi
Registration #8	2010-11-19	54.258 mi
Registration #9	2011-11-21	61.137 mi
Registration #10	2012-11-21	65.105 mi
Registration #11	2013-11-21	69.073 mi
Registration #12	2014-11-21	73.041 mi
Registration #13	2015-11-21	77.009 mi
Registration #14	2016-11-21	80.977 mi
Registration #15	2017-11-21	84.945 mi
Registration #16	2018-11-21	88.913 mi
Registration #17	2019-11-21	92.881 mi
Registration #18	2020-11-21	96.849 mi
Registration #19	2021-11-21	100.817 mi
Registration #20	2022-11-21	104.785 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1955 mm
Height	1440 mm
Length	3839 mm
Wheel base	2491 mm
Kerb weight	865 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	19N02620