



CK6IBXZ

report date: 2024-03-29

General information

Make	MAZDA
Model	5 D SPORT
Colour	Silver
Year of manufacture	2011
Top speed	111 mph
0 - 60 mph	13.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2025-04-05
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	46
Total items failed	11

MOT #14 2024-04-04 14:43

MOT test number 640998460154

Result ✓ Passed

Next expiry date 2025-04-05

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both inner (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread cracks (0.1 (b))

MOT #13 2023-04-06 08:59

MOT test number 671161011794

Result ✓ Passed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Suspension component corroded but not seriously weakened both sides (5.3.3 (b) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread multiple cracks (0.1 (b))

MOT #12 2021-10-20 12:24

MOT test number 274724950408

Result ✓ Passed

- Advice** Emissions to clean to pick up

**MOT #11**

2021-10-20 09:56

MOT test number

384256201537

Result**✗ Failed****Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Emissions to clean to pick up**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #10**

2020-10-07 07:55

MOT test number

979237086065

Result**✓ Passed****Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))

**MOT #9**

2020-10-06 13:54

MOT test number

922827700922

Result**✗ Failed****Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn arm rear bush (5.3.4 (a) (i))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**Minor** Power steering fluid level below minimum (2.1.5 (b) (i))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Fail** Offside Rear Lower Suspension arm pin or bush excessively worn arm rear bush (5.3.4 (a) (i))**Fail** Reversing lamp inoperative (4.6.1 (a))

**MOT #8**

2019-10-04 12:12

MOT test number

757345881567

Result

✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt rear
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7

2018-10-02 11:25

MOT test number

376331903245

Result

✓ Passed

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Oil leak, but not excessive diff seal leaking (8.4.1 (a) (i))

**MOT #6**

2018-10-01 11:35

MOT test number

453539473416

Result**✗ Failed**

- Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm and worn on edges (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Offside Rear Seat belt webbing significantly weakened (7.1.2 (b) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm and worn on edges (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement arm rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Oil leak, but not excessive diff seal leaking (8.4.1 (a) (i))

MOT #5

2017-09-22 10:59

MOT test number

868819502218

Result**✓ Passed**

- Advice** Tyre edges wearing.

MOT #4

2016-10-07 12:17

MOT test number

922661042893

Result**✓ Passed****MOT #3**

2015-08-21 13:27

MOT test number

527831872939

Result**✓ Passed**



MOT #2	2014-09-23 12:53
MOT test number	438286764233
Result	✓ Passed

MOT #1	2014-09-16 16:23
MOT test number	496039054257
Result	✗ Failed
Fail	Parking brake lever has no reserve travel (3.1.6b)
Fail	Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
5 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	5 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2024-04-04
Complete history	See info



Registration #1	2011-09-30	19 mi
Registration #2	2014-09-16	39.450 mi
Registration #3	2014-09-23	39.638 mi
Registration #4	2015-08-21	27.800 mi
Registration #5	2016-10-07	60.291 mi
Registration #6	2017-09-22	70.569 mi
Registration #7	2018-10-01	78.839 mi
Registration #8	2018-10-02	78.840 mi
Registration #9	2019-05-29	95.377 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1490 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Indirect Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	Y6 325182