



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE AWD
Colour	Black
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	40.4 mpg
Consumption combined	34.0 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-22
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history****MOT #25**

2021-05-21 13:25

**MOT test number**

858111860516

**Result**

✓ Passed

**Next expiry date**

2022-05-20

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Park brake effort only just met minimum requirement
- Advice** All rear lower arm bushes perished/worn
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Park brake rubber missing
- Advice** All underside slightly corroded
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #24**

2021-04-27 11:51

**MOT test number**

356179555794

**Result****✗ Failed****Advice** Coil spring corroded all (5.3.1 (b) (i))**Advice** All underside lightly corroded**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))**Advice** Offside Play in steering rack inner joint(s)**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Park brake effort only just met minimum effort**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Park brake pedal rubber missing

**MOT #23**

2021-04-01 11:43

**MOT test number**

235808419132

**Result****✗ Failed****Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Headlamp aim too high (4.1.2 (a))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Offside Rear Suspension arm pin or bush excessively worn training arm bush split and debonded (5.3.4 (a) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Central Front Windscreen in an unacceptable condition cracked form n/s too o/s (3.2 (c) (i))**Advice** Central Rear under body corrosion**Advice** Central Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Offside Front Anti-roll bar linkage fractured (5.3.3 (b) (ii))**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Rear Suspension arm pin or bush excessively worn training arm bush split and debonded (5.3.4 (a) (i))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Central Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Central Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))**Fail** Offside Front Side repeater incorrect colour (4.4.3 (a))



MOT #22

2019-06-18 16:17

MOT test number

138113075094

Result

✓ Passed

- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice

Nearside Rear tyre worn outer shoulder
- Advice

Nearside Play in steering rack inner joint(s)
- Advice

Plastic sill covers fitted
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Emissions too clean to register
- Advice

Offside Play in steering rack inner joint(s)

**MOT #21**

2019-06-18 11:00

**MOT test number**

379551552914

**Result****✗ Failed**

- Advice** Plastic sill covers fitted
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Emissions too clean to register
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Nearside Rear tyre worn outer shoulder
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Fail** Offside Side repeater incorrect colour (4.4.3 (a))
- Advice** Offside Play in steering rack inner joint(s)
- Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #20**

2018-07-23 09:29

**MOT test number**

627897766138

**Result****✓ Passed**

- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Slight oil leak at front of engine from underneath
- Advice** Unable to check rear seat belts
- Advice** Slight wear from both rear trailing arm bushes

**MOT #19** 2018-07-18 10:35**MOT test number** 663461919614**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Slight oil leak at front of engine from underneath**Fail** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Slight wear from both rear trailing arm bushes**Advice** Unable to check rera seat belts**Fail** Power steering pipe/hose leaking (2.1.5 (a))**MOT #18** 2017-07-31 12:34**MOT test number** 337545558467**Result** ✓ Passed**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #17** 2017-07-29 09:56**MOT test number** 334651761855**Result** ✗ Failed**Advice** Nearside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear Suspension arm has slight play in a pin/bush (2.4.G.2)



**MOT #16** 2016-07-22 10:40**MOT test number** 418350835546**Result** ✓ Passed**MOT #15** 2016-07-22 06:40**MOT test number** 515231382082**Result** ✗ Failed**Fail** Nearside Front Drive shaft which forms part of the suspension damaged knocks on full lock (2.4.G.4a)**Fail** Nearside Front Drive shaft which forms part of the suspension coupling gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.4.G.4e)**MOT #14** 2015-07-31 13:41**MOT test number** 165822515230**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #13

2014-07-31 09:12

MOT test number

518952614209

Result

✓ Passed

- Advice

Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice

Offside Inner Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice

Rear suspension has lots of surface rust.
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Offside rear brake has a slight bind, this requires attention.
- Advice

Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice

Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Notice

Offside rear tyre has worn bald on inside edge, replacement is strongly advised.
- Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Notice

Oil leak
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #12

2014-07-28 11:03

MOT test number

869859304286

Result

✗ Failed

**Fail** Offside Rear Rear fog lamp not working (1.3.2b)

**Notice** Oil leak

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**Advice** Offside Inner Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Notice** Rear suspension has lots of surface rust.

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear Stop lamp not working (1.2.1b)

**Notice** Offside rear brake has a slight bind, this requires attention.

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)

**Notice** Offside rear tyre has worn bald on inside edge, replacement is strongly advised.

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #11**

2013-04-04 11:06

**MOT test number**

407844893029

**Result**

✓ Passed

**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**MOT #10**

2013-03-26 13:58

**MOT test number**

597575183017

**Result**

✗ Failed

**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Rear rear brake grabbing severely (3.7.A.5b)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #9**

2012-05-22 09:28

**MOT test number**

266433542146

**Result**

✓ Passed

**MOT #8** 2012-05-14 12:30**MOT test number** 219615432461**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #7** 2011-05-26 11:08**MOT test number** 637416641107**Result** ✓ Passed**MOT #6** 2010-05-20 09:44**MOT test number** 842960340130**Result** ✓ Passed**MOT #5** 2009-06-03 12:43**MOT test number** 934784959152**Result** ✓ Passed**MOT #4** 2009-05-19 15:10**MOT test number** 420089539149**Result** ✗ Failed

- Fail** Nearside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

**MOT #3** 2008-05-16 12:07**MOT test number** 192067838130**Result** Passed**MOT #2** 2008-05-08 09:36**MOT test number** 660079828152**Result** Failed

- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #1** 2007-04-26 12:02**MOT test number** 311856517175**Result** Passed

- Advice** Offside Front Ball joint has slight play (2.2.B.1f)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)
- Advice** Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1a)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YW04UTK
Plate since	2024-03-28
Current registration	YW04UTK
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2004-04-26
Last registration	2021-05-21
Complete history	<a href="#">See info</a>



Registration #1	2004-04-26	17 mi
Registration #2	2007-04-26	85.057 mi
Registration #3	2008-05-08	100.836 mi
Registration #4	2008-05-16	100.836 mi
Registration #5	2009-05-19	110.284 mi
Registration #6	2009-06-03	110.852 mi
Registration #7	2010-05-20	119.319 mi
Registration #8	2011-05-26	128.977 mi
Registration #9	2012-05-14	138.638 mi
Registration #10	2012-05-22	138.835 mi
Registration #11	2013-03-26	146.423 mi
Registration #12	2013-04-04	146.423 mi
Registration #13	2014-07-28	155.357 mi
Registration #14	2014-07-31	155.359 mi
Registration #15	2015-05-20	161.277 mi
Registration #16	2015-05-20	161.277 mi
Registration #17	2015-05-20	161.277 mi
Registration #18	2015-05-20	161.277 mi
Registration #19	2015-05-20	161.277 mi
Registration #20	2015-05-20	161.277 mi
Registration #21	2015-05-20	161.277 mi
Registration #22	2015-05-20	161.277 mi
Registration #23	2015-05-20	161.277 mi
Registration #24	2015-05-20	161.277 mi
Registration #25	2015-05-20	161.277 mi
Registration #26	2015-05-20	161.277 mi

Registration #27	2020-05-20	20,000,000
Registration #28	2020-05-20	20,000,000

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Max. allowed weight	2720 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Engine number**

206320