



HONDA



DG05XYA

report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD CTDI EXECUTIVE
Colour	Silver
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	190 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg






LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-10
Pictures	5
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #20	2023-05-25 14:26
MOT test number	993022907610
Result	✓ Passed
Next expiry date	2024-05-24
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
Advice	Play in steering rack inner joint(s)
Advice	Upper balljoint locking pins missing
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Inner sills corroded

MOT #19	2023-05-25 14:26
MOT test number	632951876766
Result	✗ Failed
Advice	Upper balljoint locking pins missing
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both (4.1.4 (b))
Pass with rectification	Battery insecure and likely to fall from carrier (4.13 (a) (ii))
Advice	Play in steering rack inner joint(s)
Advice	Inner sills corroded
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))



MOT #182022-04-28 15:28

MOT test number109017346287

Result

✓ Passed

- Advice

Both o/s/f upper and lower ball joints locking pins are missing
- Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Both inner sills corroded
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #17**

2022-04-19 11:44

MOT test number

110600038977

Result**✗ Failed**

- Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Exhaust has a minor leak of exhaust gases by flexi pipe (6.1.2 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))
- Advice** Both inner sills corroded x2
- Advice** Both offside upper and lower ball joint locking pins missing x2
- Fail** Offside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Fail** Nearside Rear Valve stem seriously damaged (5.2.3 (j))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))
- Advice** All rear suspension corroded
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside front lower ball joint locking pin missing

**MOT #16**

2022-03-29 11:23

MOT test number

527110501888

Result**✗ Failed**

- Advice** General corrosion to chassis
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Front Headlamp lens slightly defective both lamps slightly deteriorated (4.1.1 (b) (i))
- Advice** Rear both wheel arches corroded
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front fog lamp not working
- Fail** Power steering pipe/hose leaking (2.1.5 (a))
- Advice** General corrosion to steering and suspension components
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Front abs sensor wiring not secure but not likely to cause damage
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2021-03-25 11:56**MOT test number** 550867908187**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2021-03-19 11:53**MOT test number** 923253223289**Result** ✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #13 2020-03-19 08:38**MOT test number** 869217796731**Result** ✓ Passed

**MOT #12**

2020-03-10 13:12

MOT test number

808608976749

Result**✗ Failed**

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #11

2017-10-17 15:24

MOT test number

312736528139

Result**✓ Passed**

- Advice** Offside Rear Anti-roll bar has slight play in a pin bearing (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar has slight play in a pin/bush (2.4.G.2)

MOT #10

2015-12-02 14:53

MOT test number

498269149954

Result**✓ Passed****MOT #9**

2015-12-02 14:53

MOT test number

935747624153

Result**✗ Failed**

- Pass with rectification** Centre Fuel system component leaking pipe (7.2.3)

**MOT #8** 2014-05-21 14:27**MOT test number** 428271044114**Result** ✓ Passed

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2013-03-23 12:04**MOT test number** 945412583050**Result** ✓ Passed**MOT #6** 2012-04-02 12:08**MOT test number** 795813992063**Result** ✓ Passed**MOT #5** 2011-03-31 09:19**MOT test number** 449770791080**Result** ✓ Passed

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice Front discs need attention

Advice Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #4 2010-03-27 15:10**MOT test number** 784446280014**Result** ✓ Passed



MOT #3 2009-03-02 16:00

MOT test number 152371969463

Result ✗ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice Oil leak

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #2 2009-03-02 16:00

MOT test number 801071969054

Result ✓ Passed

Notice Oil leak

Advice Nearside Lower Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Offside Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #1 2008-03-25 11:19

MOT test number 593015888085

Result ✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-29
Last registration	2023-05-25
Complete history	See info



Registration #1	2005-03-29	9 mi
Registration #2	2008-03-25	67.597 mi
Registration #3	2009-03-02	86.923 mi
Registration #4	2010-03-27	106.912 mi
Registration #5	2011-03-31	122.593 mi
Registration #6	2012-04-02	135.110 mi
Registration #7	2013-03-23	148.396 mi
Registration #8	2014-05-21	155.922 mi
Registration #9	2015-12-02	162.331 mi
Registration #10	2015-12-02	162.331 mi
Registration #11	2017-10-17	170.839 mi
Registration #12	2019-05-20	181.277 mi
Registration #13	2019-05-20	181.277 mi
Registration #14	2019-05-20	181.277 mi
Registration #15	2019-05-20	181.277 mi
Registration #16	2019-05-20	181.277 mi
Registration #17	2019-05-20	181.277 mi
Registration #18	2019-05-20	181.277 mi
Registration #19	2019-05-20	181.277 mi
Registration #20	2019-05-20	181.277 mi
Registration #21	2019-05-20	181.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1482 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	N22A12010236