





### General information

Make	FIAT
Model	500C C LOUNGE
Colour	Red
Year of manufacture	2011
Top speed	99 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.500 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	113 g/km
CO2 label	С





### Internet history

Entry	3
Date	

Pictures

2021-11-20

12

Listing price

View report



source: cargurus.co.uk

Entry 2	
Date	2021-07-01
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-06-30
Pictures	33
Listing price	View report







source: autotrader.co.uk



### MOT history

MOT expiry date	2024-07-25
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	42
Total items failed	11

MOT #17	2023-07-24 14:23
MOT test number	792543401687
Result	✓ Passed
Next expiry date	2024-07-25
Advice Oil leak	

MOT #16	2023-07-21 11:24
MOT test number	751450387813
Result	× Failed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Front Windscreen washer not working (3.5 (a))	
Advice Center exhaust clamp missing	
Advice Oil leak	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #15	2022-07-21 11:35
MOT test number	489795583998
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





2021-07-26 09:28

MOT #14	2022-07-21 09:21
MOT test number	238738526833
Result	🗙 Failed
AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))FailOffside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

# MOT #13

MOT test	number 949	432345461
Result		✓ Passed
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Exhaust corroded	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)	))

MOT #12		2020-09-17 12:11
MOT test i	number	142389197165
Result		✓ Passed
Advice	Offside Rear Shock absorbers has a slightly worn bush top bush (5.3.2 (c))	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect damp (5.3.2 (b))		ct damp (5.3.2 (b))
Advice	Exhaust corroded	





MOT #11	2020-09-17 07:50
MOT test number	847303097654
Result	🗙 Failed
<b>Fail</b> Offside Rear Tyre has a cut in excess of the requirements deep enough to reach t (5.2.3 (d) (i))	he ply or cords:
Advice Exhaust corroded	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effect	t damp (5.3.2 (b))
Advice Offside Rear Shock absorbers has a slightly worn bush top bush (5.3.2 (c))	
<b>Fail</b> Nearside Rear Shock absorbers has an excessively worn bush top bush (5.3.2 (c))	

MOT #10		2019-09-10 13:56
MOT test	number	208366890156
Result		✓ Passed
Advice Nearside Rear park brake cable bracket broken due to corrosion but still supported		ed
Advice	Offside Rear park brake cable bracket broken due to corrosion but still supported	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge and cracked (5.2.3 (e))	
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5	.3.2 (b))

МОТ #9	2019-09-10 11:59	
MOT test number	437315298064	
Result	🗙 Failed	
Advice Offside Rear Tyre worn close to legal limit/worn on edge and cracked (5.2.3 (	(e))	
Fail Nearside Front Lower Suspension arm pin or bush excessively worn fouling on subframe (5.3.4 (a) (i))		
Advice Offside Rear park brake cable bracket broken due to corrosion but still support	orted	
Advice Offside Front Shock absorbers light misting of oil or has limited damping effe	ect (5.3.2 (b))	
Advice Nearside Rear park brake cable bracket broken due to corrosion but still supp	ported	





MOT #8	2018-09-21 07:28
MOT test	number 286603510687
Result	✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Offside Front suspension top mount slight play
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and close to legal limit (5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front suspension top mount slight play

MOT #7		2018-09-20 11:40
MOT test	number	759889542681
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))	
Advice	Offside Front suspension top mount slight play	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (	5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e)	)
Advice	Nearside Front suspension top mount slight play	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing and close to legal limit	(5.2.3 (d) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))
Fail Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))		

МОТ #6	2017-08-25 09:36
MOT test number	354014786738
Result	✓ Passed





MOT #5		2016-09-01 10:26
MOT test number		873361470951
Result		✓ Passed
Advice Nearside Rear S	hock absorber has a slightly worn bush upper bush (2.7.4)	
MOT #4		2015-09-10 16:28
MOT test number		516835567969
Result		✓ Passed
MOT #3		2015-09-10 16:28
MOT test number		213428194606
Result		🗙 Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen ef	ffectively (8.2.2)

MOT #2		2014-09-23 09:28
MOT test	number	199366164243
Result		✓ Passed
<b>Advice</b> (2.5.B.1b)	Nearside Front Macpherson strut has slight movement in the upper support	bearing assembly
<b>Advice</b> (2.5.B.1b)	Offside Front Macpherson strut has slight movement in the upper support be	earing assembly

MOT #1	2014-09-22 12:13
MOT test number	739375764241
Result	🗙 Failed
<b>Fail</b> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
<b>Advice</b> Nearside Front Macpherson strut has slight movement in the upper supp (2.5.B.1b)	oort bearing assembly
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)	
Advice Offside Front Macpherson strut has slight movement in the upper support (2.5.B.1b)	rt bearing assembly



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	MOT Expires: 25 July 2024
Tax status	Valid until 1 November
Days left	186
MOT expiry date	25 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4 ARAPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-06-30
Last registration	2023-07-24
Complete history	See info



Registration #1	2011-06-30	15 mi
Registration #2	2014-09-22	30.827 mi
Registration #3	2014-09-23	30.827 mi
Registration #4	2015-09-10	35.004 mi
Registration #5	2015-09-10	35.004 mi
Registration #6	2016-09-01	38.818 mi
Registration #7	2017-08-25	42.094 mi
Registration #8	2018-09-20	46.485 mi
Registration #9	2018-09-21	46.485 mi
Registration #10	2019-09-10	49.180 mi
Registration #11	2019-09-10	49.180 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 esi
Registration #15		11.707 mi
Registration #16		11.777 esi
Registration #17		11.707 est
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 esi
Registration #21		11.777 mi

More info >





#### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	905 kg
Max. allowed weight	1320 kg
Additional information	
Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 14/14

Number of axles	2
Engine number	6497453