




report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ4
Colour	Red
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





MOT history

MOT expiry date	2020-12-18
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	65
Total items failed	3



MOT #13	2020-12-18 13:27
MOT test number	181793510427
Result	✗ Failed

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Brake fluid close to minimum mark (1.1.10 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Vehicle structure is corroded but structural rigidity is not significantly reduced Suspension mounting point. (6.1.1 (c) (i))

DANGEROUS Offside Rear Valve stem seriously damaged (5.2.3 (j))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

Advice Vehicles internal headlight adjuster altered to recheck lights

Advice Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished. (5.3.4 (a) (i))

MAJOR Offside Headlamp aim too high and too far to the left. (4.1.2 (a))

Minor Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MAJOR Battery insecure and likely to fall from carrier (4.13 (a) (ii))

Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Upper Shock absorbers has slight external damage to the casing (5.3.2 (b))

Advice Clutch biting point very high at time of test.

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Rear Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush perished. (5.3.4 (a) (i))

MAJOR Offside Front Seat belt buckle not functioning as intended (7.1.2 (d))

Minor Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12** 2019-07-02 15:53**MOT test number** 606426742199**Result** ✓ Passed**Advice** Nearside Rear Shock absorber dust cover corroded/broken**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2019-07-02 14:40**MOT test number** 430766557836**Result** ✗ Failed**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Horn not working (7.7 (a) (ii))**Advice** Nearside Rear Shock absorber dust cover corroded/broken**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-06-13 15:19**MOT test number** 313296551724**Result** ✓ Passed**Advice** Nearside rear shock absorber OUTER COVER is badly deteriorated/detached! advise replacement**Advice** Radiator appears to have a slight leak!

**MOT #9**

2018-06-13 08:04

MOT test number

723602301309

Result**✗ Failed**

- Advice** Nearside rear shock absorber OUTER COVER is badly deteriorated/detached! advise replacement
- MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- MAJOR** Front Registration plate inscription illegible badly deteriorated (0.1 (b))
- Advice** Radiator appears to have a slight leak!
- MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #8

2017-07-06 15:07

MOT test number

426595717987

Result**✓ Passed**

- Advice** Nearside rear shock absorber OUTER COVER is corroded/detached! advise replacement
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt slight leak! advise further monitoring (2.5.C.1a)

MOT #7

2016-06-28 08:05

MOT test number

497508646384

Result**✓ Passed**

- Advice** Rear wiper blade is split!
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside front tyre is wearing unevenly on inner edge!

**MOT #6** 2016-06-25 09:00**MOT test number** 934179650431**Result** ✗ Failed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear wiper blade is split!
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside front tyre is wearing unevenly on inner edge!
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #5 2016-06-13 11:02**MOT test number** 775340570480**Result** ✗ Failed

- Advice** Offside Front tyre worn on inner edge
- Advice** Nearside Front Inner cv boot damp
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Front number plate has damage
- Advice** Offside Rear tyre worn and perished
- Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)
- Advice** Rear wiper blade split

MOT #4 2015-07-07 15:43**MOT test number** 808228485119**Result** ✓ Passed

**MOT #3** 2014-06-25 10:12**MOT test number** 527056274163**Result** ✓ Passed**Notice** N/s rear wheel bearing slightly noisy**MOT #2** 2013-07-06 12:54**MOT test number** 128787083134**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Noise from the N/S/F wheel bearing. (not excessive)**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #1** 2012-07-10 15:53**MOT test number** 438612792123**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
24 December 2020

X

MOT

Expired:
18 December 2020

Tax status	Expired at 24 December 2020
Days left	1223 days too late
MOT expiry date	18 December 2020
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	HN09VNB
Plate since	2019-03-29
Current registration	HN09VNB
Plate since	2019-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-07-11
Last registration	2020-12-18
Complete history	See info



Registration #1	2009-07-11	11 mi
Registration #2	2012-07-10	48.757 mi
Registration #3	2013-07-06	60.177 mi
Registration #4	2014-06-25	64.005 mi
Registration #5	2015-07-07	75.728 mi
Registration #6	2016-06-13	88.977 mi
Registration #7	2016-06-25	89.393 mi
Registration #8	2016-06-25	89.393 mi
Registration #9	2016-06-25	89.393 mi
Registration #10	2016-06-25	89.393 mi
Registration #11	2016-06-25	89.393 mi
Registration #12	2016-06-25	89.393 mi
Registration #13	2016-06-25	89.393 mi
Registration #14	2016-06-25	89.393 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1009612