



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA CRDI GS
Colour	Silver
Year of manufacture	2009
Top speed	121 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	28.5 mpg
Consumption combined	32.5 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-08
Pictures	1
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2022-08-09
<b>MOT pass rate</b>	59 %
<b>MOT passed</b>	10
<b>Failed MOT tests</b>	7
<b>Total advice items</b>	60
<b>Total items failed</b>	24

**MOT #17** 2021-08-10 17:51**MOT test number** 394283644474**Result** Passed**Next expiry date** 2022-08-09**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16** 2021-08-10 17:51**MOT test number** 803358194364**Result** Failed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #15** 2020-12-08 19:08**MOT test number** 841543115053**Result** Passed**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #14** 2019-05-08 09:44**MOT test number** 899224265722**Result** ✓ Passed**MOT #13** 2018-02-21 11:42**MOT test number** 299875235130**Result** ✓ Passed**MOT #12** 2018-02-17 12:21**MOT test number** 920002076112**Result** ✗ Failed

**Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Nearside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

**Fail** Offside Rear Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #11** 2017-01-26 15:19**MOT test number** 793918294031**Result** ✓ Passed

**MOT #10**

2016-02-22 17:24

**MOT test number**

565848745172

**Result**

✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Front cross member wet with oil
- Advice** Engine cover and under trays fitted
- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine oil leak
- Advice** Both rear rear links loose and worn
- Advice** Both front lower front wishbone rear bushes worn

**MOT #9**

2016-02-17 13:37

**MOT test number**

218648913767

**Result**

✗ Failed

- Advice** Front cross member wet with oil
- Fail** Exhaust emits an excessive level of metered smoke (7.4.B.3a)
- Advice** Engine cover and under trays fitted
- Fail** Steering rack insecure (2.2.B.1a)
- Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)
- Advice** Engine oil leak
- Advice** Both rear rear links loose and worn
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #8**

2015-02-20 15:59

**MOT test number**

505271055022

**Result**

✓ Passed

**Notice** N/s/r and n/s/f door converted for wheelchair entry and fitment,n/s/f seat removed for wheel chair**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #7**

2015-02-19 11:32

**MOT test number**

479970755027

**Result**

✗ Failed

**Fail** Offside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** N/s/r and n/s/f door converted for wheelchair entry and fitment,n/s/f seat removed for wheel chair**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Fail** Steering rack insecure (2.2.B.1a)

**MOT #6** 2014-05-01 13:25**MOT test number** 297991224472**Result** ✓ Passed**Notice** N/s/f of vehicle converted for wheelchair access and fitment**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** No seat fitted to n/s/f**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-04-16 12:28**MOT test number** 578356204130**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Steering rack insecure (2.2.B.1a)**Notice** N/s/f of vehicle converted for wheelchair access and fitment**Pass with rectification** Offside Headlamp aim too high (1.8)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Notice** Passenger seat(s) missing at time of test**MOT #4** 2013-05-08 10:45**MOT test number** 537678923114**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #3

2013-04-16 16:58

MOT test number

215956003436

Result

✗ Failed

- Fail

Offside Parking brake lever has no reserve travel (3.1.6b)
- Notice

N/s/f of car converted for wheel chair fitment and access
- Fail

Nearside rear parking brake recording little or no effort (3.7.B.6a)
- Advice

Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Notice

Oil leak
- Fail

Nearside Parking brake lever has no reserve travel (3.1.6b)
- Notice

Play in steering rack inner joint(s)
- Fail

Parking brake: efficiency below requirements (3.7.B.7)
- Fail

Offside rear parking brake recording little or no effort (3.7.B.6a)
- Fail

Power steering component(s) leaking (2.3.3b)
- Notice

Engine covers fitted obscuring some components in the engine bay



**MOT #2** 2012-05-16 15:50**MOT test number** 266187532484**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Slight damagr to front number plate
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Power steering component(s) has slight seepage from a component (2.3.3b)
- Notice** N/s/f door and seat adapted for a wheelchair
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Handbrake efficience only 17%
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

**MOT #1** 2012-05-16 15:50**MOT test number** 817867232167**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** N/s/f door and seat adapted for a wheelchair
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Handbrake efficience only 17%
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Notice** Slight damagr to front number plate
- Advice** Nearside Power steering component(s) has slight seepage from a component (2.3.3b)
- Pass with rectification** Nearside Headlamp aim too high and too far to the right. (1.8)



Tax & MOT check

✕  
Untaxed

Tax expired:  
27 July 2021

✕  
MOT

Expired:  
9 August 2022

Tax status	Expired at 27 July 2021
Days left	1006 days too late
MOT expiry date	9 August 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-12
Last registration	2021-08-10
Complete history	<a href="#">See info</a>



Registration #1	2009-06-12	20 mi
Registration #2	2012-05-16	12.414 mi
Registration #3	2013-04-16	15.698 mi
Registration #4	2013-05-08	15.704 mi
Registration #5	2014-04-16	19.682 mi
Registration #6	2014-05-01	19.689 mi
Registration #7	2015-02-19	23.235 mi
Registration #8	2015-02-20	23.235 mi
Registration #9	2016-02-17	27.614 mi
Registration #10	2016-05-20	31.377 mi
Registration #11	2016-05-20	31.377 mi
Registration #12	2016-05-20	31.377 mi
Registration #13	2016-05-20	31.377 mi
Registration #14	2016-05-20	31.377 mi
Registration #15	2016-05-20	31.377 mi
Registration #16	2016-05-20	31.377 mi
Registration #17	2016-05-20	31.377 mi
Registration #18	2016-05-20	31.377 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2189 kg
Max. allowed weight	2920 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7



<b>Number of axles</b>	2
<b>Engine number</b>	J3 8 277532