





report date: 2024-03-28

General information

| Make | FORD |
|---------------------|--------------------|
| Model | TRANSIT 260 LR P/V |
| Colour | White |
| Year of manufacture | 2009 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 84 BHP |
|-----------------|---------------------|
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 2.198 cc |
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/15



report date: 2024-03-28

MOT history

| MOT expiry date | 2025-02-15 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 12 |
| Failed MOT tests | 6 |
| Total advice items | 36 |
| Total items failed | 36 |

| MOT #18 | 2024-02-16 12:35 |
|---|------------------|
| MOT test number | 495521421137 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-15 |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

| MOT #17 | 2024-02-12 11:00 |
|---|----------------------|
| MOT test number | 941190073338 |
| Result | X Failed |
| Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) | |
| Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps b | oth (4.7.1 (b) (ii)) |
| Fail Offside Front Inner Vehicle structure or chassis has excessive corrosion, seriously a strength within 30cm of a body mounting sill marked in yellow (6.2.2 (d) (i)) | affecting its |
| Fail Nearside Rear Outer Vehicle structure or chassis has excessive corrosion, seriously strength within 30cm of a body mounting sill marked in yellow (6.2.2 (d) (i)) | affecting its |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Rear tyer wrong rotation | |
| Fail Offside Rear Position lamp adversely affected by the operation of another lamp (4. | 2.3 (c)) |
| Fail Front Windscreen in an unacceptable condition multipule cracks (3.2 (c) (i)) | |
| Fail Nearside Front Inner Vehicle structure or chassis has excessive corrosion, seriously strength within 30cm of a body mounting sill marked in yellow (6.2.2 (d) (i)) | / affecting its |
| Fail Nearside Rear Leaf spring fractured (5.3.1 (b) (i)) | |

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT #16 2023-02-07 15:00

MOT test number 200536406002

Result ✓ Passed

Advice Offside Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security inner sill (6.2.2 (d) (i))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Central Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

Advice Electronic stability control warning lamp not working does not light up (7.12 (e))

Minor Offside Front Windscreen damaged but not adversely affecting driver's view small crack (3.2 (a) (i))

Advice Front Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security front body corrison (6.2.2 (d) (i))

Advice Rear Cab or chassis corroded within 30cm of a mounting, but not seriously affecting overall security body (6.2.2 (d) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-28

× Failed

MOT #15 2023-02-06 13:00

MOT test number 617490679919

Result

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Central Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Anti-lock braking system warning lamp does not illuminate (1.6 (a))

Fail Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced centre outrigger (6.1.1 (c) (i))

Advice Front Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Horn not working (7.7 (a))

Advice Electronic stability control warning lamp not working (7.12 (e))

Advice Offside Front Inner Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

MOT #14 2022-02-04 08:55

MOT test number 108282188888

Result \(\sqrt{Passed} \)

Advice Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Central Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1

(c) (i))

CarCheck.co.uk page 4/15



MOT #13

Fail

Advice

MV59YSN

report date: 2024-03-28

2022-01-25 14:01

MOT test number 784934812891 Result × Failed Fail Brake pipe excessively corroded front to rear (1.1.11 (c)) **Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Offside Cab steps so insecure it is likely to cause injury badly corroded (6.2.8 (a) (ii)) Offside Headlamp aim too low (4.1.2 (a)) Fail **Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c)) Fail Offside Rear Inner Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Fail Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values 1.31 (8.2.2.2 (f))

Nearside Cab steps so insecure it is likely to cause injury badly corroded (6.2.8 (a) (ii))

Fail Offside Rear Leaf spring main leaf fractured (5.3.1 (b) (ii))

Advice Central Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Fail Offside Front Brake pipe likely to become detached or damaged (1.1.11 (d) (ii))

Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #12

MOT test number

213026028369

Result

Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Minor Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))

Advice Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

CarCheck.co.uk page 5/15



report date: 2024-03-28

| MOT #11 | 2020-07-10 14:24 |
|---------|------------------|
| | |

MOT test number 898173527541

MOT #10 2018-10-11 15:33

MOT test number 359181101960

Result

Passed

MOT #9 2017-10-09 12:09

MOT test number 796041059993

Result ✓ Passed

MOT #8 2017-10-07 08:57

MOT test number 270363845826

Result X Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Rear Brake pipe excessively corroded on rear axel (3.6.B.2c)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)

MOT #7 2016-10-07 12:48

MOT test number 142302906298

Result

Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #6

MOT test number

Fesult

Advice

Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #5

MOT test number

626959874280

Result

Notice Spare tyre worn to legal limit

Notice Wiper blades worn

MOT #4 2014-09-29 09:28 **MOT** test number 207762074254 Result × Failed **Notice** Wiper blades worn Fail Brake pedal anti-slip provision incomplete (3.3.A.1b) Notice Spare tyre worn to legal limit Fail Nearside Rear Registration plate lamp not working (1.1.C.1d) Fail Nearside Rear Rear reflector excessively damaged so that its function is impaired (1.5.1c) **Notice** Engine mil on Fail Nearside Rear Stop lamp not working (1.2.1b)

 MOT #3
 2013-09-30 09:19

 MOT test number
 356893673282

 Result
 ✓ Passed

CarCheck.co.uk page 7/15



report date: 2024-03-28

× Failed

 MOT #2
 2012-10-29 14:31

 MOT test number
 445193502368

Result \(\sqrt{Passed} \)

MOT #1 2012-10-29 14:31

MOT test number 296273802391

Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification Offside Front Headlamp aim too high (1.8)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Rear Registration plate lamp not working (1.1.C.1d)

Pass with rectification Nearside Front Headlamp aim too high (1.8)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively

(8.2.2)

Result

CarCheck.co.uk page 8/15



report date: 2024-03-28

Tax & MOT check



Tax status Valid until 1 February

Days left 278

MOT expiry date 15 February 2025

Full MOT history See MOT history

CarCheck.co.uk page 9/15



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-28

| _ | |
|-------|---------|
| Owner | history |
| OWILL | 1113601 |

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
|--|-------------|
| | |
| THE PARTY OF THE P | |
| *************************************** | |
| *************************************** | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| Number of plates | , |
| Current registration | UK SARS |
| Plate since | |
| Current registration | NK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2009-11-05 |
| Last registration | 2024-02-16 |
| Complete history | See info |



| Registration #1 | 2009-11-05 | 13 mi |
|------------------|------------|------------|
| Registration #2 | 2012-10-29 | 68.087 mi |
| Registration #3 | 2013-09-30 | 79.228 mi |
| Registration #4 | 2014-09-29 | 93.780 mi |
| Registration #5 | 2014-10-06 | 94.171 mi |
| Registration #6 | 2015-10-09 | 101.863 mi |
| Registration #7 | 2016-10-07 | 120.745 mi |
| Registration #8 | 2017-10-07 | 136.245 mi |
| Registration #9 | 2017-10-09 | 136.248 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.70 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 9.70 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 9.70 es |
| Registration #18 | | 71.777 au |

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-28

Car features

| S0225 | Air conditionin |
|-------|-----------------|
| S0295 | |
| S0482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

| Dim | ensior | 3 C | MOIO | hŧ |
|-----|--------|-------|------|----|
| | ensioi | 15 (2 | werd | |

| Width | 2360 mm |
|---------------------|---------|
| Height | 1989 mm |
| Length | 4863 mm |
| Kerb weight | 1699 kg |
| Max. allowed weight | 2600 kg |

Additional information

| Fuel tank capacity | 80 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 3 |
| Engine number | 9R16420 |

CarCheck.co.uk page 15/15