



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BORA GT TDI (150BHP)
Colour	Black
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	234 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	68.9 mpg
Consumption combined	56.5 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-26
Pictures	49
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

<b>MOT #22</b>	2021-08-31 15:20
<b>MOT test number</b>	830218817343
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-08-30
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Vehicle structure is corroded but structural rigidity is not significantly reduced surface corrosion in various spots (6.1.1 (c) (i))

<b>MOT #21</b>	2020-07-08 09:03
<b>MOT test number</b>	423135099477
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Brake Back plate corroded
<b>Advice</b>	Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Front BOTH wheel arches corroded
<b>Advice</b>	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
<b>Advice</b>	Rear Beam axle corroded
<b>Advice</b>	Offside Front Brake Back plate missing
<b>Advice</b>	Front Suspension arm corroded but not seriously weakened BOTH Wishbone arms corroded (5.3.3 (b) (i))
<b>Advice</b>	Front Subframe corroded
<b>Advice</b>	Exhaust heat shield loose
<b>Advice</b>	Rear Shock absorbers has slight external damage to the casing BOTH Corroded (5.3.2 (b))



MOT #20

2020-07-07 11:59

MOT test number

543348862153

Result

✗ Failed

- Fail

Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice

Offside Front Brake Back plate missing
- Advice

Front Suspension arm corroded but not seriously weakened BOTH Wishbone arms corroded (5.3.3 (b) (i))
- Advice

Front Subframe corroded
- Fail

Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice

Exhaust heat shield loose
- Advice

Rear Shock absorbers has slight external damage to the casing BOTH Corroded (5.3.2 (b))
- Advice

Nearside Front Brake Back plate corroded
- Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice

Front BOTH wheel arches corroded
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Rear Beam axle corroded

**MOT #19**

2019-04-25 11:17

**MOT test number**

667257477773

**Result**

✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** General / light corrosion starting to the underside of vehicle / suspension / braking / steering / exhaust components
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Shock absorbers has slight external damage to the casing corroded (5.3.2 (b))
- Advice** Nearside and offside front wings corroded
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement axle (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #18**

2018-04-24 12:13

**MOT test number**

224246208471

**Result**

✓ Passed

- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Front coil spring corroded (2.4.C.1b)
- Advice** Rear axle beam very rusty/corroded
- Advice** Brake/suspension areas front/rear very rusty/corroded
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Near/side front lower ball joint hub to ball joint casting damaged

**MOT #17**

2017-05-02 13:39

**MOT test number**

860643966811

**Result**

✓ Passed

- Advice** Brake/suspension areas very rusty/corroded
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear axle beam very rusty/\*corroded
- Advice** Under trays fitted unable to inspect some areas of brakes/steering/brake items
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #16**

2017-04-28 11:58

**MOT test number**

537378445039

**Result****✗ Failed****Advice** Rear axle beam very rusty/\*corroded**Fail** Offside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Under trays fitted unable to inspect some areas of brakes/steering/brake items**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Outer Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Brake/suspension areas very rusty/corroded**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #15**

2016-03-29 10:47

**MOT test number**

680620896382

**Result****✓ Passed****Advice** Brake/suspension areas very rusty front/rear**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**MOT #14**

2015-03-25 10:15

**MOT test number**

788744885069

**Result****✓ Passed****Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #13**

2015-03-23 12:16

**MOT test number**

538422585060

**Result****✗ Failed****Fail** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #12**

2014-03-27 12:22

**MOT test number**

519116684016

**Result****✓ Passed****Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #11**

2013-03-27 10:20

**MOT test number**

829666583038

**Result****✓ Passed****Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)



**MOT #10** 2012-03-23 09:45**MOT test number** 788293482083**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Brake discs corroded**MOT #9** 2012-03-21 13:04**MOT test number** 888461082072**Result** ✗ Failed**Fail** Fuel system component leaking (7.2.3)**Notice** Brake discs corroded**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #8** 2011-03-30 16:10**MOT test number** 985369281070**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2011-03-30 16:10**MOT test number** 179629981028**Result** ✗ Failed**Pass with rectification** Fuel system component leaking (7.2.3)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #6** 2010-03-15 11:39**MOT test number** 784374370089**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Front brake discs corroded**MOT #5** 2010-03-15 11:39**MOT test number** 751654370079**Result** ✗ Failed**Pass with rectification** Fuel system component leaking (7.2.3)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Front brake discs corroded**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**MOT #4** 2009-03-06 12:11**MOT test number** 844645569074**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front brake disc slightly pitted (3.5.1h)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #3** 2008-03-20 11:54**MOT test number** 944450388092**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nail in offside rear tyre
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2007-03-19 11:59**MOT test number** 754738177096**Result** ✓ Passed**MOT #1** 2006-03-22 10:16**MOT test number** 632691786099**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>DG03WKX</b>
Plate since	2024-03-28
Current registration	 <b>DG03WKX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2003-03-27
Last registration	2021-08-31
Complete history	<a href="#">See info</a>



Registration #1	2003-03-27	6 mi
Registration #2	2006-03-22	20.830 mi
Registration #3	2007-03-19	27.029 mi
Registration #4	2008-03-20	33.450 mi
Registration #5	2009-03-06	37.330 mi
Registration #6	2010-03-15	39.040 mi
Registration #7	2011-03-30	43.189 mi
Registration #8	2012-03-21	45.945 mi
Registration #9	2012-03-23	45.945 mi
Registration #10	2013-03-27	47.934 mi
Registration #11	2014-03-27	49.601 mi
Registration #12	2015-03-27	51.277 mi
Registration #13	2016-03-27	52.953 mi
Registration #14	2017-03-27	54.629 mi
Registration #15	2018-03-27	56.305 mi
Registration #16	2019-03-27	57.981 mi
Registration #17	2020-03-27	59.657 mi
Registration #18	2021-03-27	61.333 mi
Registration #19	2022-03-27	63.009 mi
Registration #20	2023-03-27	64.685 mi
Registration #21	2024-03-27	66.361 mi
Registration #22	2025-03-27	68.037 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm
Wheel base	2511 mm
Kerb weight	1389 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2

Engine number

ARL 073617