





report date: 2024-03-28

General information

Make	FORD
Model	RANGER XLT 4X4 TD
Colour	Silver
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	266 Nm at 2.000 rpm
Engine capacity	2.500 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/17



Internet history

Emter.	1
Entry	т.

ciitiy 1	
Date	2021-06-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT expiry date	2024-11-16
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	48
Total items failed	28

MOT #25	2023-11-17 13:59
MOT test number	521161596466
Result	✓ Passed
Next expiry date	2024-11-16

MOT #24	2023-11-02 10:20
MOT test number	857722626346
Result	× Failed
Fail Exhaust system insecure (6.1.2 (a))	
Fail Nearside Drag link end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))	
Advice Both rear springs misalighned	
Fail Offside Front Drag link end ball joint has excessive play (2.1.3 (b) (i))	

MOT #23	2022-11-08 16:11
MOT test number	281213667123
Result	✓ Passed
Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))	

CarCheck.co.uk page 3/17



MOT #22 2022-10-10 10:17

MOT test number 179802589023

Result X Failed

Fail Nearside Front Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Offside Front Shock absorbers has an excessively worn bush (5.3.2 (c))

Advice Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Fail Offside Rear Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))

Fail Offside Rear Position lamp adversely affected by the operation of another lamp (4.2.3 (c))

MOT #21 2021-10-14 12:51

MOT test number 239511223914

Result

Passed

Advice Offside Front Vehicle structure is corroded but structural rigidity is not significantly reduced Body mount (6.1.1 (c) (i))

CarCheck.co.uk page 4/17



AJ05UKH

report date: 2024-03-28

MOT #20 2020-10-17 11:20 **MOT test number** 930534922597 Result ✓ Passed **Advice** Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c)) Nearside steering idler bushes wearing Advice Advice Offside Front inner wing/floor corroded but not holed Advice Various under body and chassis surface corrosion All suspension components corroded **Advice**

MOT #19	2020-10-17 09:13
MOT test number	736033298533
Result	★ Failed
Advice Various under body and chassis surface corrosion	
Advice Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c)))
Advice All suspension components corroded	
Fail Offside Front Anti-roll bar linkage pin or bush likely to become detached link bar	broken (5.3.4 (a) (ii))
Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))	
Advice Nearside steering idler bushes wearing	
Fail Offside Front Service brake excessively binding (1.2.1 (f))	
Advice Offside Front inner wing/floor corroded but not holed	
Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in exce bar (5.3.4 (a) (i))	ssive movement link

CarCheck.co.uk page 5/17



MOT #18 2019-06-22 11:18

MOT test number 703628565754

Result \rightarrow Passed

Advice Various under body corrosion but all ok for mot

Advice Brake pipe corroded, covered in grease or other material All Pipes (1.1.11 (c))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #17 2019-06-22 09:19

MOT test number 425306346096

Result X Failed

Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Brake pipe corroded, covered in grease or other material All Pipes (1.1.11 (c))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Various under body corrosion but all ok for mot

MOT #16 2018-06-20 15:37

MOT test number 374795897292

Result ✓ Passed

Advice Various under body corrosion but all ok for mot

Advice Brake pipe corroded, covered in grease or other material all pipes coated but appear ok (1.1.11 (c))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 6/17



× Failed

MOT #15 2018-06-16 08:35
MOT test number 892006428366

MOT test number 892006428366

Fail Nearside Front Service brake excessively binding (1.2.1 (f))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Various under body corrosion but all ok for mot

Advice Brake pipe corroded, covered in grease or other material all pipes coated but appear ok (1.1.11

(c))

Result

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Rear Tyre worn close to legal limit/worn on edge both sides, also cracking (5.2.3 (e))

MOT #14 2017-06-20 11:22

MOT test number 292431157703

Result ✓ Passed

Advice Both Front Tyre's Perishing

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Various underbody parts corroded but all still to mot standards

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice All Brake pipes have been coated

CarCheck.co.uk page 7/17



MOT #13 2017-06-17 08:34

MOT test number 798517122516

Result X Failed

Fail Offside Front Side repeater incorrect colour (1.4.A.2f)

Advice All Brake pipes have been coated

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Both Front Tyre's Perishing

Fail Direction indicator incorrect colour Both Rear (1.4.A.2f)

Fail Central Exhaust system not adequately supported exhaust hanger (7.1.1)

Advice Various underbody parts corroded but all still to mot standards

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Rear fog lamp not working (1.3.2b)

MOT #12 2016-06-07 11:55

MOT test number 215053370336

Result

Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11 2016-06-03 08:47

MOT test number 473129320623

Result × Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

CarCheck.co.uk page 8/17



MOT test number

837878965126

Result

Notice Exhaust center mounting strap broken and also has a slight blow on join

Notice Note; unable to fully inspect brake pipes due to coating of grease

Notice Under-trays fitted obscuring some underside components

Notice Spare tyre flat

MOT #9	2014-06-19 14:01
MOT test number	359760674180
Result	✓ Passed
MOT #8	2013-06-20 09:37
MOT test number	275591273108
Result	✓ Passed
Notice Centre exhaust bracket broken sytem still supported	

MOT #7	2012-06-21 12:04
MOT test number	108093372177
Result	✓ Passed

MOT #6	2011-06-30 08:47
MOT test number	167441481190
Result	✓ Passed

MOT #5	2010-06-24 16:29
MOT test number	370955670163
Result	✓ Passed

CarCheck.co.uk page 9/17



MOT #4

MOT test number

Result

Exhaust system not adequately supported (7.1.1)

MOT #3 2009-06-17 12:56 **MOT test number** 543508769180 Result ✓ Passed MOT #2 2009-06-17 12:56 **MOT** test number 811538369123 Result × Failed **Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2008-06-24 13:18
MOT test number	830936478178
Result	✓ Passed


CarCheck.co.uk page 10/17



See MOT history

Tax & MOT check

Full MOT history



CarCheck.co.uk page 11/17



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

e mier metery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 14/17



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 15/17



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-06-30
Last registration	2023-11-17
Complete history	See info



Registration #1	2005-06-30	25 mi
Registration #2	2008-06-24	11.093 mi
Registration #3	2009-06-17	13.636 mi
Registration #4	2010-06-24	18.056 mi
Registration #5	2010-06-24	18.056 mi
Registration #6	2011-06-30	24.687 mi
Registration #7	2012-06-21	32.485 mi
Registration #8	2013-06-20	39.977 mi
Registration #9	2014-06-19	45.641 mi
Registration #10	2015-06-17	50.066 mi
Registration #11	2016-06-03	53.789 mi
Registration #12	2016-06-07	53.789 mi
Registration #13	2017-06-17	57.131 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		71.777 es
Registration #25		11.777 esi
Registration #26		11.777 au

CarCheck.co.uk page 16/17



Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Additional information

Fuel tank capacity	70 I
Fuel delivery	Indirect Injection
Number of doors	4
Number of seats	5
Engine number	551939

CarCheck.co.uk page 17/17