





# General information

Make	HYUNDAI
Model	I20 CLASSIC
Colour	Blue
Year of manufacture	2013
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	84 BHP
Max. torque	120 Nm at 4.000 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg
CO2 emission	114 g/km
CO2 label	С





Internet history		
Entry 1		
Date	2021-01-31	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk



# MOT history

MOT expiry date	2025-03-17
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	14
Total items failed	10

MOT #14	2024-03-04 11:58
MOT test number	430098188966
Result	✓ Passed
Next expiry date	2025-03-17
Advice Offside Front auxilary drive belt perished	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing badly cracked and inner tread stepped 18560x15 (5.2.3 (d) (ii))	
Advice Exhaust corroded	
Advice Rear Coil spring corroded nearside and offside (5.3.1 (b) (i))	

MOT #13	2023-03-08 08:46
MOT test number	294327349937
Result	✓ Passed
Advice Items removed from driver's view prior to test	





MOT #12	2023-03-08 08:46
MOT test number	264117242733
Result	× Failed
Pass with rectification	Nearside Rear Seat belt not functioning as intended (7.1.2 (c))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice Items removed f	rom driver's view prior to test
<b>Pass with rectification</b> (ii))	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

MOT #11		2022-03-01 15:08
MOT test	number	663205051361
Result		✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #10	2022-03-01 10:42
MOT test number	329092928598
Result	🗙 Failed
Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress	of dirt (5.3.4 (b) (ii))
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	
FailNearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)(ii))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

МОТ #9	2021-03-18 09:37
MOT test number	266906561791
Result	✓ Passed





MOT #8	2020-07-13 12:04
MOT test number	363869109733
Result	🗸 Passed
MOT #7	2020-07-13 10:23
MOT test number	606808880598
Result	🗙 Failed
<b>Fail</b> Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
<b>Fail</b> Offside Rear Seat belt buckle not functioning as intended (7.1.2 (d))	
MOT #6	2019-06-17 10:47

MOT test number	523274699047
Result	✓ Passed

MOT #5	2019-06-17 10:47
MOT test number	343599843015
Result	× Failed
Pass with rectification	Front Windscreen washer provides insufficient washer liquid both sides (3.5 (a))

MOT #4	2018-02-06 10:52
MOT test number	881957816021
Result	✓ Passed
Advice Nearside Rear Nail in tyre	





MOT #3		2018-02-06 10:52
MOT test number		669075278484
Result		🗙 Failed
Advice Nearside Rear N	ail in tyre	
Pass with rectification	Offside Front Front position lamp(s) not working (1.1.A.3b)	
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)	

MOT #2		2017-02-08 09:34
MOT test	number	330604086893
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
MOT #1		2016-02-04 09:35

MOT test number	884849541029
Result	✓ Passed



Tax & MOT check

<b>Tax due:</b> 1 March 2025	√ axed	<b>Expires:</b> 17 March 2025	√ мот
Tax status			Valid until 1 March
Days left			306
MOT expiry date			17 March 2025
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





## Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E E H - S - A
Date	*
Category	AMP.
Туре	

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and a second sec	
*********	
********	
*******	
********	
********	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-03-01
Last registration	2024-03-04
Complete history	<u>See info</u>



Registration #1	2013-03-01	13 mi
Registration #2	2016-02-04	21.822 mi
Registration #3	2017-02-08	28.303 mi
Registration #4	2018-02-06	34.427 mi
Registration #5	2018-02-06	34.427 mi
Registration #6	2019-06-17	41.926 mi
Registration #7	2019-06-17	41.926 mi
Registration #8	2020-07-13	46.213 mi
Registration #9		11.177 mi
Registration #10		10.200 est
Registration #11		11.777 mi
Registration #11 Registration #12		10.000 est
-		10.000 est 10.000 est 10.000 est
Registration #12		10.000 mi 0.000 mi 00.000 mi 00.000 mi
Registration #12 Registration #13		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est

More info >





# Car features

50225	Air conditioning
50295	
50482	
60501	
0566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	88%
Children	83%
Pedestrian	64%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1710 mm
Height	1490 mm
Length	3995 mm
Wheel base	2525 mm
Kerb weight	1083 kg
Max. allowed weight	1515 kg
Additional information	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13