





report date: 2024-03-28

General information

Make	JAGUAR
Model	XK8 CONVERTIBLE
Colour	Green
Year of manufacture	2000
Top speed	155 mph
0 - 60 mph	6.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	290 BHP
Max. torque	393 Nm at 4.250 rpm
Engine capacity	3.996 сс
Cylinders	8
Fuel type	Petrol
Consumption city	15.9 mpg
Consumption extra urban	33.4 mpg
Consumption combined	23.9 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-15


Pictures 16

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



report date: 2024-03-28

MOT history

Advice

MOT expiry date	2025-01-09
MOT pass rate	90 %
MOT passed	19
Failed MOT tests	2
Total advice items	55
Total items failed	8

MOT #21	2024-01-09 09:37	
MOT test number	414712528358	
Result	✓ Passed	
Next expiry date	2025-01-09	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #20	2023-12-20 12:42	
MOT test number	594852715770	
Result	× Failed	
Fail Nearside Front Suspension component mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing the structural strength inner wing/chassis within subframe mounting prescribed area excessive reducing the structural struct		
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))		
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))		
Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wing/chassis within subframe mounting prescribed area (5.3.6 (a) (i))		
Advice Corrosion on both front floor pans and both rear lower outer sills		
Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))		

CarCheck.co.uk page 3/15

Nearside Front Brake pipe corroded, covered in grease or other material inner arch (1.1.11 (c))



report date: 2024-03-28

MOT #19 2022-12-20 15:26

MOT test number 703323785334

Result ✓ Passed

Advice Offside Front Excessive corrosion found behind front subframe in wheel arch, however affected panel not considered to be load bearing or structural part of chassis.

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement 'D' bush (5.3.4 (a) (i))

MOT #18 2022-01-10 07:03

MOT test number 849657135394

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside mirror glass deteriorated.

Advice Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside rear tyre sidewall perishing/scuffed.

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside mirror glass deteriorated.

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside front tyre sidewall perishing/scuffed.

Advice Offside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-28

MOT #17 2020-11-19 12:37

MOT test number 588525018736

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt minor (2.1.3 (g) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan rusty (5.3.6 (a) (i))

Minor Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #16 2019-12-07 11:47

MOT test number 342161566237

Result

Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis rail (5.3.6 (a) (i))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan (5.3.6 (a) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis rail (5.3.6 (a) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan (5.3.6 (a) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

CarCheck.co.uk page 5/15



report date: 2024-03-28

MOT #15 2019-12-05 10:09

MOT test number 361591920682

Result X Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis rail (5.3.6 (a) (i))

Fail Offside Rear Outer Suspension component mounting prescribed area excessively damaged significantly reducing structural strength sill (5.3.6 (a) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Nearside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan (5.3.6 (a) (i))

Advice Nearside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

Fail Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive chassis rail (5.3.6 (a) (i))

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive floor pan (5.3.6 (a) (i))

Fail Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

Advice Offside Rear Drive shaft joint worn, but not excessively (6.1.7 (c) (i))

MOT #14 2018-12-12 12:44

MOT test number 744219263356

Result

✓ Passed

MOT #13 2017-10-05 14:08

MOT test number 989090762475

CarCheck.co.uk page 6/15



report date: 2024-03-28

MOT #12

MOT test number

Result

Advice Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #11

MOT test number

Passed

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #10

MOT test number

S49644194206

Result

Notice Drivers floor corroded

MOT #9

MOT test number

S85878293281

Result

√ Passed

MOT #8 2012-10-08 12:37
MOT test number 856612382292
Result
✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 7/15



report date: 2024-03-28

MOT #7 2011-10-11 11:57

MOT test number 376744481446

Result \rightarrow Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

MOT #6 2010-10-08 10:30

MOT test number 804451580281

Result \(\sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2009-10-29 10:29

MOT test number 762572809303

Result ✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2008-10-28 12:53

MOT test number 873072508310

Result

Passed

MOT #3 2007-10-23 13:12

MOT test number 923936997272

MOT #2 2006-10-13 17:42

MOT test number 951366086224

Result

Passed

CarCheck.co.uk page 8/15



MOT #1 2005-10-07 10:35

MOT test number 871110485212


CarCheck.co.uk page 9/15



See MOT history

_

Full MOT history



CarCheck.co.uk page 10/15



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/15



Owner history

e mier metery	
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	NK NEW
Plate since	
	More info >
	PIOTE IIIIO /

CarCheck.co.uk page 12/15



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 13/15



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2000-11-15
Last registration	2024-01-09
Complete history	See info



Registration #1	2000-11-15	7 mi
Registration #2	2005-10-07	35.169 mi
Registration #3	2006-10-13	38.629 mi
Registration #4	2007-10-23	43.143 mi
Registration #5	2008-10-28	47.238 mi
Registration #6	2009-10-29	51.402 mi
Registration #7	2010-10-08	54.766 mi
Registration #8	2011-10-11	59.334 mi
Registration #9	2012-10-08	63.092 mi
Registration #10	2013-10-25	67.172 mi
Registration #11	2014-10-21	68.823 mi
Registration #12	2015-10-02	71.077 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 14/15



		_		
- I) Im	ension	c l	WAIG	nt.
	CHSIUH	3 W	weiu	III.

Width	2015 mm
Height	1306 mm
Length	4760 mm
Wheel base	2588 mm

Additional information

Fuel tank capacity	75 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	NB0012020817

CarCheck.co.uk page 15/15