



HG54VVU

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT 300 LWB HR P/V
Colour	Red
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2021-12-17
MOT pass rate	54 %
MOT passed	13
Failed MOT tests	11
Total advice items	90
Total items failed	62

MOT #24	2020-12-18 17:19
---------	------------------

MOT test number	634220198878
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2021-12-17
------------------	------------

- Minor

Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Front and rear chassis corroded
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Front inner arch corroded
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Tested wet
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Rear and middle cross beams corroded
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #23**

2020-12-10 12:46

MOT test number

104148436665

Result**✗ Failed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front and rear chassis corroded
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front inner arch corroded
- Fail** Exhaust gas recirculation valve obviously modified (8.2.2.1 (a))
- Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis near subframe (5.3.6 (a) (i))
- Advice** Tested wet
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear and middle cross beams corroded
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner arch (5.3.6 (a) (i))

MOT #22

2019-12-04 14:50

MOT test number

434975202301

Result**✓ Passed**

- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced all chassis corroding (6.1.1 (c) (i))



MOT #21	2019-12-04 10:21
MOT test number	845776747726
Result	✗ Failed
Fail	Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Advice	Vehicle structure is corroded but structural rigidity is not significantly reduced all chassis corroding (6.1.1 (c) (i))

MOT #20	2018-09-05 15:57
MOT test number	336459688569
Result	✓ Passed
Advice	Power steering close to minimum mark (2.1.5 (b) (i))
Advice	Rear cross members slight corrosion
Advice	Rear chassis slight corrosion
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Welding throughout underside of vehicle

**MOT #19**

2018-09-05 15:50

MOT test number

350364245389

Result**✗ Failed**

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength cross member (5.3.6 (a) (i))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wing (5.3.6 (a) (i))

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Advice Rear cross members slight corrosion

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced sill to floor (7.1.1 (a) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Power steering close to minimum mark (2.1.5 (b) (i))

Advice Rear chassis slight corrosion

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Fail Central Parking brake mechanism/associated mounting prescribed area is excessively corroded x2 places (1.1.21 (e) (i))

**MOT #18**

2018-08-29 14:49

MOT test number

147553067516

Result**✗ Failed**

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner wing (5.3.6 (a) (i))

Advice Power steering close to minimum mark (2.1.5 (b) (i))

Advice Rear cross members slight corrosion

Fail Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced sill to floor (7.1.1 (a) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Rear chassis slight corrosion

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Suspension component mounting prescribed area excessively corroded significantly reducing structural strength chassis (5.3.6 (a) (i))

Fail Offside Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))

Fail Central Parking brake mechanism/associated mounting prescribed area is excessively corroded x2 places (1.1.21 (e) (i))

Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength cross member (5.3.6 (a) (i))

MOT #17

2017-03-01 12:58

MOT test number

219651160126

Result**✓ Passed**

Advice All light underside corrosion

Advice Front Brake pad(s) wearing thin (3.5.1g)

**MOT #16**

2016-11-23 12:20

MOT test number

266663956041

Result**✗ Failed**

- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded chassis (2.4.A.3)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded behind seat (5.2.6)
- Fail** Offside Upper Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Body has a projection caused by corrosion tipper body (6.1.C.1)
- Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Oil leak
- Advice** All general body and chassis corrosion
- Fail** Offside Front Suspension spring mounting prescribed area is excessively corroded inner arch (2.4.A.3)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded inner sill (5.2.6)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded behind seat (5.2.6)
- Advice** Coolant leak pipe rubbed through on injector
- Fail** Parking brake mechanism/associated mounting prescribed area is excessively corroded chassis (3.1.9)
- Advice** Nearside Front brake disc modified but not seriously weakened scored (3.5.1n)
- Advice** Exhaust system deteriorated
- Fail** Nearside Front Suspension spring mounting prescribed area is excessively corroded inner arch (2.4.A.3)
- Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)
- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #15**

2016-10-13 13:15

MOT test number

270810937230

Result

✗ Failed

- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Nearside Body has a sharp edge caused by corrosion tubular step (6.1.C.1)
- Advice** Oil leak
- Advice** Offside Front Upper marker light not working
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Centre Parking brake mechanism/associated mounting prescribed area is excessively corroded cross member (3.1.9)
- Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Front Lower Body has a sharp edge caused by corrosion both sills (6.1.C.1)
- Advice** Offside Front Upper Coolant leak chaffing on injector pipe
- Fail** Front Lower Parking brake lever, pawl mechanism pivots or their associated mountings are insecure mount (3.1.4b)
- Fail** Centre Seat belt anchorage prescribed area is excessively corroded cab floor (5.2.6)

MOT #14

2015-10-24 11:15

MOT test number

769557173668

Result

✓ Passed

- Advice** Nearside Front floor slightly corroded, on seat/belt mount
- Advice** Offside Rear tyre has a nail

**MOT #13**

2015-10-15 15:06

MOT test number

835222162692

Result

✗ Failed

Advice

Nearside Front floor slightly corroded, on seat/belt mount

Fail

Nearside Rear Suspension spring mounting prescribed area is excessively corroded cross member (2.4.A.3)

Fail

Centre Parking brake mechanism/associated mounting prescribed area is excessively corroded chassis cross member (3.1.9)

Fail

Offside Front Inner Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings top of chassis leg next to engine mount (6.1.B.2)

Advice

Offside Rear tyre has a nail

Fail

Parking brake lever has no reserve travel (3.1.6b)

Fail

Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings chassis centre & rear cross members (6.1.B.2)

MOT #12

2014-10-27 10:55

MOT test number

396070504392

Result

✓ Passed

Advice

Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Notice

Vehicle's internal headlight adjuster altered to recheck lights

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #11

2013-10-28 16:17

MOT test number

437721103411

Result

✓ Passed

Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice

Vehicle structure has slight corrosion (6.1.A.1)

Advice

Body has slight corrosion (6.1.B.2)

Notice

Vehicle's internal headlight adjuster altered to recheck lights



MOT #10	2013-10-23 12:15
MOT test number	917086593299
Result	✗ Failed
Advice	Body has slight corrosion (6.1.B.2)
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Notice	Vehicle's internal headlight adjuster altered to recheck lights
Advice	Vehicle structure has slight corrosion (6.1.A.1)
Fail	Offside Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

MOT #9	2012-11-03 08:58
MOT test number	479248602349
Result	✓ Passed
Notice	Filler neck to rubber, breather hose deteriorated
Advice	Nearside Seat belt stitching slightly frayed (5.2.2b)
Advice	Offside Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Nearside rear position marker light has slight damage
Advice	Offside Seat belt stitching slightly frayed (5.2.2b)

**MOT #8** 2012-10-29 13:52**MOT test number** 956023002322**Result** ✗ Failed**Advice** Offside Seat belt stitching slightly frayed (5.2.2b)**Notice** Filler neck to rubber, breather hose deteriorated**Fail** Nearside Lower Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Advice** Nearside Seat belt stitching slightly frayed (5.2.2b)**Advice** Offside Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nearside rear position marker light has slight damage**Fail** Offside Lower Seat belt anchorage prescribed area is excessively corroded (5.2.6)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #7** 2011-11-02 11:10**MOT test number** 689506301309**Result** ✓ Passed**MOT #6** 2011-10-26 12:39**MOT test number** 579879091287**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Centre Vehicle structure has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)**Fail** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)



MOT #5	2010-10-26 09:39
MOT test number	910629790290
Result	✓ Passed
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	N/s/r light lens cracked
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Notice	Both front coil springs corroding
Notice	N/s mirror casing broken/missing

MOT #4	2009-11-09 12:58
MOT test number	684543019374
Result	✓ Passed
Notice	N/s mirror casing broken/missing
Notice	N/s/r light lens cracked
Notice	N/s mirror glass cracked
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3**

2009-11-05 17:14

MOT test number

432019409338

Result**✗ Failed**

- Notice** N/s/r light lens cracked
- Fail** Power steering pump leaking from a failed component (2.3.3b)
- Notice** N/s mirror glass cracked
- Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Notice** N/s mirror casing broken/missing
- Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #2

2008-10-21 13:06

MOT test number

394115998445

Result**✓ Passed**

- Notice** Ns door mirror backing missing
- Notice** Ns windscreen trim loose

MOT #1

2007-10-30 11:02

MOT test number

563323907323

Result**✓ Passed**

- Notice** N/s/r light lens cracked
- Notice** Slight leak from power steering pump



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2020-01-01
Current registration	XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-11-09
Last registration	2020-12-18
Complete history	See info



Registration #1	2004-11-09	26 mi
Registration #2	2007-10-30	13.421 mi
Registration #3	2008-10-21	21.476 mi
Registration #4	2009-11-05	27.288 mi
Registration #5	2009-11-09	27.288 mi
Registration #6	2010-10-26	33.508 mi
Registration #7	2011-10-26	40.761 mi
Registration #8	2011-11-02	40.768 mi
Registration #9	2012-10-29	51.500 mi
Registration #10	2012-11-03	51.500 mi
Registration #11	2013-10-23	57.609 mi
Registration #12	2013-10-28	57.804 mi
Registration #13	2014-10-28	57.804 mi
Registration #14	2015-10-28	57.804 mi
Registration #15	2016-10-28	57.804 mi
Registration #16	2017-10-28	57.804 mi
Registration #17	2018-10-28	57.804 mi
Registration #18	2019-10-28	57.804 mi
Registration #19	2020-10-28	57.804 mi
Registration #20	2021-10-28	57.804 mi
Registration #21	2022-10-28	57.804 mi
Registration #22	2023-10-28	57.804 mi
Registration #23	2024-10-28	57.804 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1974 mm
Kerb weight	1766 kg
Max. allowed weight	3000 kg

Additional information

Number of axles	2
Engine number	3P70193