



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA VTX 16V PICASSO
Colour	Beige
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	13.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	215 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT #23

2024-03-06 11:00

MOT test number

434594418084

Result

✗ Failed

- Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))
- Fail** Brake performance unable to be tested (1.2.1 (g))
- Fail** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced outer sill (7.1.1 (a) (i))
- Fail** Offside Front Brake pipe leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #22

2023-03-01 11:14

MOT test number

589900811076

Result

✓ Passed

MOT #21

2023-03-01 11:14

MOT test number

294923765508

Result

✗ Failed

- Pass with rectification** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))



MOT #20	2022-03-16 14:42
MOT test number	822925857039
Result	✓ Passed

MOT #19	2022-03-16 14:42
MOT test number	189291871318
Result	✗ Failed
<div>Pass with rectification</div> Headlamp aim too low (4.1.2 (a))	

MOT #18	2021-12-16 13:51
MOT test number	321319266595
Result	✓ Passed
<div>Advice</div> Oil leak, but not excessive (8.4.1 (a) (i))	
<div>Advice</div> Rear Shock absorbers has slight external damage to the casing BOTH SHOCK ABSORBERS CORRODED (5.3.2 (b))	
<div>Advice</div> Offside Rear OSR LIGHT UNIT DAMAGED	
<div>Advice</div> Oil leak, but not excessive FRONT DRIVESHAFT OIL SEALS LEAKING (8.4.1 (a) (i))	

**MOT #17**

2021-11-30 12:52

**MOT test number**

632924794534

**Result****✗ Failed****Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front FRONT SUBFRAME CORRODING.**Advice** Offside Rear OSR TYRE 2015 YEAR OF MANUFACTURE,ADVISE OLD & DETERIORATING.**Fail** Nearside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt ADVISE BOTH SIDES. (2.1.3 (g) (ii))**Fail** Offside Front Seat belt anchorage prescribed area strength or continuity significantly reduced OUTER SILL CORRODED THROUGH,POSSIBLE FRONT TO REAR. (7.1.1 (a) (i))**Advice** Front Oil leak, but not excessive BOTH FRONT DRIVE SHAFT OIL SEALS LEAKING. (8.4.1 (a) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Direction indicator incorrect colour SHOWING WHITE. (4.4.3 (a))**Advice** Offside Rear OSR LIGHT UNIT DAMAGED.**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Front Seat belt anchorage prescribed area strength or continuity significantly reduced OUTER SILL CORRODED THROUGH ,FRONT TO REAR. (7.1.1 (a) (i))**Advice** Nearside Rear NSR TYRE 2003 YEAR OF MANUFACTURE,ADVISE OLD & PERISHING.(185-65X15H)**Advice** Front Brake pipe corroded, covered in grease or other material NSF & OSF METAL BRAKE PIPES CORRODED,WILL REQUIRE REPLACING SOON. (1.1.11 (c))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Brake pipe excessively corroded BOTH FRONT TO REAR METAL BRAKE PIPES HEAVILY CORRODED. (1.1.11 (c))**Advice** Shock absorbers has slight external damage to the casing FRONT & REAR SHOCK ABSORBERS HEAVILY CORRODED. (5.3.2 (b))**MOT #16**

2020-12-22 18:05

**MOT test number**

930262619871

**Result****✓ Passed**

**Advice** Outer Vehicle structure is corroded but structural rigidity is not significantly reduced both sills  
(6.1.1 (c) (i))

**MOT #15** 2019-09-24 08:47**MOT test number** 491962825848**Result** ✓ Passed

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced both outer sills (6.1.1 (c) (i))

**MOT #14** 2018-10-02 10:23**MOT test number** 627883147163**Result** ✓ Passed

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced at both outer sills (6.1.1 (c) (i))

**MOT #13** 2017-10-04 08:27**MOT test number** 561656842988**Result** ✓ Passed

**Advice** Offside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Nearside Vehicle structure has slight corrosion outer sills (6.1.B.2)

**MOT #12** 2016-09-26 10:50**MOT test number** 426701030100**Result** ✓ Passed

**Advice** Nearside Rear Nail in tyre

**MOT #11** 2016-09-23 11:13**MOT test number** 998516338965**Result** ✗ Failed

**Fail**

Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail**

Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice**

Nearside Rear Nail in tyre



**MOT #10** 2015-10-12 12:21**MOT test number** 679874635922**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-10-10 13:25**MOT test number** 495423984273**Result** ✓ Passed**MOT #8** 2014-10-10 13:25**MOT test number** 148713784203**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2013-10-02 12:34**MOT test number** 257455873211**Result** ✓ Passed**MOT #6** 2012-10-09 10:58**MOT test number** 499813582256**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2012-10-09 10:58**MOT test number** 258933382245**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Pass with rectification** Offside Headlamp aim too high (1.8)

**MOT #4** 2011-10-14 13:11**MOT test number** 558677781293**Result** ✓ Passed**MOT #3** 2010-10-15 15:05**MOT test number** 240188380291**Result** ✓ Passed**MOT #2** 2010-04-01 16:49**MOT test number** 150361990455**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2010-04-01 10:42**MOT test number** 933291390047**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Direction indicator not working (1.4.A.2c)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>SE07EHW</b>
Plate since	2019-09-28
Current registration	<b>SE07EHW</b>
Plate since	2019-09-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-05-14
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2007-05-14	6 mi
Registration #2	2010-04-01	31.771 mi
Registration #3	2010-04-01	31.771 mi
Registration #4	2010-10-15	32.796 mi
Registration #5	2011-10-14	35.292 mi
Registration #6	2012-10-09	38.167 mi
Registration #7	2013-10-02	40.258 mi
Registration #8	2014-10-10	41.460 mi
Registration #9	2015-10-12	42.837 mi
Registration #10	2016-09-23	43.767 mi
Registration #11	2016-09-26	43.767 mi
Registration #12	2017-10-04	48.987 mi
Registration #13	2018-05-20	55.277 mi
Registration #14	2018-05-20	55.277 mi
Registration #15	2018-05-20	55.277 mi
Registration #16	2018-05-20	55.277 mi
Registration #17	2018-05-20	55.277 mi
Registration #18	2018-05-20	55.277 mi
Registration #19	2018-05-20	55.277 mi
Registration #20	2018-05-20	55.277 mi
Registration #21	2018-05-20	55.277 mi
Registration #22	2018-05-20	55.277 mi
Registration #23	2018-05-20	55.277 mi

More info >



Safety ratings

NCAP rating 

★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1751 mm
Height	1637 mm
Length	4276 mm
Wheel base	2760 mm
Kerb weight	1300 kg
Max. allowed weight	1850 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JB660199901