





report date: 2024-03-29

#### General information

Make	KIA
Model	SORENTO CRDI XT
Colour	Blue
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	138 BHP
Max. torque	343 Nm at 1.850 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg



CarCheck.co.uk page 1/15



report date: 2024-03-29

#### **MOT** history

**MOT #21** 2021-01-15 10:19

MOT test number 178600131216

**Result** 
✓ Passed

Next expiry date 2022-01-18

Advice Offside Front Exhaust has a minor leak of exhaust gases joint B4 cat (6.1.2 (a))

**Advice** Handbrake has littlr reser travel

**Advice** Front Noise front tensor belt pully/bearing

**Advice** Headlamp has a product on the lens but not seriously reducing light output both lenes sligthy cloudy (4.1.4 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Vehicle structure is corroded but structural rigidity is not significantly reduced Chassie leg (6.1.1 (c) (i))

**Advice** Rear Parking brake imbalanced

**Advice** Brake pedal wearing smooth (1.1.2 (c))

Advice Nearside Front Prob shaft removed

CarCheck.co.uk page 2/15



report date: 2024-03-29

**MOT #20** 2021-01-06 11:21

**MOT test number** 447308411992

Result X Failed

Advice Offside Front Exhaust has a minor leak of exhaust gases joint B4 cat (6.1.2 (a))

**Advice** Front Noise front tensor belt pully/bearing

Advice Offside Vehicle structure is corroded but structural rigidity is not significantly reduced Chassie leg (6.1.1 (c) (i))

**Fail** Exhaust emissions exceed manufacturer's specified limit 0.80 (8.2.2.2 (a))

**Advice** Brake pedal wearing smooth (1.1.2 (c))

**Advice** Rear Parking brake imbalanced

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**Fail** Nearside Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced Chassie leg (6.1.1 (c) (i))

Advice Nearside Front Prob shaft removed

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Handbrake has littlr reser travel

**Advice** Headlamp has a product on the lens but not seriously reducing light output both lenes sligthy cloudy (4.1.4 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19** 2020-01-17 16:37

MOT test number 109718339326

Result \rightarrow Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Both chassis legs (6.1.1 (c) (i))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/15



report date: 2024-03-29

× Failed

**MOT #18** 2020-01-08 12:28

**MOT test number** 459965075105

Result

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Front Brakes imbalanced across an axle (1.2.1 (b) (i))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Both chassis legs (6.1.1 (c) (i))

**MOT #17** 2019-01-17 10:15

**MOT test number** 391329677070

**Result** 
✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cut outer sidewall no cords xpos (5.2.3 (d) (ii))

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Front center to front prob shaft removed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced slight corrtion, both chassie legs (6.1.1 (c) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 4/15



report date: 2024-03-29

**MOT #16** 2019-01-08 15:30

MOT test number 304618181318

Result X Failed

Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Rear Brake pipe excessively corroded front to rear pipe (1.1.11 (c))

**Fail** Nearside Front Position lamp not working (4.2.1 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cut outer sidewall no cords xpos (5.2.3 (d) (ii))

**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced slight corrtion, both chassie legs (6.1.1 (c) (i))

**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a) (ii))

Fail Brake performance not tested n/s/r pad/disc metel to metel & both front to rear brake pipes badly corrded (1.2.1 (g))

Fail Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Advice** Nearside Front center to front prob shaft removed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Rear Brake pipe excessively corroded front to rear pipe (1.1.11 (c))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #15

MOT test number

334108473571

Result

✓ Passed

**MOT #14** 2018-01-16 08:09

**MOT test number** 452947922413

Result X Failed

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Fail** Offside Front Inner Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

**Fail** Offside Steering rack gaiter split (2.2.D.2d)

**Fail** Parking brake: efficiency below requirements (3.7.C.1b)

**Fail** Offside Rear coil spring broken (2.4.C.1a)

**Fail** Offside Power steering component(s) leaking from a failed seal (2.3.3b)

**MOT #13** 2017-01-17 12:53

MOT test number 538741500715

Result \( \sqrt{Passed} \)

**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)

**Advice** Offside Brake pipe slightly corroded Front to Rear (3.6.B.2c)

**Advice** Nearside Brake pipe slightly corroded Front to Rear (3.6.B.2c)

CarCheck.co.uk page 6/15



report date: 2024-03-29

**MOT #12** 2017-01-10 12:57 950016212453 **MOT** test number Result × Failed Fail Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2) Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c) **Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c) Advice Offside Brake pipe slightly corroded Front to Rear (3.6.B.2c) Fail Offside Rear Wheel nut(s) missing (4.2.A.1e) Fail Parking brake: efficiency below requirements (3.7.B.7) Offside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2) Fail Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c) **Advice** Nearside Brake pipe slightly corroded Front to Rear (3.6.B.2c) Fail Rear fog lamp not working (1.3.2b) Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

MOT #11		2016-01-11 10:28
MOT test number		473079192442
Result		✓ Passed
MOT #10		2016-01-11 10:28
MOT test number		762297165289
Result		<b>X</b> Failed
Pass with rectification	Parking brake lever has no reserve travel (3.1.6b)	

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT #9

MOT test number

Result

Notice Engine covers fitted obscuring some components in the engine bay

2015-07-31 10:08

719382115236

MOT #8

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT test number

Result

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT test number

Result

Advice (2.4.G.2)

Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

 MOT #5
 2012-01-28 13:20

 MOT test number
 338648222002

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



report date: 2024-03-29

MOT #4	2012-01-28 10:50
MOT test number	807618122043
Result	<b>x</b> Failed
Fail Offside Rear rear brake binding (3.7.B.1)	

<b>Fail</b> Offside Rear rear brake binding (3.7.B.1)	
MOT #3	2011-02-05 12:58
MOT test number	765316131054
Result	<b>✓</b> Passed
MOT #2 MOT test number	2010-01-30 12:11 101910430441
Result	701910430441 ✓ Passed
	·
MOT #1	2009-01-23 14:11
MOT test number	700013629073
Result	<b>✓</b> Passed
Notice Outer sills covered	

CarCheck.co.uk page 9/15



report date: 2024-03-29

#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

### Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
HARMAN CONTRACTOR CONT	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Current registration	NE AIR
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

#### Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 13/15



report date: 2024-03-29

## Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-01-31
Last registration	2021-01-15
Complete history	See info



2006-01-31	27 mi
2009-01-23	24.978 mi
2010-01-30	30.335 mi
2011-02-05	37.371 mi
2012-01-28	44.885 mi
2012-01-28	44.885 mi
2013-02-02	50.721 mi
2014-02-01	55.872 mi
2014-07-28	57.629 mi
2015-07-31	74.068 mi
2016-01-11	78.935 mi
	11.777 es
	0.00 44
	11.777 es
	11.777 es
	91.777 es
	0.00 44
	0.074
	11.777 au
	2010-01-23 2010-01-30 2011-02-05 2012-01-28 2012-01-28 2013-02-02 2014-02-01 2014-07-28 2015-07-31 2016-01-11

More info >

CarCheck.co.uk page 14/15



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1884 mm
Height	1804 mm
Length	4567 mm
Wheel base	2710 mm
Kerb weight	2056 kg
Max. allowed weight	2600 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 15/15

Number of axles 2

Engine number D4CB5878441