



report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Sequential

Engine & fuel consumption

Power	145 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-01
Pictures	8
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #15**

2022-07-19 15:58

**MOT test number**

621612801256

**Result**

✓ Passed

**Next expiry date**

2023-07-18

- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Rear Coil spring corroded Both springs (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Body component slightly loose Lower bumper panel (6.2.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced Various parts of under body (6.1.1 (c) (i))
- Advice** Nearside Front Road wheel slightly distorted Inner bead (5.2.2 (c) (i))
- Advice** Nearside Front Body component slightly loose Bumper (6.2.1 (a) (i))

**MOT #14**

2022-07-15 15:59

**MOT test number**

342902188045

**Result****✗ Failed**

- Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
- Advice** Rear Body component slightly loose Lower bumper panel (6.2.1 (a) (i))
- Advice** Rear Coil spring corroded Both springs (5.3.1 (b) (i))
- Advice** Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Undertray likely to become detached Under Tray & wheel arch liner (6.2.1 (a) (ii))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Body component slightly loose Bumper (6.2.1 (a) (i))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced Various parts of under body (6.1.1 (c) (i))
- Advice** Nearside Front Road wheel slightly distorted Inner bead (5.2.2 (c) (i))
- Advice** Offside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #13**

2021-06-17 11:05

**MOT test number**

840584649749

**Result**

✓ Passed

- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner shoulder badly worn (5.2.3 (e))
- Advice** Front Suspension arm corroded but not seriously weakened Both NS & OS (5.3.3 (b) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
- Advice** Exhaust system corroded but secure
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice** Rear Suspension spring mounting prescribed area is corroded but not considered excessive Both NS & OS (5.3.6 (a) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive all (5.3.6 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

**MOT #12**

2020-07-14 10:12

**MOT test number**

408184553972

**Result**

✓ Passed

- Advice** Front Suspension arm corroded but not seriously weakened Both NS & OS (5.3.3 (b) (i))
- Minor** Nearside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced Both NS & OS (5.3.3 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice** Front Subframe mounting prescribed area is corroded but not considered excessive Both NS & OS (5.3.6 (a) (i))
- Minor** Offside Front Brake hose slightly chafed (1.1.12 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened all NS , OS , upper & lower (5.3.3 (b) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Rear Coil spring corroded Both NS & OS (5.3.1 (b) (i))



MOT #11

2019-07-23 11:30

MOT test number

560102257921

Result

✓ Passed

- Minor

Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice

Offside Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Towball/hitch not fitted at time of test
- Advice

Towbar slightly damaged within 30cm of towbar mounting (6.1.6 (i) (i))
- Advice

Nearside Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

**MOT #10**

2019-07-22 15:34

**MOT test number**

419421305377

**Result****✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Pass with rectification** Nearside Headlamp aim too high and too far to the right. (4.1.2 (a))
- Advice** Towbar slightly damaged within 30cm of towbar mounting (6.1.6 (i) (i))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Nearside Rear Suspension arm attachment bracket/mounting corroded but its strength is not seriously reduced (5.3.3 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

**MOT #9**

2018-07-12 16:21

**MOT test number**

452654381925

**Result****✓ Passed****MOT #8**

2017-09-14 09:09

**MOT test number**

560188231783

**Result****✓ Passed**

- Advice** Offside Front tyre worn badly inner edge



**MOT #7** 2016-10-04 10:16**MOT test number** 707093705910**Result** ✓ Passed**Advice** Engine covers and undertrays fitted obscuring some components at time of the test**MOT #6** 2015-10-02 09:51**MOT test number** 129233805391**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Tow ball not fitted at time of test.**Advice** Engine covers and undertrays fitted obscuring some components**MOT #5** 2014-09-30 10:02**MOT test number** 547723774242**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #4** 2014-09-30 10:02**MOT test number** 347093474430**Result** ✗ Failed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #3** 2013-09-30 10:55**MOT test number** 815523573201**Result** ✓ Passed**Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2012-09-28 12:18**MOT test number** 329972872221**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-09-20 14:37**MOT test number** 736923861247**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	DE58FCX
Plate since	2019-09-28
Current registration	DE58FCX
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-10-13
Last registration	2022-07-19
Complete history	<a href="#">See info</a>



Registration #1	2008-10-13	13 mi
Registration #2	2011-09-20	30.014 mi
Registration #3	2012-09-28	43.165 mi
Registration #4	2013-09-30	58.220 mi
Registration #5	2014-09-30	70.981 mi
Registration #6	2015-10-02	85.289 mi
Registration #7	2016-10-04	99.025 mi
Registration #8	2017-09-14	111.301 mi
Registration #9	2018-09-20	125.277 mi
Registration #10	2019-09-20	139.253 mi
Registration #11	2020-09-20	153.229 mi
Registration #12	2021-09-20	167.205 mi
Registration #13	2022-09-20	181.181 mi
Registration #14	2023-09-20	195.157 mi
Registration #15	2024-09-20	209.133 mi
Registration #16	2025-09-20	223.109 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	080212203227BG