



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	LAND CRUISER D-4D LC3 8 SEATS
Colour	Silver
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	164 BHP
Max. torque	410 Nm at 2.000 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.4 mpg
CO2 emission	243 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-07-14
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-28
MOT pass rate	63 %
MOT passed	15
Failed MOT tests	9
Total advice items	100
Total items failed	20

MOT #242023-11-29 17:50

MOT test number242319635056

Result✓ Passed

Next expiry date2024-11-28

- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush worn (5.3.4 (a) (i))
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))
- Minor

Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #23**

2023-11-29 17:50

**MOT test number**

561939563212

**Result**

✗ Failed

**Pass with rectification**

Nearside Rear Lower Anti-roll bar insecurely attached bracket broke away (5.3.3 (a) (i))

**Minor**

Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**Pass with rectification**

Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**Advice**

Nearside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice**

Front Brake pipe corroded, covered in grease or other material both sides (1.1.11 (c))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush worn (5.3.4 (a) (i))

**Pass with rectification**

Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**Advice**

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #22**

2022-06-03 10:38

**MOT test number**

251771454895

**Result**

✓ Passed

**Advice**

Nearside front lower suspension arm bush slightly worn

**Advice**

Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))

**Advice**

Underside of vehicle undersealed

**MOT #21**

2021-07-28 13:58

**MOT test number**

124177935427

**Result**

✓ Passed

**MOT #20**

2020-07-30 08:12

**MOT test number**

530442280752

**Result**

✓ Passed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Inner Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Sills both sides (6.2.2 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Wiper linkage deteriorated
- Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Integral body structure is corroded but structural rigidity is not significantly reduced Floorpan (6.1.1 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** All service brakes only just met requirements

**MOT #19**

2019-08-08 10:28

**MOT test number**

831634546024

**Result**

✓ Passed

- Advice** Fuel Pipe/s corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #18** 2019-08-07 09:34**MOT test number** 561514182744**Result** ✗ Failed

- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear fog lamp not working (4.5.1 (a) (ii))
- MAJOR** Offside Rear Upper Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced CHASSIS LEG (6.1.1 (c) (i))
- Minor** Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Fuel Pipe/s corroded
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- MAJOR** Nearside Rear Body mounting fixings insecure BODY MOUNTING CORRODED (6.2.2 (c) (i))

**MOT #17** 2018-08-06 14:37**MOT test number** 855145222051**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

**MOT #16**

2018-08-06 09:45

**MOT test number**

583052618006

**Result****✗ Failed**

- MAJOR** Front Anti-roll bar pin or bush excessively worn BOTH (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2017-08-07 14:08

**MOT test number**

166080239593

**Result****✓ Passed**

- Advice** Offside Front tyre worn on inner edge
- Advice** Plastic sill covers fitted
- Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement Both front 'D' mounting bushes (2.4.G.2)
- Advice** Nearside Front tyre worn on outer edge
- Advice** Nearside Front Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)
- Advice** Vehicle rear under side corroded
- Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front suspension arms inner rear bushes (2.4.G.2)

**MOT #14**

2017-07-31 14:17

**MOT test number**

816386085009

**Result****✗ Failed****Advice** Brake disc worn, pitted or scored, but not seriously weakened FRONTS - inner surfaces (3.5.1i)**Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement Both front 'D' mounting bushes (2.4.G.2)**Advice** Offside Front tyre worn on inner edge**Advice** Nearside Front Front suspension has slight play in a upper suspension ball joint (2.5.B.1a)**Fail** Brake pad(s) less than 1.5 mm thick REARS (3.5.1g)**Advice** Nearside Rear Lower lamp damaged**Fail** Nearside Front Inner Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Brake pipe slightly corroded Vehicles metal brake pipes before flexible hose connections (3.6.B.2c)**Advice** Suspension arm rubber bush deteriorated but not resulting in excessive movement Both front suspension arms inner rear bushes (2.4.G.2)**Advice** Nearside Front tyre worn on outer edge**Fail** Brake pad(s) less than 1.5 mm thick FRONTS (3.5.1g)**Advice** Vehicle rear under side corroded**Fail** Windscreen wiper does not clear the windscreen effectively Both front (8.2.2)**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover insecure so that it no longer prevents the ingress of dirt and slight play in balljoint (2.4.G.2)**Advice** Plastic sill covers fitted



**MOT #13**

2016-07-13 13:25

**MOT test number**

832420602465

**Result**

✓ Passed

- Advice** Registration plate deteriorated but not likely to be misread both (6.3.1d)
- Advice** Rear pads not visible
- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Under car corroded
- Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement both d bushes have very slight play (2.4.G.2)

**MOT #12**

2015-08-04 10:44

**MOT test number**

508226715242

**Result**

✓ Passed

- Notice** Underside of car corroded
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Lower Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Lower Brake pipe slightly corroded (3.6.B.2c)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Nearside Front Upper Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Upper Brake pipe slightly corroded (3.6.B.2c)

**MOT #11**

2015-08-04 10:44

**MOT test number**

715396415227

**Result****✗ Failed**

- Advice** Nearside Front Lower Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Lower Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice** Underside of car corroded
- Advice** Nearside Front Upper Brake pipe slightly corroded (3.6.B.2c)
- Advice** Offside Front Upper Brake pipe slightly corroded (3.6.B.2c)
- Pass with rectification** Rear fog lamp not working (1.3.2b)
- Pass with rectification** All position lamps not working (1.1.A.3b)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #10**

2014-07-28 14:04

**MOT test number**

318149004211

**Result****✓ Passed**

- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #9** 2014-07-28 11:25**MOT test number** 608869604290**Result** ✗ Failed**Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2013-07-26 16:51**MOT test number** 279407603208**Result** ✓ Passed**Notice** All three wipers smearing**MOT #7** 2013-07-17 11:25**MOT test number** 777178093184**Result** ✗ Failed**Notice** All three wipers smearing**Fail** Nearside Upper Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #6** 2012-08-04 10:38**MOT test number** 626207312221**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2012-08-03 16:17**MOT test number** 295576712222**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2011-08-05 16:16**MOT test number** 435557611241**Result** ✓ Passed**Notice** Offside front tyre worn heavily inner egde**MOT #3** 2010-08-19 15:36**MOT test number** 334111730401**Result** ✓ Passed**Notice** Front brake discs corroded



MOT #2 2009-09-11 08:51

MOT test number 290644259201

Result ✓ Passed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Brake pad(s) wearing thin (3.5.1g)

**Advice** Front brake disc slightly scored (3.5.1h)

MOT #1 2009-09-10 11:17

MOT test number 964393659248

Result ✗ Failed

**Advice** Brake pad(s) wearing thin (3.5.1g)

**Fail** Nearside Rear fog lamp excessively deteriorated so that it is not visible from a reasonable distance (1.3.2d)

**Advice** Front brake disc slightly scored (3.5.1h)

**Fail** Nearside Rear fog lamp does not emit a steady red light (1.3.2e)

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

X

Untaxed

Tax expired:  
31 December 2023

✓

MOT

Expires:  
28 November 2024

Tax status	Expired at 31 December 2023
Days left	120 days too late
MOT expiry date	28 November 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>WJ56XHU</b>
Plate since	2019-09-28
Current registration	<b>WJ56XHU</b>
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-09-13
Last registration	2023-11-29
Complete history	<a href="#">See info</a>



Registration #1	2006-09-13	18 mi
Registration #2	2009-09-10	31.430 mi
Registration #3	2009-09-11	31.430 mi
Registration #4	2010-08-19	41.991 mi
Registration #5	2011-08-05	53.029 mi
Registration #6	2012-08-03	63.472 mi
Registration #7	2012-08-04	63.472 mi
Registration #8	2013-07-17	73.506 mi
Registration #9	2013-07-26	73.761 mi
Registration #10	2014-07-28	86.989 mi
Registration #11	2014-07-28	86.989 mi
Registration #12	2015-08-04	98.125 mi
Registration #13	2016-07-13	108.425 mi
Registration #14	2016-07-13	108.425 mi
Registration #15	2016-07-13	108.425 mi
Registration #16	2016-07-13	108.425 mi
Registration #17	2016-07-13	108.425 mi
Registration #18	2016-07-13	108.425 mi
Registration #19	2016-07-13	108.425 mi
Registration #20	2016-07-13	108.425 mi
Registration #21	2016-07-13	108.425 mi
Registration #22	2016-07-13	108.425 mi
Registration #23	2016-07-13	108.425 mi
Registration #24	2016-07-13	108.425 mi
Registration #25	2016-07-13	108.425 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1875 mm
Height	1905 mm
Length	4850 mm
Wheel base	2790 mm
Kerb weight	2190 kg
Max. allowed weight	2850 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	8

<b>Number of axles</b>	2
<b>Engine number</b>	1KD1422973