



report date: 2024-03-29

General information

Make	JAGUAR
Model	S-TYPE SE V6
Colour	Blue
Year of manufacture	-
Top speed	141 mph
0 - 60 mph	6.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	300 Nm at 4.500 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	17.0 mpg
Consumption extra urban	31.0 mpg
Consumption combined	23.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-06
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT #19	2021-11-25 10:47
MOT test number	466507747446
Result	✓ Passed
Next expiry date	2022-11-24

MOT #18	2021-04-15 14:43
MOT test number	851612653841
Result	✓ Passed

MOT #17	2021-04-12 14:01
MOT test number	610178414961
Result	✗ Failed

- Fail

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice

Handbrake has no reserv travel
- Fail

Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #16**

2021-01-19 14:00

MOT test number

529287667093

Result

✗ Failed

- Fail** Nearside Windscreen washer not working (3.5 (a))
- Fail** Offside Rear Suspension arm pin or bush excessively worn ROSE BUSH (5.3.4 (a) (i))
- Advice** Brake pipe corroded, covered in grease or other material front to rears (1.1.11 (c))
- Advice** Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt TIE ARM DUST COVERS (5.3.4 (b) (ii))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn ROSE BUSH (5.3.4 (a) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Advice** N/s rear outer Tyre wall deteriorated
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Suspension arm ball joint dust cover no longer prevents the ingress of dirt TIE ARM DUST COVERS (5.3.4 (b) (ii))
- Fail** Nearside Rear Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #15

2019-07-04 09:01

MOT test number

502463430324

Result

✓ Passed

- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #14** 2018-05-19 08:04**MOT test number** 444628149662**Result** ✓ Passed**MOT #13** 2018-04-27 14:40**MOT test number** 939849360247**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (1.3.2b)**Advice** Nearside washer jet poor**Advice** Rear all rose joint boots perished**Fail** Electronic stability system warning lamp indicates a fault (3.4.1c)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear slight binding on brake**MOT #12** 2017-01-17 10:54**MOT test number** 445959293822**Result** ✓ Passed**MOT #11** 2016-01-06 13:08**MOT test number** 649449417651**Result** ✓ Passed**MOT #10** 2015-01-12 10:58**MOT test number** 705072215067**Result** ✓ Passed**MOT #9** 2013-12-11 13:26**MOT test number** 929145743310**Result** ✓ Passed

**MOT #8** 2013-02-27 13:36**MOT test number** 997298753029**Result** ✓ Passed

Advice Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #7 2012-02-21 14:32**MOT test number** 168212152404**Result** ✓ Passed**MOT #6** 2011-02-28 11:38**MOT test number** 586789651047**Result** ✓ Passed**MOT #5** 2010-02-25 11:17**MOT test number** 874216550046**Result** ✓ Passed**MOT #4** 2009-02-21 10:02**MOT test number** 473062159016**Result** ✓ Passed**MOT #3** 2008-02-27 10:01**MOT test number** 123148758092**Result** ✓ Passed**MOT #2** 2007-02-26 11:54**MOT test number** 760837657090**Result** ✓ Passed



MOT #1	2005-12-29 10:00
MOT test number	420873365448
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	Y567CGN
Plate since	2024-03-29
Current registration	Y567CGN
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2001-04-06
Last registration	2021-11-25
Complete history	See info



Registration #1	2001-04-06	13 mi
Registration #2	2005-12-29	30.194 mi
Registration #3	2007-02-26	31.524 mi
Registration #4	2008-02-27	32.546 mi
Registration #5	2009-02-21	33.583 mi
Registration #6	2010-02-25	34.486 mi
Registration #7	2011-02-28	35.273 mi
Registration #8	2012-02-21	35.740 mi
Registration #9	2013-02-27	36.715 mi
Registration #10	2013-12-11	36.811 mi
Registration #11	2015-01-12	39.983 mi
Registration #12	2015-01-12	39.983 mi
Registration #13	2015-01-12	39.983 mi
Registration #14	2015-01-12	39.983 mi
Registration #15	2015-01-12	39.983 mi
Registration #16	2015-01-12	39.983 mi
Registration #17	2015-01-12	39.983 mi
Registration #18	2015-01-12	39.983 mi
Registration #19	2015-01-12	39.983 mi
Registration #20	2015-01-12	39.983 mi
Registration #21	2015-01-12	39.983 mi

More info >



Dimensions & weight

Width	1819 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1630 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	115854363FB