



CP53YDW

report date: 2024-03-28

General information

Make	SUZUKI
Model	LIANA GLX SE
Colour	Green
Year of manufacture	2004
Top speed	109 mph
0 - 60 mph	11.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	144 Nm at 4.000 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	40.9 mpg
CO2 emission	169 g/km
CO2 label	H





MOT history

MOT expiry date	2020-12-27
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	134
Total items failed	13

MOT #19 2019-06-28 08:46

MOT test number 366052761619

Result ✓ Passed

Next expiry date 2020-12-27

Advice Brake pipe corroded, covered in grease or other material all pipes around fuel tank (1.1.11 (c))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Seat belt anchorage prescribed area is corroded but not considered excessive both inner sills (7.1.1 (a) (i))

MOT #18 2019-06-27 16:00

MOT test number 791110730067

Result ✗ Failed

Advice Brake pipe corroded, covered in grease or other material all pipes around fuel tank (1.1.11 (c))

Advice Seat belt anchorage prescribed area is corroded but not considered excessive both inner sills (7.1.1 (a) (i))

Fail Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #17** 2018-06-13 10:16**MOT test number** 929994679341**Result** ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Brake pipe corroded, covered in grease or other material around fuel tank (1.1.11 (c))

MOT #16 2017-07-27 11:24**MOT test number** 949811427795**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Ball joint has slight play (2.2.B.1f)



MOT #15

2016-07-29 10:44

MOT test number

702962747213

Result

✓ Passed

- Advice** Brake pipe slightly corroded rear metal brake pipe on load valve (3.6.B.2c)
- Advice** Rear chassis and bootfloor corroded
- Advice** Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt n/s o/s (2.5.C.1a)
- Advice** Offside Rear Tyre worn close to the legal limit wearing inner edge close to canvas and heavily perishing (4.1.E.1)
- Advice** Rear back box deteriorating
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** N/s/f tyre perishing and has glass
- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** N/s o/s inner sills corroded
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** All steering and suspension components corroded
- Advice** Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement n/s o/s (2.4.G.2)
- Advice** Front subframe corroded
- Advice** Brake hose has slight corrosion to ferrules all (3.6.B.4e)
- Advice** Rear subframe heavily corroded

**MOT #14**

2016-07-22 11:16

MOT test number

749317574979

Result**✗ Failed**

- Advice** Rear subframe heavily corroded
- Advice** Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt n/s o/s (2.5.C.1a)
- Fail** Windscreen wiper does not clear the windscreen effectively n/s o/s (8.2.2)
- Advice** Rear chassis and bootfloor corroded
- Advice** Offside Rear Tyre worn close to the legal limit wearing inner edge close to canvas and heavily perishing (4.1.E.1)
- Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear back box deteriorating
- Advice** Brake pipe slightly corroded front to rear (3.6.B.2c)
- Advice** N/s/f tyre perishing and has glass
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** N/s o/s inner sills corroded
- Advice** Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement n/s o/s (2.4.G.2)
- Fail** Front registration plate deteriorated (6.3.1d)
- Advice** All steering and suspension components corroded
- Fail** Bonnet cannot be secured in the closed position (8.4.1)
- Advice** Brake hose has slight corrosion to ferrules all (3.6.B.4e)
- Advice** Front subframe corroded
- Advice** Brake pipe slightly corroded rear metal brake pipe on load valve (3.6.B.2c)



MOT #13

2015-07-07 10:43

MOT test number

177738085181

Result

✓ Passed

- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

All steering and suspension components corroded
- Advice

Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice

Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice

N/s/r tyre perishing
- Advice

Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)



MOT #12

2015-07-07 10:43

MOT test number

207088785441

Result

✗ Failed

- Advice

Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice

All steering and suspension components corroded
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Rear Subframe mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification

Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

N/s/r tyre perishing
- Advice

Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice

Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #112014-03-27 14:46

MOT test number629466984000

Result

✓ Passed

- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice

Rear underside of vehicle has corrosion
- Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice

Offside Rear Seat belt damaged but webbing not significantly weakened (5.2.2a)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Notice

All steering and suspension components corroded
- Advice

Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice

Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #10**

2013-03-28 12:04

MOT test number

916157583087

Result

✓ Passed

- Notice** Exhaust is deteriorated
- Advice** Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** Front cross member is corroded and engine crossmember is corroded
- Advice** Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** All steering and suspension components are corroded
- Advice** Sub-frame corroded but not seriously weakened (2.4.G.1)
- Notice** Fuel pipes are corroded
- Advice** Coil spring corroded (2.4.C.1b)
- Advice** Registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Brake pipe slightly corroded (3.6.B.2c)
- Notice** N/s wiper is split
- Advice** Brake servo corroded but not excessively weakened (3.6.A.2b)



MOT #9

2013-03-27 15:42

MOT test number

339576883075

Result

✗ Failed

- Advice

Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Advice

Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice

Frunt cross member is corroded and engine crossmember is corroded
- Advice

Sub-frame corroded but not seriously weakened (2.4.G.1)
- Notice

All steering and suspension components a corroded
- Fail

Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice

Coil spring corroded (2.4.C.1b)
- Notice

Feul pipes a corroded
- Advice

Registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Rear Suspension component mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice

Brake pipe slightly corroded (3.6.B.2c)
- Advice

Brake servo corroded but not excessively weakened (3.6.A.2b)
- Notice

N/s wipper is split
- Advice

Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Exhaust is deteriated
- Fail

Brakes imbalanced across an axle (3.7.B.5b)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8**

2012-03-27 12:04

MOT test number

828917982057

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** All rear suspension components has corrosion
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Slight corrosion on front suspension
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)
- Notice** Corrosion on rear exhaust
- Notice** Oil leak

MOT #7

2010-10-01 15:44

MOT test number

524154970241

Result

✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Rear Vehicle structure has slight corrosion (6.1.B.2)



MOT #6

2009-09-17 11:04

MOT test number

582280769209

Result

✓ Passed

- Advice

Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice

Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)
- Advice

Rear Suspension arm corroded but not seriously weakened (2.4.G.1)
- Advice

Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice

Front coil spring corroded (2.4.C.1b)
- Notice

N/s o/s rear chasis rail corroded
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2009-09-09 17:14**MOT test number** 541742159219**Result** ✗ Failed**Advice** Front Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Rear Suspension arm corroded but not seriously weakened (2.4.G.1)**Notice** N/s o/s rear chasis rail corroded**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Front coil spring corroded (2.4.C.1b)**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Registration plate lamp not working (1.1.5c)**MOT #4** 2008-09-05 14:57**MOT test number** 640149648208**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.5c)



MOT #3	2008-09-05 14:57
MOT test number	811909648295
Result	✓ Passed
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #2	2007-08-30 16:24
MOT test number	250722847205
Result	✓ Passed

MOT #1	2007-01-24 11:23
MOT test number	304394127007
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2004-01-26
Last registration	2019-06-28
Complete history	See info



Registration #1	2004-01-26	28 mi
Registration #2	2007-01-24	18.227 mi
Registration #3	2007-08-30	31.100 mi
Registration #4	2008-09-05	39.416 mi
Registration #5	2009-09-09	50.009 mi
Registration #6	2009-09-17	50.014 mi
Registration #7	2010-10-01	60.583 mi
Registration #8	2012-03-27	74.476 mi
Registration #9	2013-03-27	79.927 mi
Registration #10	2019-06-28	85.377 mi
Registration #11	2019-06-28	85.377 mi
Registration #12	2019-06-28	85.377 mi
Registration #13	2019-06-28	85.377 mi
Registration #14	2019-06-28	85.377 mi
Registration #15	2019-06-28	85.377 mi
Registration #16	2019-06-28	85.377 mi
Registration #17	2019-06-28	85.377 mi
Registration #18	2019-06-28	85.377 mi

More info >



Dimensions & weight

Width	1720 mm
Height	1550 mm
Length	4230 mm
Wheel base	2480 mm

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	M16A-1043661