





report date: 2024-03-28

General information

Make	NISSAN
Model	ALMERA S
Colour	Silver
Year of manufacture	-
Top speed	108 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	128 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.8 mpg



CarCheck.co.uk page 1/16



report date: 2024-03-28

Internet history

Entry 1

Date 2022-02-05

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

MOT history

MOT #27 2022-01-28 12:33

MOT test number 871153717695

Result \rightarrow Passed

Next expiry date 2023-02-13

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #26 2021-02-05 15:01

MOT test number 392572559661

Result \rightarrow Passed

Advice

(b) (ii))

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #25 2021-02-05 15:01

MOT test number 546003025894

Result X Failed

Pass with rectification

Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (3.4

MOT #24 2020-02-12 15:09

MOT test number 653449775024

Advice Power steering component has slight seepage from a component (2.1.5 (a))

MOT #23 2020-02-10 12:13

MOT test number 503289259337

Result X Failed

CarCheck.co.uk page 3/16



Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice

Power steering component has slight seepage from a component (2.1.5 (a))



report date: 2024-03-28

X Failed

MOT #22 2019-02-12 16:56

MOT test number 368786731708

Result ✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #21 2019-02-12 16:56

MOT test number 284649788644

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Pass with rectification Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

MOT #20 2018-02-06 12:51

MOT test number 620195735978

Result ✓ Passed

Advice Nearside Rear Outer Tyre worn close to the legal limit edge (4.1.E.1)

Advice Offside Headlamp has a product on the lens but not seriously reducing light output condensation


(1.7.5a)

Result

CarCheck.co.uk page 4/16



report date: 2024-03-28




MOT #18		2017-02-14 14:58
MOT test	number	601827902674
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Wiper blade splitting	
Advice	Offside Front Tyre worn close to the legal limit edges (4.1.E.1)	

CarCheck.co.uk page 5/16



report date: 2024-03-28



MOT #16	201	6-02-12 16:11
MOT test	number 6	70654667704
Result		✓ Passed
Advice (2.2.C.1c)	Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of	of dirt
Advice	Oil leak	
Advice	Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Play in steering rack inner joints	
Advice	Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of	dirt
(2.2.C.1c)		
Advice	Power steering component(s) has slight seepage from a component rack (2.3.3b)	

CarCheck.co.uk page 6/16



report date: 2024-03-28

MOT #15 2016-02-12 10:40 **MOT** test number 402133592670 Result × Failed **Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d) Advice Oil leak Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c) **Advice** Power steering component(s) has slight seepage from a component rack (2.3.3b) Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2) Play in steering rack inner joints **Advice** Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b) Advice Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c) **Advice** Power steering pipe(s) or hose(s) has slight seepage from a joint (2.3.3b) Fail Power steering fluid level below minimum (2.3.1)

MOT #14		2015-01-29 15:19
MOT test	number	618729425019
Result		✓ Passed
MOT #13		2014-02-05 12:08
MOT test	number	265936234099
Result		✓ Passed
Notice	Gearbox mounting showing deterioration	
Advice	Power steering component(s) has slight seepage from a component (2.3.3b)	
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)	
Advice	Power steering component(s) has slight seepage from a component (2.3.3b)	

CarCheck.co.uk page 7/16



report date: 2024-03-28

× Failed

MOT #12 2014-02-01 13:11 896712634008 **MOT** test number Result × Failed Fail Front registration plate insecure (6.3.1b) **Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d) **Advice** Power steering component(s) has slight seepage from a component (2.3.3b) Notice Gearbox mounting showing deterioration Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b) **Advice** Power steering component(s) has slight seepage from a component (2.3.3b)

MOT #11

MOT test number

206458703074

Result

✓ Passed

MOT #10

2013-01-08 13:05

MOT test number

478188003070

Result × Failed

Fail Nearside Front Mechanical brake component has restricted free movement (3.5.1k)

Fail Offside Front Mechanical brake component has restricted free movement (3.5.1k)

MOT #9 2012-01-09 11:15
MOT test number 846769002060

Result ✓ Passed

MOT #8 2012-01-09 11:15

MOT test number 108829002079

Pass with rectification Nearside Stop lamp not working (1.2.1b)

Result

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #7

MOT test number

Result

Advice Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

MOT test number

Result

Fail Offside Front position lamp(s) obviously incorrectly positioned (1.1.A.3a)

Advice Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

Fail Nearside Front position lamp(s) obviously incorrectly positioned (1.1.A.3a)

 MOT #5
 2010-08-11 12:04

 MOT test number
 711343120251

 Result
 ✓ Passed

MOT #4 2009-08-26 12:13

MOT test number 674188439251

Result ✓ Passed

Result ✓ Passed

MOT #3 2008-08-22 10:30

MOT test number 590925038210

Result Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 9/16



report date: 2024-03-28

MOT #2	2007-08-31 11:08
MOT test number	884273547255
Result	✓ Passed
MOT #1	2006-08-31 16:17
MOT test number	612393746267
Result	✓ Passed

CarCheck.co.uk page 10/16



report date: 2024-03-28

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



Owner history

GU53SUF

report date: 2024-03-28

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this NISSAN had different number plates.

More info >

More info >

CarCheck.co.uk page 13/16



GU53SUF report date: 2024-03-28

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 14/16



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2003-09-01
Last registration	2022-01-28
Complete history	See info



Registration #1	2003-09-01	24 mi
Registration #2	2006-08-31	20.917 mi
Registration #3	2007-08-31	24.884 mi
Registration #4	2008-08-22	29.467 mi
Registration #5	2009-08-26	33.760 mi
Registration #6	2010-08-11	38.097 mi
Registration #7	2011-01-17	39.060 mi
Registration #8	2011-01-17	39.060 mi
Registration #9	2012-01-09	43.194 mi
Registration #10	2013-01-08	46.619 mi
Registration #11	2013-01-08	46.619 mi
Registration #12	2014-02-01	51.133 mi
Registration #13	2014-02-05	51.133 mi
Registration #14	2015-01-29	55.123 mi
Registration #15		11.177 es
Registration #16		71.777 es
Registration #17		11.177 es
Registration #18		71.777 es
Registration #19		71.777 66
Registration #20		77,777 46
Registration #21		11.177 es
Registration #22		77,777 46
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		71.777 66
CarCheck.co.uk		page 15/16

Registration #27

Registration #28

More info >

mn.n.n



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1706 mm
Height	1448 mm
Length	4184 mm
Wheel base	2535 mm
Kerb weight	1170 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number Carcheck.co.uk	197826 page 16/16