





General information

Make	ΤΟΥΟΤΑ
Model	CELICA VVTI BLUE
Colour	Blue
Year of manufacture	2005
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	172 Nm at 4.200 rpm
Engine capacity	1.794 сс
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry	1
Date	


Pictures

2021-06-17

8

Listing price

View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-10
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	30
Total items failed	16

MOT #22	2024-01-03 11:07
MOT test number	
Result	Passed
Next expiry date	2025-01-10
Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))	

MOT #21		2024-01-03 10:17
MOT test n	umber	837548449518
Result		🗙 Failed
Minor N	learside Windscreen wiper blade defective (3.4 (b) (i))	
Fail From	nt Position lamp not working both (4.2.1 (a) (ii))	
Fail Reg	gistration plate lamp inoperative in the case of a single lamp or all lamps	both (4.7.1 (b) (ii))

MOT #20	2023-01-03 15:57
MOT test number	608763923527
Result	✓ Passed
MOT #19	2022-01-05 11:53
MOT test number	702929489693
Result	✓ Passed
Minor Offside Registration plate lamp inoperative in the case of multiple lam (i))	ps or light sources (4.7.1 (b)

CarCheck.co.uk





MOT #18	2022-01-05 11:53
MOT test number	735449611523
Result	🗙 Failed
Minor Offside Registration plate lamp inoperative in the case of multiple la (i))	amps or light sources (4.7.1 (b)
Pass with rectification Engine MIL inoperative or indicates a malfunction	n (8.2.2.2 (g))

MOT #17	2021-01-05 13:39
MOT test	number 255039922201
Result	✓ Passed
Advice (ii))	Nearside Rear Tyre slightly damaged/cracking or perishing BADLY CRACKED IN TREAD (5.2.3 (d)
Advice	Offside Rear Tyre slightly damaged/cracking or perishing BADLY CRACKED IN TREAD (5.2.3 (d) (ii))

MOT #16	2020-01-07 12:16
MOT test number	891190595012
Result	✓ Passed

MOT #15		2019-01-11 11:54
MOT test	number	173688395659
Result		✓ Passed
Advice	Rear axle / sub frame corroded	
Advice	Front both front suspension arms corroded	
Advice	Rear Brake pipe corroded, covered in grease or other material both sides (1.1.11 ((c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



FH05AFF
report date: 2024-03-29

MOT #14	2019-01-04 16:11
MOT test number	976132518370
Result	🗙 Failed
Fail Offside Front Brake pipe excessively corroded (1.1.11 (c))	
Advice Rear axle / sub frame corroded	
Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
Advice Front both front suspension arms corroded	
Advice Rear Brake pipe corroded, covered in grease or other material both sides (1.1.1	.1 (c))

MOT #13	2017-11-10 15:36
MOT test number	129983279903
Result	✓ Passed

MOT #12	2016-11-30 16:31
MOT test number	525935866560
Result	✓ Passed
Advice Parking brake lever has little reserve travel (3.1.6b)	

MOT #11	2015-06-04 08:58
MOT test number	445605755179
Result	✓ Passed

MOT #10	2014-06-13 10:30
MOT test number	249214464462
Result	✓ Passed





MOT #9		2013-05-22 16:47
MOT test	number	208572143167
Result		✓ Passed
Notice	Both rear exhaust backbox rubber mounts detereiorated but system still s	upported at time of test
MOT #8		2013-05-22 11:17
MOT test	number	825482443169
Result		🗙 Failed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Both rear exhaust backbox rubber mounts detereiorated but system still s	upported at time of test
Fail W	indscreen has damage to an area in excess of a 10mm circle within zone 'A	' (8.3.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice requires a	Service brake: service brake efficiency only just met. It would appear that djustment or repair. (3.7.B.7)	the braking system

MOT #7	2012-05-23 16:45
MOT test	number 769504542198
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Both rear exhaust mount rubbers deteriorated one split but still supports exhaust system



FH05AFF
report date: 2024-03-29

MOT #6		2012-05-23 11:46
MOT test	number	355544742186
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Offside rear brake binding slightly	
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Fail C	ffside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Notice	Both rear exhaust mount rubbers deteriorated one split but still supports exhaust	system
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1	La)
Notice	Rear disc brakes both sides corroded and pads aprox 75% worn	
Fail N	earside Windscreen wiper does not clear the windscreen effectively (8.2.2)	

MOT #5	2011-05-25 13:11
MOT test number	899965341112
Result	✓ Passed
MOT #4	2010-05-21 12:11

MOT test number	814831740165
Result	✓ Passed





MOT #3	3 2010-05-21 10:13
MOT te	est number 971491240159
Result	× Failed
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #2	2009-06-01 16:40
MOT test number	674382759191
Result	✓ Passed

MOT #1	2008-06-13 16:24
MOT test number	650525168132
Result	✓ Passed
Notice Both rear exhaust rubber mountings split but still secure	



Tax & MOT check

✓ Taxed	✓ MOT
Tax due: 1 June 2024	Expires: 10 January 2025
Tax status	Valid until 1 June
Days left	32
MOT expiry date	10 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



FH05AFF report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-06-15
Last registration	2024-01-03
Complete history	See info



Registration #1	2005-06-15	19 mi
Registration #2	2008-06-13	24.072 mi
Registration #3	2009-06-01	32.694 mi
Registration #4	2010-05-21	44.171 mi
Registration #5	2010-05-21	44.171 mi
Registration #6	2011-05-25	52.294 mi
Registration #7	2012-05-23	62.862 mi
Registration #8	2012-05-23	62.862 mi
Registration #9	2013-05-22	70.792 mi
Registration #10	2013-05-22	70.792 mi
Registration #11	2014-06-13	79.020 mi
Registration #12	2015-06-04	84.958 mi
Registration #13		11.777 esi
Registration #13 Registration #14		11.227 est
		01.000 est 01.000 est 01.000 est
Registration #14		01.000 est 01.000 est 01.000 est 01.000 est
Registration #14 Registration #15		01.000 est 0.000 est 01.000 est 01.000 est 01.000 est
Registration #14 Registration #15 Registration #16		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #14 Registration #15 Registration #16 Registration #17		01.007 46 0.007 46 0.007 46 0.007 46 0.007 46 0.007 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		0.202 es 0.222 es 0.222 es 0.222 es 0.222 es 0.222 es 0.222 es
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		0.200 est 0.200 est 0.200 est 0.200 est 0.200 est 0.200 est 0.200 est 0.200 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460 00.000 460
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		0.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46 0.202 46
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22		0.000 es 0.000 es 0.0000 es 0.000 es 0.0000 es 0.0000 es 0.000 es 0.0000 es 0.0000 es 0.0000 es 0.0000 es 0.000 es 0.000 es 0.000 es 0.000







Car features

S0225	Air conditioning
\$0295	
\$0482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1735 mm
Height	1315 mm
Length	4350 mm
Wheel base	2600 mm
Kerb weight	1145 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1ZZ2317949