





report date: 2024-03-29

General information

| Make | TOYOTA |
|---------------------|----------------------------|
| Model | HIACE 2.4D SWB GS 4DRTGP/V |
| Colour | Turquoise |
| Year of manufacture | 2000 |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Engine capacity | 2.446 cc |
|-----------------|----------|
| Cylinders | 4 |
| Fuel type | Diesel |



CarCheck.co.uk page 1/17



report date: 2024-03-29

Internet history

Entry 1

Date 2021-11-05

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/17



report date: 2024-03-29

MOT history

| MOT expiry date | 2022-10-20 |
|--------------------|------------|
| MOT pass rate | 59 % |
| MOT passed | 16 |
| Failed MOT tests | 11 |
| Total advice items | 63 |
| Total items failed | 29 |

| MOT #27 | | 2021-10-21 15:12 |
|-----------|---|------------------|
| MOT test | number | 106987718784 |
| Result | | ✓ Passed |
| Next expi | ry date | 2022-10-20 |
| Advice | Brake pipe corroded, covered in grease or other material all greased (1.1.11 (c)) | |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) | |

| MOT #26 | 2021-10-05 15:18 | |
|---|------------------|--|
| MOT test number | 614190757008 | |
| Result | X Failed | |
| Fail Offside Front Brake pipe excessively corroded (1.1.11 (c)) | | |
| Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Fail Nearside Front Upper Suspension component ball joint excessively worn (5.3.4 (| a) (i)) | |
| Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i)) | | |
| Fail Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner/outer sill (5.3.6 (a) (i)) | | |
| Advice Brake pipe corroded, covered in grease or other material all pipes (1.1.11 (c) |) | |
| Fail Offside Front Upper Suspension component ball joint excessively worn (5.3.4 (a) | (i)) | |

CarCheck.co.uk page 3/17



report date: 2024-03-29

MOT #25 2021-09-10 10:07

MOT test number 991972918856

Result X Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing heavily cracking in tread (5.2.3 (d) (ii))

Advice Nearside Front jacking point holed and heavily corroded

Advice Underbody age related corrosion

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Advice Offside Rear wheel arch corroded

Fail Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired inner sill (6.2.2 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing heavily cracking in tread and sidewall (5.2.3 (d) (ii))

Advice Offside Front jacking point holed and heavily corroded

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

Fail Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Nearside Front Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired inner sill (6.2.2 (d) (ii))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #24 2020-09-03 14:22

MOT test number 867185879735

Advice Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #23 2020-09-03 10:48 **MOT test number** 151337030236 Result × Failed **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) Fail

| MOT #22 | | 2019-08-28 10:17 |
|----------------------------|---|-----------------------------|
| MOT test | number | 466508671045 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing cracking and | l perished (5.2.3 (d) (ii)) |
| Advice | Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) |) |
| Advice (a) (i)) | Offside Front Anti-roll bar linkage pin or bush worn but not resulting in ex | xcessive movement (5.3.4 |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing cracking and p | perished (5.2.3 (d) (ii)) |
| Advice (5.3.4 (a) (| Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in (i)) | excessive movement |

CarCheck.co.uk page 5/17



report date: 2024-03-29

MOT #21 2019-08-28 10:17 **MOT** test number 819015499790 Result **X** Failed **Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Pass with rectification Offside Front Direction indicator not working (4.4.1 (a) (ii)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking and perished (5.2.3 (d) (ii)) **Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Pass with rectification Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing cracking and perished (5.2.3 (d) (ii)) **Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #20

MOT test number

489792381009

Result

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))

| MOT #19 | 2018-09-03 08:04 | |
|--|--|--|
| MOT test number | 589913861336 | |
| Result | ★ Failed | |
| Advice Offside Front Ty | re slightly damaged/cracking or perishing (5.2.3 (d) (i)) | |
| Pass with rectification (ii)) | Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) | |
| Advice Oil leak, but not excessive (8.4.1 (a) (i)) | | |
| Advice Rear Registratio | n plate deteriorated but not likely to be misread (0.1 (b)) | |

CarCheck.co.uk page 6/17



report date: 2024-03-29

MOT test number

Result

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Brake pipe slightly corroded (3.6.B.2c)

Advice Oil leak

 MOT #17
 2016-09-07 09:31

 MOT test number
 876952192618

 Result
 ✓ Passed

MOT test number

Result

Advice Oil leaks


Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Rear washer not working

CarCheck.co.uk page 7/17



report date: 2024-03-29



| MOT #14 | | 2014-09-03 10:48 |
|----------|--|------------------|
| MOT test | number | 215346144208 |
| Result | | ✓ Passed |
| Advice | Suspension arm corroded but not seriously weakened (2.4.G.1) | |
| Notice | Rear wiper blade split | |
| Notice | Oil leak | |
| Advice | Rear registration plate deteriorated but not likely to be misread (6.3.1d) | |
| Advice | Coil spring corroded (2.4.C.1b) | |
| Notice | Spare tyre defective | |

CarCheck.co.uk page 8/17



MOT #10

V366FUF

report date: 2024-03-29

2011-08-30 13:50

MOT #13 2014-08-30 10:04 646642944283 **MOT** test number Result × Failed Fail Offside Seat belt anchorage prescribed area is fractured (5.2.6) Notice Rear wiper blade split **Advice** Suspension arm corroded but not seriously weakened (2.4.G.1) Notice Oil leak **Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d) Notice Spare tyre defective **Advice** Coil spring corroded (2.4.C.1b)

| MOT #12 | 2013-08-17 12:08 |
|-----------------|------------------|
| MOT test number | 466629923247 |
| Result | ✓ Passed |
| | |

| MOT #11 | 2012-08-21 14:06 |
|-----------------|------------------|
| MOT test number | 835384232295 |
| Result | ✓ Passed |

| MOT test number | 525362041288 |
|-----------------|--------------|
| Result | ✓ Passed |

| MOT #9 | | 2010-08-21 11:57 |
|--------|--|------------------|

MOT test number 571243930273

Result Passed

Advice Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 9/17



report date: 2024-03-29

MOT #8 2010-08-20 16:41 470572330256 **MOT** test number Result × Failed Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2) Fail Front registration plate deteriorated (6.3.1d) Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2) **Advice** Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #7

MOT test number

Result

Notice Front number plate slightly deteriorated

Pass with rectification Nearside Front position lamp(s) not working (1.1.A.3b)

MOT #6

MOT test number

673486249261

Result

Notice Front number plate slightly deteriorated

2009-09-03 09:29

673486249261

✓ Passed

 MOT #5
 2008-08-26 12:13

 MOT test number
 900989838264

 Result
 ✓ Passed

CarCheck.co.uk page 10/17



MOT #4

V366FUF report date: 2024-03-29

2007-08-14 16:16

MOT test number 213396627232

Result ★ Failed

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification Nearside Headlamp aim too high (1.8)

Pass with rectification Offside Headlamp aim too far to the left (1.8)

MOT #3 2007-08-14 16:16

MOT test number 770386727281

Result ✓ Passed

MOT #2 2006-08-10 09:48

MOT test number 884082326207

MOT #1 2006-08-10 09:48

MOT test number 940252226248

Result X Failed

Pass with rectification Offside Windscreen wiper blade deteriorated (8.2.2)

Pass with rectification Nearside Windscreen wiper blade deteriorated (8.2.2)

CarCheck.co.uk page 11/17



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

| e when miscory | | |
|--|---------------|----|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively. | | ТА |
| THE PARTY OF THE P | | |
| | | |
| *************************************** | | |
| ********* | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this TOYOTA had different number plates. | | |
| Number of plates | | , |
| Current registration | OK CONTRACTOR | |
| Plate since | | |
| Current registration | UK UK | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 14/17



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 15/17



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 26 |
| First mileage registration | 2000-02-04 |
| Last registration | 2021-10-21 |
| Complete history | See info |



| Registration #1 | 2000-02-04 | 25 mi |
|------------------|------------|-----------|
| Registration #2 | 2006-08-10 | 14.669 mi |
| Registration #3 | 2007-08-14 | 18.129 mi |
| Registration #4 | 2008-08-26 | 21.350 mi |
| Registration #5 | 2009-09-03 | 24.517 mi |
| Registration #6 | 2010-08-20 | 28.711 mi |
| Registration #7 | 2010-08-21 | 28.711 mi |
| Registration #8 | 2011-08-30 | 31.259 mi |
| Registration #9 | 2012-08-21 | 34.855 mi |
| Registration #10 | 2013-08-17 | 38.075 mi |
| Registration #11 | 2014-08-30 | 41.999 mi |
| Registration #12 | 2014-09-03 | 41.999 mi |
| Registration #13 | 2015-09-03 | 44.651 mi |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.777 es |
| Registration #19 | | 11.777 es |
| Registration #20 | | 11.777 es |
| Registration #21 | | 11.777 es |
| Registration #22 | | 11.777 es |
| Registration #23 | | 11.777 es |
| Registration #24 | | 11.777 es |
| Registration #25 | | 11.777 es |
| Registration #26 | | 71,777 es |

CarCheck.co.uk page 16/17



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Dimensions & weight

| Width | 1650 mm |
|---------------------|---------|
| Kerb weight | 1570 kg |
| Max. allowed weight | 2800 kg |

Additional information

| Number of axles | 2 |
|-----------------|-----------|
| Engine number | 2L5003764 |

CarCheck.co.uk page 17/17