



report date: 2024-03-28

General information

Make	CITROEN
Model	SAXO VTR
Colour	Grey
Year of manufacture	2003
Top speed	119 mph
0 - 60 mph	9.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	135 Nm at 3.500 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-07-05
Pictures	46
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-05
Pictures	46
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	47
Total items failed	8

MOT #21	2023-08-04 12:44
MOT test number	294244487367
Result	✓ Passed
Next expiry date	2024-08-03

MOT #20	2022-04-21 10:18
MOT test number	874606337369
Result	✓ Passed
Advice	Offside Rear Axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))
Advice	Nearside Rear Axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))

**MOT #19**

2022-04-19 11:11

**MOT test number**

489129979233

**Result****✗ Failed**

- MAJOR** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner arch x2 (6.2.2 (d) (i))
- Advice** Nearside Rear Axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))
- MAJOR** Nearside Rear Brake load sensing valve inoperative but ABS functioning (1.1.17 (c) (i))
- MAJOR** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Nearside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting inner arch under bonnet next to fuse box (6.2.2 (d) (i))
- Advice** Offside Rear Axle has slight vertical movement between stub axle and axle beam (5.1.2 (c) (i))
- MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- MAJOR** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #18**

2021-03-22 13:00

**MOT test number**

455750535416

**Result****✓ Passed****MOT #17**

2019-01-11 10:52

**MOT test number**

870370725838

**Result****✓ Passed**

- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #16**

2017-11-09 15:03

**MOT test number**

261953236874

**Result****✓ Passed**



MOT #15

2016-11-23 10:00

MOT test number

301600764928

Result

✓ Passed

- Advice

Exhaust has a minor leak of exhaust gases catalytic converter (7.1.2)
- Advice

Both rear tyres perished
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Nearside Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice

Front exhaust deteriorated/corroded
- Advice

Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #14

2016-11-22 11:38

MOT test number

932755225426

Result

✗ Failed

- Fail

Parking brake lever insecure (3.1.3b)
- Advice

Rear registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice

Nearside Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice

Front exhaust deteriorated/corroded
- Fail

Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice

Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice

Exhaust has a minor leak of exhaust gases catalytic converter (7.1.2)
- Advice

Both rear tyres perished

**MOT #13** 2015-11-24 13:12**MOT test number** 692747090550**Result** ✓ Passed

- Advice** Parking brake lever ratchet mechanism is slightly worn (3.1.5)
- Advice** FRONT EXHAUST SLIGHTLY CORRDOED/DETERIORATED
- Advice** Brake load sensing valve stiff (3.6.E.3)
- Advice** BOTH REAR TYRES PERISHED
- Advice** Nearside Front Outer Front constant velocity joint is slightly worn (2.5.C.1b)

**MOT #12** 2014-11-25 09:11**MOT test number** 325239924379**Result** ✓ Passed

- Advice** Nearside Outer Front constant velocity joint is slightly worn (2.5.C.1b)
- Advice** Brake load sensing valve stiff (3.6.E.3)

**MOT #11** 2014-11-21 15:26**MOT test number** 945595024311**Result** ✗ Failed

- Fail** Exhaust has a major leak of exhaust gases (7.1.2)
- Advice** Nearside Outer Front constant velocity joint is slightly worn (2.5.C.1b)
- Fail** Nearside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
- Fail** Parking brake lever, pawl mechanism pivots or their associated mountings are insecure (3.1.4b)
- Advice** Brake load sensing valve stiff (3.6.E.3)

**MOT #10** 2013-11-14 09:40**MOT test number** 256748413354**Result** ✓ Passed

- Notice** Recommend anti corrosion treatment of vehicle underside.
- Notice** Recommend timing belt renewal if not recently done.
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Offside and nearside front wheel arch liners insecure.
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Notice** Exhaust center pipe and box + tailpipe and box corroding,not blowing at present.
- Notice** Offside and nearside rear tyres perishing(aged) recommend renewal.
- Notice** Offside rear tyre wearing unevenly.recommend new.
- Advice** Offside Inner Rear Brake pad(s) wearing thin (3.5.1g)
- Notice** Bonnet stay securing clip broken,stay may touch battery terminals.

**MOT #9** 2012-11-22 11:33**MOT test number** 499027522408**Result** ✓ Passed**MOT #8** 2011-11-22 15:15**MOT test number** 937836921398**Result** ✓ Passed**MOT #7** 2011-11-21 15:17**MOT test number** 906505821345**Result** ✗ Failed

- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)

**MOT #6** 2010-11-12 16:21**MOT test number** 782916110379**Result** ✓ Passed**MOT #5** 2010-11-12 11:33**MOT test number** 170096810343**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2009-11-23 15:01**MOT test number** 982667429326**Result** ✓ Passed**MOT #3** 2008-11-20 17:17**MOT test number** 773725828388**Result** ✓ Passed**MOT #2** 2007-11-22 16:50**MOT test number** 491536427337**Result** ✓ Passed**MOT #1** 2006-11-24 12:24**MOT test number** 383508426373**Result** ✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
3 August 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	3 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-11-25
Last registration	2023-08-04
Complete history	<a href="#">See info</a>



Registration #1	2003-11-25	21 mi
Registration #2	2006-11-24	8.906 mi
Registration #3	2007-11-22	11.140 mi
Registration #4	2008-11-20	12.941 mi
Registration #5	2009-11-23	16.053 mi
Registration #6	2010-11-12	17.920 mi
Registration #7	2010-11-12	17.922 mi
Registration #8	2011-11-21	20.146 mi
Registration #9	2011-11-22	20.147 mi
Registration #10	2012-11-22	22.618 mi
Registration #11	2013-11-14	24.807 mi
Registration #12	2014-11-21	28.928 mi
Registration #13	2015-11-21	31.377 mi
Registration #14	2016-11-21	31.377 mi
Registration #15	2017-11-21	31.377 mi
Registration #16	2018-11-21	31.377 mi
Registration #17	2019-11-21	31.377 mi
Registration #18	2020-11-21	31.377 mi
Registration #19	2021-11-21	31.377 mi
Registration #20	2022-11-21	31.377 mi
Registration #21	2023-11-21	31.377 mi
Registration #22	2024-11-21	31.377 mi
Registration #23	2025-11-21	31.377 mi
Registration #24	2026-11-21	31.377 mi

More info >



Safety ratings

NCAP rating ★ ★ ★ ★ ★

Video [see crash video](#)

Dimensions & weight

Width	1595 mm
Height	1360 mm
Length	3718 mm
Wheel base	2385 mm
Kerb weight	920 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	FX4D1898243