



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX GHIA
Colour	Black
Year of manufacture	2005
Top speed	120 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	166 Nm at 4.500 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	38.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-09-17
Pictures	19
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-17
Pictures	23
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-09-13
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	60
Total items failed	14

MOT #22	2022-09-08 10:17
---------	------------------

MOT test number	771452747257
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2023-09-13
------------------	------------

- Minor

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Offside Play in steering rack inner joint(s)
- Advice

Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice

Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #21**

2022-09-08 09:30

MOT test number

984168920528

Result

✗ Failed

- Advice** Offside Rear Parking (secondary brake) grabbing slightly (1.3.1 (c))
- Fail** Offside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
- Advice** Offside Play in steering rack inner joint(s)
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Headlamp has a product on the light source so that the light output is severely reduced (4.1.4 (b))
- Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #20

2021-09-14 16:19

MOT test number

251309327794

Result

✓ Passed

- Advice** Tyre worn close to legal limit/worn on edge O/S/F, N/S/F and N/S/R (5.2.3 (e))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #19**

2021-09-06 18:31

MOT test number

463230810416

Result**✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge O/S/F, N/S/F and N/S/R (5.2.3 (e))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #18

2020-09-07 12:54

MOT test number

848372165635

Result**✓ Passed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner tread (5.2.3 (e))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #17

2020-09-07 08:11

MOT test number

557358239023

Result**✗ Failed**

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn inner tread (5.2.3 (e))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #16** 2019-09-16 10:25**MOT test number** 400438030721**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #15** 2019-09-16 10:25**MOT test number** 204290793578**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #14** 2018-09-24 09:53**MOT test number** 217723069689**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #13**

2017-10-02 15:04

MOT test number

570035948010

Result

✓ Passed

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Both front tyres worn on edges inner edges smooth**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside headlamp slightly deteriorated image ok**Advice** Offside Rear worn inner most edge**MOT #12**

2017-10-02 10:17

MOT test number

927365348995

Result

✗ Failed

Advice Offside Rear worn inner most edge**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Both front tyres worn on edges inner edges smooth**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Nearside headlamp slightly deteriorated image ok**MOT #11**

2016-09-28 11:01

MOT test number

867743984275

Result

✓ Passed

Advice Offside headlamp lens slightly deteriorated**Advice** Offside Front Tyre worn close to the legal limit worn / wearing inner edge (4.1.E.1)

**MOT #10** 2015-09-28 13:55**MOT test number** 957601232175**Result** ✓ Passed**MOT #9** 2014-09-22 14:42**MOT test number** 599885964234**Result** ✓ Passed**MOT #8** 2013-09-30 09:57**MOT test number** 655313673254**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** N/s/f tyre wearing on inner edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in offside rear tyre**MOT #7** 2012-10-01 12:21**MOT test number** 119525472213**Result** ✗ Failed**Notice** O/s/f tyre worn very low on inner edge**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2012-10-01 12:21**MOT test number** 317755872494**Result** ✓ Passed**Notice** O/s/f tyre worn very low on inner edge


**MOT #5** 2011-09-19 09:21**MOT test number** 438822461213**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Wiper blades in poor condition**MOT #4** 2010-09-20 09:23**MOT test number** 332063460287**Result** ✓ Passed**MOT #3** 2009-09-14 16:18**MOT test number** 340917459299**Result** ✓ Passed**MOT #2** 2009-09-14 09:24**MOT test number** 764537559292**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2008-09-22 10:03**MOT test number** 443196868225**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EK55LWH
Plate since	2019-03-28
Current registration	EK55LWH
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2005-10-12
Last registration	2022-09-08
Complete history	See info



Registration #1	2005-10-12	28 mi
Registration #2	2008-09-22	21.117 mi
Registration #3	2009-09-14	29.232 mi
Registration #4	2009-09-14	29.232 mi
Registration #5	2010-09-20	36.600 mi
Registration #6	2011-09-19	44.284 mi
Registration #7	2012-10-01	51.134 mi
Registration #8	2013-09-30	58.203 mi
Registration #9	2014-09-22	65.313 mi
Registration #10	2015-09-28	72.028 mi
Registration #11	2016-09-28	79.914 mi
Registration #12	2017-10-02	86.521 mi
Registration #13	2018-09-22	93.128 mi
Registration #14	2019-09-22	99.735 mi
Registration #15	2020-09-22	106.342 mi
Registration #16	2021-09-22	112.949 mi
Registration #17	2022-09-08	119.556 mi
Registration #18	2023-09-08	126.163 mi
Registration #19	2024-03-28	132.770 mi
Registration #20	2024-03-28	139.377 mi
Registration #21	2024-03-28	145.984 mi
Registration #22	2024-03-28	152.591 mi
Registration #23	2024-03-28	159.198 mi
Registration #24	2024-03-28	165.805 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1783 mm
Height	1558 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5C13915