



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 111 CDI EXTRA LONG TRAVELINER
Colour	White
Year of manufacture	2004
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2024-08-23
MOT pass rate	54 %
MOT passed	14
Failed MOT tests	12
Total advice items	96
Total items failed	56

MOT #26 2023-08-24 10:20

MOT test number 393307266027

Result ✓ Passed

Next expiry date 2024-08-23

Advice Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

Advice Welding to under side of vehicle

MOT #25 2022-08-18 12:50

MOT test number 832399916877

Result ✓ Passed

Advice Rear Vehicle structure is repaired but structural rigidity is not significantly reduced (6.1.1 (d) (i))

Advice Underbody heavily undersealed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #24**

2021-04-30 16:45

MOT test number

285134014949

Result

✓ Passed

- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Headlamp beam images poor
- Advice** Rear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively n/s and o/s (1.2.1 (e))
- Advice** Front Direction indicator slightly discoloured n/s and o/s (4.4.3 (a))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced heavily corroded and covered in underseal (6.1.1 (c) (i))

**MOT #23**

2021-04-16 14:32

MOT test number

962408812059

Result**✗ Failed**

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Front Direction indicator slightly discoloured n/s and o/s (4.4.3 (a))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Upper Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Advice** Rear Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Windscreen wipers smearing
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Front Anti-roll bar pin or bush worn but not resulting in excessive movement n/s and o/s (5.3.4 (a) (i))
- Advice** Nearside Front Nail in tyre
- Fail** Nearside Front Service brake excessively fluctuating (1.2.1 (e))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced heavily corroded and covered in underseal (6.1.1 (c) (i))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Front Suspension arm attachment bracket/mounting corroded and seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength rear mounting (5.3.6 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Rear Upper Suspension spring mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

Advice Headlamps full of water

Advice Brake disc worn, pitted or scored, but not seriously weakened Front and rear (1.1.14 (a) (ii))

Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Coolant leak

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Minor Offside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**MOT #22**

2020-03-24 13:22

MOT test number

888704401114

Result

✓ Passed

- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Many old welded repairs covered over with sealer and underseal
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** General corrosion on rest of underneath of vehicle
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material to brake flexi (1.1.11 (c))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Parking brake could do with some adjustment
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #21

2019-04-11 09:39

MOT test number

823866288513

Result

✓ Passed



MOT #20	2017-12-12 15:08
MOT test number	767900856516
Result	✗ Failed
Fail	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Front coil spring broken (2.4.C.1a)
Fail	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Bonnet cannot be secured in the closed position (8.4.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Stop lamp not working (1.2.1b)

**MOT #19**

2017-06-08 10:32

MOT test number

644772873952

Result**✗ Failed****Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Rear arches corroded**Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded outrider (5.2.6)**Fail** Exhaust emits excessive smoke or vapour of any colour (7.4.B.4)**Fail** Front passenger door does not latch securely closed (6.2.B.1a)**Fail** Nearside Rear Suspension component mounting prescribed area is excessively corroded chassis,sill and undersill (2.4.A.3)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Headlamp excessively deteriorated so that the light output is severely reduced both (1.7.5a)**Advice** Rear crossmember corroded and holed**Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded outrider (5.2.6)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Suspension spring mounting prescribed area is excessively corroded both rear (2.4.A.3)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Fail** Offside Rear Suspension component mounting prescribed area is excessively corroded chassis,sill and undersill (2.4.A.3)

**MOT #18**

2016-03-21 15:44

MOT test number

342763819829

Result

✓ Passed

- Advice** Corrsion on floors
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Offside sill corroded
- Advice** Corrsion on n/s and o/s sills
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside sill corroded

MOT #17

2016-03-15 11:49

MOT test number

992599261615

Result

✗ Failed

- Fail** Offside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Offside sill corroded
- Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Corrsion on n/s and o/s sills
- Fail** Nearside Rear Suspension spring mounting prescribed area is excessively corroded (2.4.A.3)
- Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)
- Advice** Nearside sill corroded
- Advice** Corrsion on floors

MOT #16

2015-04-01 15:51

MOT test number

765391895038

Result

✓ Passed

- Notice** Corrosion on front and rear chassis

**MOT #15**

2015-03-31 10:36

MOT test number

107890195404

Result**✗ Failed**

- Notice** Corrosion on front and rear chassis
- Fail** Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Front Anti-roll bar insecure (2.4.G.1)

MOT #14

2014-01-07 16:15

MOT test number

497247104064

Result**✓ Passed**

- Notice** Nail in the nsr tyre + close to limits
- Notice** Underbody + both sills corroded
- Notice** Osf steering rack gaitor slightly worn
- Notice** Rear discs corroded
- Notice** Osr tyre close to limits
- Notice** Osf brake pipe slightly corroded

**MOT #13**

2014-01-07 12:51

MOT test number

726547204032

Result**✗ Failed**

- Notice** Rear discs corroded
- Fail** Nearside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Notice** Osr tyre close to limits
- Notice** Osf brake pipe slightly corroded
- Fail** Front Anti-roll bar has excessive play in a pin/bush (2.4.G.2)
- Notice** Nail in the nsr tyre + close to limits
- Fail** Offside Front Anti-roll bar has excessive play in a ball joint (2.4.G.2)
- Notice** Underbody + both sills corroded
- Notice** Osf steering rack gaitor slightly worn

MOT #12

2012-10-08 17:27

MOT test number

935422482256

Result**✓ Passed**

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Body has slight corrosion (6.1.B.2)

MOT #11

2012-10-08 10:51

MOT test number

758382682230

Result**✗ Failed**

- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Offside Front Anti-roll bar ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**MOT #10** 2011-05-21 13:20**MOT test number** 299111041473**Result** ✓ Passed**MOT #9** 2011-05-20 12:49**MOT test number** 256470441461**Result** ✗ Failed**Advice** Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** All under body corrosion**MOT #8** 2009-12-24 11:12**MOT test number** 144998559343**Result** ✓ Passed**MOT #7** 2009-12-23 10:41**MOT test number** 173377859356**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Nearside front brake grabbing severely (3.7.A.2b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside front brake binding (3.7.B.1)**Fail** Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i)

**MOT #6** 2009-01-13 16:13**MOT test number** 491863119073**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2009-01-05 16:43**MOT test number** 394145209041**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Rear coil spring incomplete (2.4.C.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2008-01-14 16:42**MOT test number** 123704718494**Result** ✓ Passed**MOT #3** 2008-01-14 11:35**MOT test number** 244064818070**Result** ✗ Failed**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)



MOT #2	2007-09-27 09:48
MOT test number	783790677251
Result	✓ Passed

MOT #1	2007-09-25 16:31
MOT test number	751608767261
Result	✗ Failed
<div><div>Fail</div>Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Fail</div>Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)</div>	
<div><div>Fail</div>Service brake: efficiency below requirements (3.7.D.4)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
23 August 2024

Tax status		Valid until 1 August
Days left		95
MOT expiry date		23 August 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history


For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2004-10-25
Last registration	2023-08-24
Complete history	See info



Registration #1	2004-10-25	8 mi
Registration #2	2007-09-25	51.332 mi
Registration #3	2007-09-27	51.332 mi
Registration #4	2008-01-14	55.616 mi
Registration #5	2008-01-14	55.616 mi
Registration #6	2009-01-05	69.262 mi
Registration #7	2009-01-13	69.743 mi
Registration #8	2009-12-23	76.568 mi
Registration #9	2009-12-24	76.568 mi
Registration #10	2011-05-20	88.953 mi
Registration #11	2011-05-21	88.953 mi
Registration #12	2012-10-08	102.656 mi
Registration #13	2012-10-08	102.660 mi
Registration #14	2014-01-07	115.320 mi
Registration #15	2015-05-20	131.332 mi
Registration #16	2015-05-20	131.332 mi
Registration #17	2015-05-20	131.332 mi
Registration #18	2015-05-20	131.332 mi
Registration #19	2015-05-20	131.332 mi
Registration #20	2015-05-20	131.332 mi
Registration #21	2015-05-20	131.332 mi
Registration #22	2015-05-20	131.332 mi
Registration #23	2015-05-20	131.332 mi
Registration #24	2015-05-20	131.332 mi
Registration #25	2015-05-20	131.332 mi
Registration #26	2015-05-20	131.332 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1872 mm
Length	5223 mm
Kerb weight	1965 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	64698250083709