



**HJ56GOP**

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	LT 35P/VMWBH/R108BHPTDI
Colour	White
Year of manufacture	-
Top speed	84 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	5
Fuel type	Diesel



LABEL UNKNOWN

**MOT history****MOT #20** 2020-12-18 19:35**MOT test number** 193785570416**Result** ✓ Passed**Next expiry date** 2021-12-19

- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Parking (secondary brake) grabbing slightly (1.3.1 (c))

**MOT #19** 2019-12-20 09:15**MOT test number** 367995237487**Result** ✓ Passed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak, but not excessive engine, (8.4.1 (a) (i))
- Advice** Rear both light clusters damaged,
- Advice** Rear Service brake fluctuating, but not excessively both sides, (1.2.1 (e))
- Advice** Front Wheel bearing has slight play both sides, (5.1.3 (a) (i))
- Advice** Offside Front wiper linkage badly worn,
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))



MOT #18	2019-12-09 11:20
MOT test number	960820947915
Result	✗ Failed

- Fail** Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Nearside Front Side repeater flashing more than 120 times a minute (4.4.4 (a))
- Fail** Offside Front Headlamp not working on dipped beam when main beam switched on, (4.1.1 (a) (ii))
- Advice** Rear both light clusters damaged,
- Fail** Nearside Obligatory mirror insecure (3.3 (b) (ii))
- Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Service brake fluctuating, but not excessively both sides, (1.2.1 (e))
- Advice** Front Wheel bearing has slight play both sides, (5.1.3 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Offside Front wiper linkage badly worn,
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Minor** Nearside Rear Side repeater flashing more than 120 times a minute (4.4.4 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Battery insecure and likely to cause a short circuit (4.13 (a) (ii))
- Fail** Offside Obligatory mirror insecure (3.3 (b) (ii))
- Fail** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive engine, (8.4.1 (a) (i))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #17** 2018-12-06 11:23**MOT test number** 873126460193**Result** ✓ Passed**Advice** Handbrake requires early attention**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #16** 2017-12-09 12:51**MOT test number** 767184427444**Result** ✓ Passed**Advice** Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.B.2)**Advice** Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt both (2.4.G.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #15** 2017-05-02 12:11**MOT test number** 106562697121**Result** ✓ Passed**Advice** Oil leak**Advice** Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt both (2.4.G.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Play in steering rack inner joint(s)

**MOT #14**

2017-05-02 12:11

**MOT test number**

176999468991

**Result****✗ Failed****Advice** Play in steering rack inner joint(s)**Pass with rectification** Nearside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)**Advice** Oil leak**Advice** Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt both (2.4.G.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #13**

2016-01-22 08:10

**MOT test number**

645626549906

**Result****✓ Passed****Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** N/s+o/s front shocker dust covers missing**Advice** Rear brake fluctuating, but not excessively n/s+o/s (3.7.B.3)**Advice** Oil leak

**MOT #12**

2016-01-11 09:37

**MOT test number**

405648061655

**Result****✗ Failed**

- Fail** Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Exhaust has a major leak of exhaust gases centre box joint (7.1.2)
- Fail** Offside Front Headlamp not working on main beam (1.7.5a)
- Fail** Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** N/s+o/s front shocker dust covers missing
- Fail** Rear parking brake recording little or no effort n/s+o/s (3.7.B.6a)
- Fail** Front position lamp(s) not working n/s+{o/s roof (1.1.A.3b)
- Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)
- Advice** Rear brake fluctuating, but not excessively n/s+o/s (3.7.B.3)
- Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)
- Advice** Oil leak
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

**MOT #11** 2014-10-28 15:38**MOT test number** 685511604352**Result** ✓ Passed**Advice** Nearside Front Shock absorber has slight external damage to the casing (2.7.2a)**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**Advice** Offside Front Shock absorber has slight external damage to the casing (2.7.2a)**Notice** Oil leak**MOT #10** 2014-10-28 09:53**MOT test number** 117771504379**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)**Advice** Offside Front Shock absorber has slight external damage to the casing (2.7.2a)**Notice** Oil leak**Fail** Offside Front Anti-roll bar attachment bracket/mounting insecure (2.4.G.1)**Advice** Nearside Front Shock absorber has slight external damage to the casing (2.7.2a)**Advice** Offside Front Lower Shock absorber has a slightly worn bush (2.7.4)**MOT #9** 2013-10-09 14:01**MOT test number** 316302183405**Result** ✓ Passed



**MOT #8**

2013-10-03 16:44

**MOT test number**

619306473281

**Result****✗ Failed**

- Fail** Brake load sensing valve linkage defective and function impaired (3.6.E.3)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Brake load sensing valve seized (3.6.E.3)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Notice** Oil leak
- Advice** Nearside Front Direction indicator damaged, but still visible from a reasonable distance (1.4.A.2e)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Fail** Offside Stop lamp not working (1.2.1b)
- Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)



MOT #7

2012-10-05 16:33

MOT test number

339639572405

Result		✓ Passed
Advice	Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Oil leak	
Advice	Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)	
Notice	Gearbox mounting defective	
Advice	Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	

**MOT #6**

2012-10-03 12:52

**MOT test number**

535067572264

**Result****✗ Failed**

- Fail** Offside Obligatory mirror insecure (8.1.1)
- Fail** Offside Lower Front suspension has excessive movement at a wishbone pin or bush (2.5.A.1c)
- Fail** Rear registration plate letter/figure incomplete (6.3.1c)
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Oil leak
- Fail** Spare wheel carrier insecure (6.4.2)
- Fail** Nearside Obligatory mirror insecure (8.1.1)
- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)
- Fail** Offside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear position lamp(s) has less than 50% of the light sources illuminating (1.1.A.3b)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Advice** Power steering pipe(s) or hose(s) has slight seepage from a seal (2.3.3b)
- Notice** Gearbox mounting defective
- Fail** Nearside Front Anti-roll bar linkage rubber bush deteriorated resulting in excessive movement (2.4.G.2)



**MOT #5** 2011-08-10 16:40**MOT test number** 189322121236**Result** ✓ Passed**MOT #4** 2011-08-08 13:10**MOT test number** 307870021293**Result** ✗ Failed

- Fail** Offside Obligatory mirror insecure (8.1.1)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Front wheel bearing has excessive play (2.5.A.3c)
- Fail** Rear registration plate obscured (6.3.1d)
- Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)
- Fail** Nearside Headlamp aim too far to the right (1.8)
- Fail** Spare wheel carrier insecure (6.4.2)
- Fail** Offside Front wheel bearing has excessive play (2.5.A.3c)

**MOT #3** 2010-08-05 10:21**MOT test number** 720117010241**Result** ✓ Passed

- Advice** Nearside Front Ball joint has slight play (2.2.B.1f)

**MOT #2** 2009-08-10 11:46**MOT test number** 373492129240**Result** ✓ Passed



MOT #1	2009-08-10 11:46
MOT test number	813732229263
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper blade insecure (8.2.2)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	 <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-09-22
Last registration	2020-12-18
Complete history	<a href="#">See info</a>



Registration #1	2006-09-22	25 mi
Registration #2	2009-08-10	119.472 mi
Registration #3	2010-08-05	132.213 mi
Registration #4	2011-08-08	146.416 mi
Registration #5	2011-08-10	146.420 mi
Registration #6	2012-10-03	167.602 mi
Registration #7	2012-10-05	167.625 mi
Registration #8	2013-10-03	184.873 mi
Registration #9	2013-10-09	184.877 mi
Registration #10	2014-10-28	200.240 mi
Registration #11	2015-05-20	215.557 mi
Registration #12	2015-05-20	215.557 mi
Registration #13	2015-05-20	215.557 mi
Registration #14	2015-05-20	215.557 mi
Registration #15	2015-05-20	215.557 mi
Registration #16	2015-05-20	215.557 mi
Registration #17	2015-05-20	215.557 mi
Registration #18	2015-05-20	215.557 mi
Registration #19	2015-05-20	215.557 mi
Registration #20	2015-05-20	215.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	AVR 072201