





report date: 2024-03-29

## General information

Make	HYUNDAI
Model	COUPE SE
Colour	Silver
Year of manufacture	-
Top speed	128 mph
0 - 60 mph	9.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	136 BHP
Max. torque	181 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg



CarCheck.co.uk page 1/17




# Internet history

## Entry 1

Date 2021-09-01


Pictures 26

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/17



MOT history

MOT #21		2021-11-13 11:32
MOT test	number	102509367841
Result		✓ Passed
Next expi	ry date	2022-11-12
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))	

MOT #20		2021-01-18 12:49
MOT test	number	472401947420
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge void of tread on edg	e (5.2.3 (e))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened o/s & n/s (1	1.1.14 (a) (ii))
Advice	Power steering pipe/hose has slight seepage border line (2.1.5 (a))	
Advice	Nearside Front Brake pipe clips or supports missing, pipe adequately supported	I (1.1.11 (d) (i))
Advice	Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11)	(c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge void of tread on edge	(5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))	

CarCheck.co.uk page 3/17



report date: 2024-03-29

**MOT #19** 2021-01-08 15:02

MOT test number 705623988583

Result × Failed **Advice** Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i)) **Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) Fail Front Registration plate deteriorated but not likely to be misread (0.1 (b)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge void of tread on edge (5.2.3 (e)) **Advice** Fail Nearside Rear Anti-roll bar pin or bush excessively worn D- bush (5.3.4 (a) (i)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened o/s & n/s (1.1.14 (a) (ii)) **Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) **Advice** Front Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i)) Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Nearside Front Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i)) Advice Offside Rear Tyre slightly damaged/cracking or perishing border line (5.2.3 (d) (ii)) Advice Power steering pipe/hose has slight seepage border line (2.1.5 (a)) Advice Offside Front Tyre worn close to legal limit/worn on edge void of tread on edge (5.2.3 (e)) Offside Rear Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i)) Fail

CarCheck.co.uk page 4/17



report date: 2024-03-29

MOT #18 2020-01-13 11:25

**MOT test number** 672511056591

Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i))
Advice	Nearside Front Brake pipe clips or supports missing, pipe adequately supported (1.1.11 (d) (i))
Advice	Fluid leak, but not excessive (8.4.1 (a) (i))
Advice	Power steering pipe/hose has slight seepage (2.1.5 (a))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, but not excessively o/s & n/s inner face's (1.1.14 (a) (i))
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
<b>Advice</b> (5.3.4 (a) (	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement mounting
<b>Advice</b> requires ac	Front Brakes imbalanced requirements only just met. It would appear that the braking system djustment or repair. (1.2.1 (b) (i))

CarCheck.co.uk page 5/17



(5.3.4 (a) (i))

ET53FHR

report date: 2024-03-29

**MOT #17** 2020-01-10 10:17

**MOT test number** 591938483824

Result **X** Failed **Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i)) **Advice** Rear Brake hose has slight corrosion to ferrule o/s & n/s (1.1.12 (f) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Power steering pipe/hose has slight seepage (2.1.5 (a)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Fluid leak, but not excessive (8.4.1 (a) (i)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Fail** Nearside Front Brake pipe excessively corroded inner wing (1.1.11 (c)) **Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice **Advice** Front Brake disc worn, but not excessively o/s & n/s inner face's (1.1.14 (a) (i)) Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement mounting

CarCheck.co.uk page 6/17



report date: 2024-03-29

**MOT #16** 2019-01-09 14:14 **MOT** test number 923555131998 ✓ Passed Result **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Rear subframe corroded Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Front Brake disc worn, pitted or scored, but not seriously weakened both inner faces (1.1.14 (a) Advice (ii)) Advice Power steering pipe/hose has slight seepage (2.1.5 (a)) Minor Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Various corrosion underside **Advice** Offside Front Nail in tyre

MOT #15		2018-01-09 11:49
MOT test	number	938751822854
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases rear joint in poor condition (7.1.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 7/17



report date: 2024-03-29

**MOT #14** 2018-01-02 14:53

MOT test number 641182348061

**Result** X Failed

**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill/floor (2.4.A.3)

Fail Nearside Headlamp aim too low (1.8)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Advice Signs of fluid leak from power steering pipe/joint (pipe from pump to rack). no visible leaks at time of test.

**Advice** Front brake fluctuating, but not excessively both sides (3.7.B.3)

**Advice** Exhaust has a minor leak of exhaust gases rear joint excessively corroded (7.1.2)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive inner sill/floor (2.4.A.3)

**Fail** Offside Headlamp aim aimed so that it dazzles other road users no pattern (1.8.A.1a)

**Advice** Offside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Advice** Slight imbalance on front brakes

**Fail** Offside Brake pipe inadequately clipped front to rear brake pipe rubbing on floor/chassis next to fuel tank (3.6.B.1)

MOT #13 2016-12-20 10:54

**MOT test number** 522830290618

**Result** ✓ Passed

**MOT #12** 2015-12-22 11:55

**MOT test number** 679941095185

**Result** 
✓ Passed

**Advice** Exhaust clamp corroded middle to rear

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 8/17



report date: 2024-03-29

MOT test number

Result

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Exhaust clamp corroded middle to rear

Fail Exhaust has a major leak of exhaust gases front flexi pipe (7.1.2)

MOT test number
916333564316

Result

Advice
Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice
Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice
Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9	2014-01-14 09	9:12
<b>MOT</b> test	<b>number</b> 909634714	090
Result	✓ Pas	sed
Notice	Nail in nearside front tyre	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Exhaust clamp middle to rear corroded	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 9/17



MOT #8 2014-01-10 11:50

**MOT test number** 448410314065

**Result** X Failed

**Notice** Nail in nearside front tyre

Fail Nearside Brake pipe excessively corroded (3.6.B.2c)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Exhaust clamp middle to rear corroded

**Fail** Offside Brake pipe excessively corroded (3.6.B.2c)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2013-01-08 12:34

**MOT test number** 298188903046

**Result** ✓ Passed

**Notice** Exhaust corroded middle to rear clamp

**MOT #6** 2012-01-10 13:08

**MOT test number** 928390712096

CarCheck.co.uk page 10/17



report date: 2024-03-29

MOT #5		2011-01-06 15:26
MOT test	number	585656901085
Result		✓ Passed
Advice	Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice	Nearside front brake discs worn	
Advice	Offside Rear Brake pipe slightly corroded (3.6.B.2c)	
Notice	Offside front brake discs worn	

MOT #4	2010-01-08 13:14
MOT test number	383738600051
Result	✓ Passed
MOT #3	2009-01-02 14:46
1101 #3	2009-01-02 14.40
MOT test number	121572209050

MOT #2	2008-01-02 10:25
MOT test number	381922308051
Result	<b>✓</b> Passed
MOT #1	2007-01-04 12:04

MOT #1	2007-01-04 12:04
MOT test number	522504707037
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 11/17



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 12/17



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 13/17



Owner history

e mier metery	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	AR AR
Plate since	
	More info >

CarCheck.co.uk page 14/17



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 15/17



# Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-01-08
Last registration	2021-11-13
Complete history	See info



Registration #1	2004-01-08	19 mi
Registration #2	2007-01-04	18.058 mi
Registration #3	2008-01-02	24.058 mi
Registration #4	2009-01-02	30.279 mi
Registration #5	2010-01-08	35.798 mi
Registration #6	2011-01-06	41.127 mi
Registration #7	2012-01-10	46.018 mi
Registration #8	2013-01-08	49.921 mi
Registration #9	2014-01-10	53.743 mi
Registration #10	2014-01-14	53.776 mi
Registration #11	2014-12-29	57.262 mi
Registration #12	2015-12-22	60.511 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 16/17



Car features

S0225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1280 kg
Max. allowed weight	1740 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC4993655

CarCheck.co.uk page 17/17