





report date: 2024-03-29

General information

Make	FORD
Model	ESCORT SI
Colour	Yellow
Year of manufacture	-
Top speed	110 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	134 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	34.0 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-29

MOT history

MOT #16		2020-11-16 16:19
MOT test	number	118467549124
Result		✓ Passed
Next expi	ry date	2021-11-15
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))
Advice	Front and rear underbody corroded	
Advice	Front Brake pipe corroded, covered in grease or other material o/s & n/s (1.1.	11 (c))
Advice	Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Fuel tank corroded		
Advice Brake pipe corroded, covered in grease or other material o/s & n/s front to rear (1.1.11 (c))		
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	O/s & n/s inner and outer sills corroded	
Advice chassis (6.	Rear Vehicle structure is corroded but structural rigidity is not significantly re 1.1 (c) (i))	duced o/s & n/s

CarCheck.co.uk page 2/13



MOT #15

Advice

Advice

Advice

Result

Pass with rectification

Front and rear underbody corroded

P530MJW

report date: 2024-03-29

2020-11-16 16:19

✓ Passed

MOT test number 997042739691 Result × Failed **Advice** Brake pipe corroded, covered in grease or other material o/s & n/s front to rear (1.1.11 (c)) **Advice** Fuel tank corroded Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced o/s & n/s chassis (6.1.1 (c) (i)) Advice O/s & n/s inner and outer sills corroded Pass with rectification Offside Rear Position lamp not working (4.2.1 (a) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14 2016-09-29 11:45
MOT test number 965410985906

Front Brake pipe corroded, covered in grease or other material o/s & n/s (1.1.11 (c))


Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Nearside Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 3/13



report date: 2024-03-29



MOT #12		2015-03-12 16:20
MOT test	number	519881875097
Result		✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Fuel filter corroded	
Advice	Rear Brake pipe slightly corroded (3.6.B.2c)	

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #11 2015-03-06 12:02 136395065419 **MOT** test number Result × Failed Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2) Fail Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4) Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3) Fail Fail Rear fog lamp not working (1.3.2b) **Advice** Rear Brake pipe slightly corroded (3.6.B.2c) Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail Fail Nearside Rear wheel bearing has excessive play (2.6.2) Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3) **Advice** Exhaust has a minor leak of exhaust gases (7.1.2) Notice Fuel filter corroded

MOT #10	2012-06-14 15:53
MOT test number	208316062170
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #9 2012-05-31 11:14 **MOT** test number 358552752196 Result × Failed Fail Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a) Fail Nearside Front Front position lamp(s) not working (1.1.A.3b) Offside Rear Rear fog lamp not working (1.3.2b) Fail Parking brake: efficiency below requirements (3.7.B.7) Fail Fail Nearside Front Steering rack gaiter insecure (2.2.D.2d) Fail Offside Front Front position lamp(s) not working (1.1.A.3b) Service brake: efficiency below requirements (3.7.B.7) Fail

MOT #8 2011-05-26 11:30 **MOT** test number 899226541161 Result ✓ Passed **Advice** Front Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Rear wheel bearing has slight play (2.6.2) Advice Offside Body has slight corrosion (6.1.B.2) Advice Nearside Front Radius arm has slight play in a ball joint (2.4.G.2) Advice Nearside Body has slight corrosion (6.1.B.2)

MOT #7

MOT test number

284866940492

Result

Notice Oil leak

2010-05-26 13:43

✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

MOT #6 2010-05-15 09:58 114715830190 **MOT** test number Result × Failed **Notice** Oil leak **Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2) Fail Offside Front Front constant velocity joint gaiter split (2.5.C.1a) Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2) Fail Parking brake lever has no reserve travel (3.1.6b) Parking brake: efficiency below requirements (3.7.B.7) Fail

MOT #5

MOT test number

862408049197

Result

Notice Oil leak

2009-05-28 09:25

862408049197

MOT test number

472377949156

Result

Fail Nearside Front Front constant velocity joint gaiter split (2.5.C.1a)

Notice Oil leak

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Service brake: efficiency below requirements (3.7.B.7)

MOT #3

MOT test number

891039948173

Result

✓ Passed

CarCheck.co.uk page 7/13



report date: 2024-03-29

MOT #2	2007-05-31 12:17
MOT test number	853631157173
Result	✓ Passed
MOT #1	2006-05-25 13:15
MOT #1 MOT test number	2006-05-25 13:15 271815946441

CarCheck.co.uk page 8/13



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

_	
Owner	hictory
OWITEI	HISLOLY

Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	1997-04-15
Last registration	2020-11-16
Complete history	See info



Registration #1	1997-04-15	20 mi
Registration #2	2006-05-25	65.378 mi
Registration #3	2007-05-31	76.717 mi
Registration #4	2008-05-28	87.855 mi
Registration #5	2009-05-27	93.492 mi
Registration #6	2009-05-28	93.492 mi
Registration #7	2010-05-15	10.510 mi
Registration #8	2010-05-26	11.083 mi
Registration #9	2011-05-26	23.640 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.177 au
Registration #17		11.177 mi

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	******
Video	see crash video



Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	VR88033

CarCheck.co.uk page 13/13