



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SPRINTER 311 CDI LWB P/V
Colour	White
Year of manufacture	2004
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	at 1.400 rpm
Engine capacity	2.151 cc
Cylinders	4
Fuel type	Diesel





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-07-26
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	140
Total items failed	30

MOT #26	2023-07-13 15:56
---------	------------------

MOT test number	724278840855
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-07-26
------------------	------------

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Integral body structure is repaired but structural rigidity is not significantly reduced (6.1.1 (d) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** N/S/F sill corroded
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Off brake hose (1.1.11 (c))
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #25**

2023-07-06 11:15

MOT test number

520432274294

Result**✗ Failed**

- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** N/S/F sill corroded
- Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Off brake hose (1.1.11 (c))
- Advice** Play in steering rack inner joint(s)
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Suspension component mounting prescribed area is corroded to the extent that control of the vehicle is likely to be adversely affected Rear leaf spring mounting (5.3.6 (a) (ii))
- Fail** Nearside Front Anti-roll bar linkage pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Driver's door hinge deteriorated but the door can still be readily opened and closed (6.2.3 (c) (i))



MOT #242022-07-26 15:22

MOT test number260125267948

Result		✓ Passed
Advice	Play in steering rack inner joint(s)	
Advice	Front Suspension component pin or bush slightly worn D bushes x2 (5.3.4 (a) (i))	
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Nearside Seat belt buckle slightly damaged (7.1.2 (d))	
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Advice	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step (6.1.1 (c) (i))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice	Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))	
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer sill (6.1.1 (c) (i))	

**MOT #23**

2022-07-19 15:19

MOT test number

646517405044

Result**✗ Failed****Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced inner and outer sill (6.1.1 (c) (i))**Advice** Offside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Front Suspension component pin or bush slightly worn D bushes x2 (5.3.4 (a) (i))**Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Play in steering rack inner joint(s)**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step (6.1.1 (c) (i))**Advice** Nearside Seat belt buckle slightly damaged (7.1.2 (d))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #22

2021-07-15 15:41

MOT test number

806729653042

Result		✓ Passed
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))	
Advice	Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))	
Minor	Headlamp lens slightly defective cloudy x2 (4.1.1 (b) (i))	
Advice	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step inner and outer (6.1.1 (c) (i))	
Advice	Front Wheel bearing has slight play x2 (5.1.3 (a) (i))	
Advice	Surface corrosion to underside	
Advice	Play in steering rack inner joint(s)	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step inner and outer (6.1.1 (c) (i))	

**MOT #21**

2021-07-15 08:57

MOT test number

970988096336

Result**✗ Failed**

- Advice** Nearside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step inner and outer (6.1.1 (c) (i))
- Advice** Brake pipe corroded, covered in grease or other material all (1.1.11 (c))
- Advice** Surface corrosion to underside
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Front Seat belt buckle slightly damaged (7.1.2 (d))
- Advice** Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced door step inner and outer (6.1.1 (c) (i))
- Advice** Front Wheel bearing has slight play x2 (5.1.3 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Minor** Headlamp lens slightly defective cloudy x2 (4.1.1 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #20

2020-07-27 14:52

MOT test number

383801155145

Result**✓ Passed**

- Advice** Underbody corrosion
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2020-07-25 12:22

MOT test number

555191811389

Result**✗ Failed****Advice**

Underbody corrosion

Fail

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail

Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail

Lower Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))

Fail

Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail

Front Registration plate missing (0.1 (a))

Fail

Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #18

2019-01-16 14:34

MOT test number

536725608716

Result**✓ Passed****Advice**

Tyres perished

Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice

Play in steering rack inner joint(s)

**MOT #17**

2018-01-18 14:57

MOT test number

794329975384

Result

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Front Tyre worn close to the legal limit outer tread (4.1.E.1)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Front registration plate damaged

MOT #16

2017-01-19 10:43

MOT test number

319146309963

Result

✓ Passed

- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement 'D' bush (2.4.G.2)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement 'D' bush (2.4.G.2)

MOT #15

2016-01-22 09:26

MOT test number

278711881616

Result

✓ Passed

- Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Glow plug warning light illuminated on dash

**MOT #14**

2015-01-20 15:50

MOT test number

417250325067

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Both front flexy brake hoses badly deteriorated
- Advice** Offside Rear Anti-roll bar has slight play in a pin bearing (2.4.G.2)
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Notice** Offside rear tyre worn 3mm
- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #13

2015-01-20 15:50

MOT test number

527520425079

Result

✗ Failed

- Advice** Offside Rear Anti-roll bar has slight play in a pin bearing (2.4.G.2)
- Notice** Both front flexy brake hoses badly deteriorated
- Advice** Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar has slight play in a ball joint (2.4.G.2)
- Notice** Offside rear tyre worn 3mm
- Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)
- Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)



MOT #12

2014-01-13 10:28

MOT test number

607023914053

Result		✓ Passed
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)	
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Brake hose slightly deteriorated (3.6.B.4d)	
Advice	Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)	
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake hose slightly deteriorated (3.6.B.4d)	



MOT #11 2014-01-13 10:28

MOT test number 168373514495

Result ✗ Failed

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Pass with rectification Nearside Headlamp aim too high and too far to the left. (1.8)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Headlamp aim too high and too far to the left. (1.8)

Advice Nearside Front Brake hose slightly deteriorated (3.6.B.4d)

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Offside Front wheel bearing has slight play (2.5.A.3c)

Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #10 2013-01-09 12:25

MOT test number 159479303469

Result ✓ Passed

Notice Eml on

Notice Slight lift in both lower ball joints

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #9**

2013-01-09 12:25

MOT test number

428469703041

Result**✗ Failed****Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Slight lift in both lower ball joints**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Notice** Eml on**MOT #8**

2012-01-23 11:36

MOT test number

837143522036

Result**✓ Passed****Notice** Vin plate missing under hood**Notice** EMISSIONS TO CLEAN TO DETECT**MOT #7**

2012-01-23 09:21

MOT test number

489883822053

Result**✗ Failed****Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front registration plate missing (6.3.1a)**Notice** Vin plate missing under hood**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Registration plate lamp shows direct white light to the rear (1.1.C.1f)**Fail** Rear registration plate deteriorated (6.3.1d)**Notice** EMISSIONS TO CLEAN TO DETECT

**MOT #6** 2011-01-06 10:56**MOT test number** 679896901050**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2010-01-19 11:41**MOT test number** 113399910433**Result** ✓ Passed**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #4** 2010-01-18 09:23**MOT test number** 704458710077**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #3** 2009-01-19 10:09**MOT test number** 211189619099**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #2** 2007-11-27 13:36**MOT test number** 510171937381**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a ball joint (2.4.G.2)



MOT #1	2007-01-27 09:55
MOT test number	171387427015
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 August
-------------------	----------------------

Days left	95
------------------	----

MOT expiry date	26 July 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 XXXXXX
Plate since	2024-03-28
Current registration	 XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-03-05
Last registration	2023-07-13
Complete history	See info



Registration #1	2004-03-05	27 mi
Registration #2	2007-01-27	65.079 mi
Registration #3	2007-11-27	80.363 mi
Registration #4	2009-01-19	83.235 mi
Registration #5	2010-01-18	84.983 mi
Registration #6	2010-01-19	84.997 mi
Registration #7	2011-01-06	90.142 mi
Registration #8	2012-01-23	92.041 mi
Registration #9	2012-01-23	92.041 mi
Registration #10	2013-01-09	93.493 mi
Registration #11	2014-01-13	96.983 mi
Registration #12	2015-01-20	98.077 mi
Registration #13	2016-01-22	98.502 mi
Registration #14	2016-01-22	98.502 mi
Registration #15	2016-01-22	98.502 mi
Registration #16	2016-01-22	98.502 mi
Registration #17	2016-01-22	98.502 mi
Registration #18	2016-01-22	98.502 mi
Registration #19	2016-01-22	98.502 mi
Registration #20	2016-01-22	98.502 mi
Registration #21	2016-01-22	98.502 mi
Registration #22	2016-01-22	98.502 mi
Registration #23	2016-01-22	98.502 mi
Registration #24	2016-01-22	98.502 mi
Registration #25	2016-01-22	98.502 mi



Dimensions & weight

Width	1933 mm
Kerb weight	2090 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	4
Number of axles	2
Engine number	61198150828212