



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Silver
Year of manufacture	-
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	165 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.8 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-02-21
Pictures	12
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

---



MOT #17	2023-06-13 10:31
MOT test number	747980989830
Result	✗ Failed

- Advice** Nearside Rear Lower Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- Advice** Plastic covers on both outer sills
- Fail** Offside Rear Lower Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Fail** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Fail** Nearside Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- Advice** Fuel pipes corroded
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Seat belt anchorage prescribed area is corroded but not considered excessive (7.1.1 (a) (i))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Rear Shock absorbers has negligible damping effect (5.3.2 (d))

**MOT #16**

2022-02-12 14:06

**MOT test number**

300279131404

**Result**

✓ Passed

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive front and rear, nearside and offside and also front sub frame (5.3.6 (a) (i))

**Advice** Offside Rear Fuel Pipe/s corroded

**MOT #15**

2022-02-09 12:30

**MOT test number**

350139086432

**Result**

✗ Failed

**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail** Rear Exhaust has a major leak of exhaust gases back box (6.1.2 (a))

**Advice** Offside Rear Fuel Pipe/s corroded

**Advice** Suspension component mounting prescribed area is corroded but not considered excessive front and rear, nearside and offside and also front sub frame (5.3.6 (a) (i))

**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #14**

2021-03-29 15:07

**MOT test number**

606758174394

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #13**

2021-03-29 15:07

**MOT test number**

195076031754

**Result**

✗ Failed

**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #12** 2020-03-02 11:06**MOT test number** 470877015597**Result** ✓ Passed

**Advice** Nearside Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2019-03-11 13:32**MOT test number** 815254969690**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear tyre worn slightly on edge

**MOT #10** 2019-03-11 10:13**MOT test number** 107905696221**Result** ✗ Failed

**Fail** Brake fluid significantly below minimum mark (1.1.10 (d) (ii))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear tyre worn slightly on edge

**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #9** 2018-09-22 09:07**MOT test number** 482211085843**Result** ✓ Passed**MOT #8** 2017-09-28 09:01**MOT test number** 865061954758**Result** ✓ Passed



<b>MOT #7</b>	2016-09-27 14:15
<b>MOT test number</b>	863266997530
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2015-09-12 09:17
<b>MOT test number</b>	784345770290
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2014-09-22 09:48
<b>MOT test number</b>	247905364282
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2013-09-21 10:53
<b>MOT test number</b>	448344463208
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2012-09-29 12:10
<b>MOT test number</b>	559563472297
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2011-09-22 13:51
<b>MOT test number</b>	199475661202
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2010-08-09 11:31
<b>MOT test number</b>	390411820468
<b>Result</b>	✓ Passed





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-09-07
Last registration	2023-06-13
Complete history	<a href="#">See info</a>



Registration #1	2007-09-07	17 mi
Registration #2	2010-08-09	6.966 mi
Registration #3	2011-09-22	13.380 mi
Registration #4	2012-09-29	20.861 mi
Registration #5	2013-09-21	27.365 mi
Registration #6	2014-09-22	33.884 mi
Registration #7	2015-09-12	39.953 mi
Registration #8	2016-09-27	47.609 mi
Registration #9	2017-09-28	55.631 mi
Registration #10	2018-09-22	64.531 mi
Registration #11	2019-09-22	73.431 mi
Registration #12	2020-09-22	82.331 mi
Registration #13	2021-09-22	91.231 mi
Registration #14	2022-09-22	100.131 mi
Registration #15	2023-06-13	109.031 mi
Registration #16	2023-06-13	117.931 mi
Registration #17	2023-06-13	126.831 mi
Registration #18	2023-06-13	135.731 mi
Registration #19	2023-06-13	144.631 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1655 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1512 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 20217257