





report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER VX
Colour	Silver
Year of manufacture	2001
Top speed	109 mph
0 - 60 mph	11.7 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	232 BHP
Max. torque	434 Nm at 3.400 rpm
Engine capacity	4.686 cc
Cylinders	8
Fuel type	Petrol
Consumption city	12.6 mpg
Consumption extra urban	21.2 mpg
Consumption combined	17.0 mpg
CO2 emission	405 g/km
CO2 label	M



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 1

Date 2021-12-06

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/15



Y846VDA report date: 2024-03-29

MOT history

MOT expiry date	2024-08-07
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	52
Total items failed	6

MOT #22		2023-08-08 16:05
MOT test	number	385822684671
Result		✓ Passed
Next expi	ry date	2024-08-07
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely de	eteriorated (6.1.7 (g) (i))
Advice	Offside Front Anti-roll bar pin or bush worn but not resulting in excessive	ve movement (5.3.4 (a) (i))
Advice (i))		
Advice (i))		
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely det	eriorated (6.1.7 (g) (i))
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in ex	xcessive movement (5.3.4

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #21 2023-08-08 16:05 **MOT** test number 398359221682 Result × Failed **Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Pass with rectification Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii)) **Advice** Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #20		2021-10-28 08:42
MOT test	number	754950563718
Result		× Failed
MAJOR significan	Nearside Rear Outer Suspension component mounting prescribed area excessive tly reducing structural strength sill (5.3.6 (a) (i))	ely corroded
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light	t sources (4.7.1
Advice	Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT #19 2020-11-13 14:59 MOT test number 346471006229

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18 2020-11-13 11:10

MOT test number 643252570820

Result X Failed

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Rear Coil spring corroded (5.3.1 (b) (i))

Advice

Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #17 2019-10-21 15:39 819413082390 **MOT** test number Result ✓ Passed **Advice** Nearside front brake pipe corroded. **Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Slight exhaust blow offside manifold area. Minor Brake pipe inadequately clipped or supported front to rear (1.1.11 (d) (i)) Minor Nearside Registration plate lamp insecure (4.7.1 (c) (i))

MOT #16 2019-10-17 13:19 **MOT** test number 426488388308 Result **X** Failed Minor Brake pipe inadequately clipped or supported front to rear (1.1.11 (d) (i)) **MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i)) Minor Nearside Registration plate lamp insecure (4.7.1 (c) (i)) **Advice** Slight exhaust blow offside manifold area. Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) **Advice** Nearside Front Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) **Advice** Nearside front brake pipe corroded.

 MOT #15
 2018-09-04 12:30

 MOT test number
 808626137584

 Result
 ✓ Passed

CarCheck.co.uk page 6/15



report date: 2024-03-29

MOT #14 2017-08-11 16:04

MOT test number 693175019056

Result ✓ Passed

MOT #13 2017-08-11 12:02

MOT test number 520045967178

Result X Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Fail Nearside Headlamp aim too high (1.8)

MOT #12 2016-09-09 14:05

MOT test number 667526386423

Result \rightarrow Passed

MOT #11 2015-09-08 16:10

MOT test number 903044657929

MOT #10 2015-09-08 13:27

MOT test number 318028113647

Result X Failed

Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

CarCheck.co.uk page 7/15



report date: 2024-03-29

MOT test number

Result

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Rear position lamp(s) has a product on the lens but not adversely affecting light output (1.1.A.3d)

Advice Centre Brake pipe slightly corroded (3.6.B.2c)

MOT #8

MOT test number

Result

Notice N/s/r light is broken

MOT #7

MOT test number

Result

MOT #6

MOT test number

2011-06-10 17:15

MOT test number

196881761151

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #5
 2010-05-28 12:54

 MOT test number
 861578840162

 Result
 ✓ Passed

 MOT #4
 2009-05-14 11:48

 MOT test number
 172144339141

 Result
 ✓ Passed

CarCheck.co.uk page 8/15



Advice

Rear brake disc slightly pitted (3.5.1h)

Y846VDA report date: 2024-03-29

 MOT #3
 2008-03-06 09:18

 MOT test number
 214736868023

 Result
 ✓ Passed

 MOT #2
 2007-03-09 12:24

 MOT test number
 521558567097

 Result
 ✓ Passed

MOT #1	2006-03-08 11:14
MOT test number	631507966014
Result	✓ Passed

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



Y846VDA report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



Y846VDAreport date: 2024-03-29

Owner history

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owners have? Check it in the premium report and see all owner registrations. Download the full re		DTA

THE STATE OF THE S		

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK C	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 12/15



Y846VDA report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2001-03-01
Last registration	2023-08-08
Complete history	See info



Registration #1	2001-03-01	21 mi
Registration #2	2006-03-08	64.677 mi
Registration #3	2007-03-09	72.122 mi
Registration #4	2008-03-06	79.680 mi
Registration #5	2009-05-14	85.110 mi
Registration #6	2010-05-28	87.572 mi
Registration #7	2011-06-10	90.063 mi
Registration #8	2012-07-13	92.208 mi
Registration #9	2013-08-02	92.987 mi
Registration #10	2014-09-04	94.364 mi
Registration #11	2015-09-08	95.511 mi
Registration #12	2015-09-08	95.511 mi
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		71.777 es
Registration #19		11.777 es
Registration #20		71.777 es
Registration #21		71.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es

More info >



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1940 mm
Height	1890 mm
Length	4890 mm
Wheel base	2850 mm
Kerb weight	2465 kg

Additional information

Fuel tank capacity	96
Fuel delivery	Multi-Point Injection
Number of doors	5
Engine number	2UZ9028980

CarCheck.co.uk page 15/15