



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ CRTD CDX
Colour	Blue
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	235 Nm at 2.750 rpm
Engine capacity	1.493 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-25
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-15
MOT pass rate	61 %
MOT passed	14
Failed MOT tests	9
Total advice items	60
Total items failed	7

MOT #23	2023-09-16 12:01
MOT test number	844554552879
Result	✓ Passed
Next expiry date	2024-09-15
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))

MOT #22	2023-09-16 12:01
MOT test number	485780892232
Result	✗ Failed
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Pass with rectification	Offside Front Seat belt installation has a rail or other harsh object fitted without suitable padding as required (10.1 (j))
Advice	Rear Coil spring corroded both sides (5.3.1 (b) (i))
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #21**

2022-06-28 08:49

**MOT test number**

166306016988

**Result**

✓ Passed

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing nearside & offside (5.2.3 (d) (ii))
- Advice** Service brake pedal has travel
- Advice** Nearside Rear Shock absorbers has light misting of oil ON LIMIT (5.3.2 (b))
- Advice** Rear Coil spring corroded nearside & offside (5.3.1 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front moisture at hub
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #20**

2022-06-22 08:41

**MOT test number**

519050205270

**Result****✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Tyre slightly damaged/cracking or perishing nearside & offside (5.2.3 (d) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Service brake pedal has travel
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Offside Front Steering locking device missing track rod end castellated nut split pin (2.1.3 (d))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil ON LIMIT (5.3.2 (b))
- Advice** Rear Coil spring corroded nearside & offside (5.3.1 (b) (i))
- Advice** Offside Front moisture at hub
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- MAJOR** Nearside Front Steering locking device missing track rod end castellated nut split pin (2.1.3 (d))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #19**

2021-07-13 08:56

**MOT test number**

312026927969

**Result****✓ Passed**

- Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #18** 2021-07-13 08:56**MOT test number** 879206872698**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #17** 2020-09-28 10:35**MOT test number** 285109674482**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. both sides (1.4.2 (a) (i))**MOT #16** 2020-09-28 10:21**MOT test number** 962800178740**Result** ✗ Failed**MAJOR** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #15** 2019-08-31 15:44**MOT test number** 152852344736**Result** ✓ Passed**Advice** Clutch biting point very low

**MOT #14**

2019-08-30 14:55

**MOT test number**

969825556337

**Result****✗ Failed****Advice** Clutch biting point very low**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Headlamp aim too high (4.1.2 (a))**MOT #13**

2018-09-28 11:11

**MOT test number**

199514956715

**Result****✓ Passed****Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #12**

2017-09-23 15:15

**MOT test number**

228967019222

**Result****✓ Passed****MOT #11**

2016-08-31 08:56

**MOT test number**

753276823816

**Result****✓ Passed****Advice** Nearside Rear Tyre worn close to the legal limit 175/65R14 (4.1.E.1)**Advice** Nearside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Wiper split

**MOT #10** 2015-09-02 07:42**MOT test number** 649102392080**Result** ✓ Passed**MOT #9** 2014-09-04 08:48**MOT test number** 758527744270**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #8** 2014-09-04 08:48**MOT test number** 787697844260**Result** ✗ Failed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #7** 2013-09-13 10:05**MOT test number** 379126753201**Result** ✓ Passed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #6** 2013-09-13 10:05**MOT test number** 656696653273**Result** ✗ Failed**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2012-09-20 09:42**MOT test number** 917994262276**Result** ✓ Passed



**MOT #4** 2012-09-20 09:42**MOT test number** 519294362210**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #3** 2011-09-09 13:27**MOT test number** 467862351271**Result** ✓ Passed**Notice** Rear brake discs corroded and pads low**MOT #2** 2011-09-06 09:25**MOT test number** 689689441247**Result** ✗ Failed**Notice** Rear brake discs corroded and pads low**Fail** Nearside Rear rear brake binding (3.7.B.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #1** 2010-09-11 10:20**MOT test number** 712994650254**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
15 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	15 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	DN57KKC
Plate since	2019-09-28
Current registration	DN57KKC
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-29
Last registration	2023-09-16
Complete history	<a href="#">See info</a>



Registration #1	2007-09-29	18 mi
Registration #2	2010-09-11	28.174 mi
Registration #3	2011-09-06	36.646 mi
Registration #4	2011-09-09	36.692 mi
Registration #5	2012-09-20	47.091 mi
Registration #6	2013-09-13	58.049 mi
Registration #7	2014-09-04	66.639 mi
Registration #8	2015-09-02	75.323 mi
Registration #9	2016-08-31	84.590 mi
Registration #10	2017-09-23	91.403 mi
Registration #11	2018-09-28	98.358 mi
Registration #12	2019-09-28	98.358 mi
Registration #13	2020-09-28	98.358 mi
Registration #14	2021-09-28	98.358 mi
Registration #15	2022-09-28	98.358 mi
Registration #16	2023-09-28	98.358 mi
Registration #17	2024-09-28	98.358 mi
Registration #18	2025-09-28	98.358 mi
Registration #19	2026-09-28	98.358 mi
Registration #20	2027-09-28	98.358 mi
Registration #21	2028-09-28	98.358 mi
Registration #22	2029-09-28	98.358 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1112 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5



<b>Number of axles</b>	2
<b>Engine number</b>	D4FA7U117601