



 **K54LEU**

report date: 2024-03-29

General information

Make	LAND ROVER
Model	DEFENDER TDI HT
Colour	Red
Year of manufacture	1992
Gearbox	-Manual

Engine & fuel consumption

Power	107 BHP
Engine capacity	2.495 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-05-17
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-09-17
Pictures	13
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-09-01
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	110
Total items failed	46



<b>MOT #19</b>	2021-09-02 11:22
<b>MOT test number</b>	260670254963
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-01
<b>Advice</b>	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
<b>Advice</b>	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
<b>Advice</b>	Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Coil spring corroded all (5.3.1 (b) (i))
<b>Advice</b>	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
<b>Advice</b>	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
<b>Advice</b>	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
<b>Advice</b>	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Underside of vehicle has been undersealed
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
<b>Advice</b>	Nearside Front Upper shock absorber mounting starting to corrode

**MOT #18**

2021-08-24 16:37

**MOT test number**

936996282464

**Result****✗ Failed**

- Advice** Nearside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Coil spring corroded all (5.3.1 (b) (i))
- Advice** Underside of vehicle has been undersealed
- Fail** Nearside Front Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Upper Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))
- Fail** Offside Front Upper Suspension component mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #17**

2021-05-25 12:32

**MOT test number**

641443170602

**Result****✗ Failed**

- Fail** Offside Front Direction indicator not working (4.4.1 (a) (ii))
- Fail** Offside Front Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting (6.2.2 (d) (i))
- Fail** Rear Electrical wiring for braking components extremely deteriorated (4.11 (b) (iii))
- Minor** Front Window damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Rear Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Front Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Semaphore indicator switch inoperative (4.4.2 (a) (ii))
- Fail** Nearside Front Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting (6.2.2 (d) (i))
- Fail** Brake fluid contaminated (1.8 (a))
- Advice** Under the car sprayed
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Rear Electrical wiring insulation in such a condition there is an imminent risk of fire or formation of sparks (4.11 (c) (iii))
- Minor** Fuel pipe chafing (6.1.3 (c) (i))
- Fail** Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen Both (3.5 (a))
- Fail** Front Brake hose ferrule excessively corroded and likely to fail Both (1.1.12 (f) (ii))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Coil spring corroded All X4 (5.3.1 (b) (i))

**MOT #16**

2015-11-20 17:08

**MOT test number**

141918393559

**Result**

✓ Passed

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #15**

2015-11-18 10:50

**MOT test number**

643657480832

**Result**

✗ Failed

**Fail** Offside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings floor (6.1.B.2)**Fail** Vehicle structure excessively corroded within 30cm of towbar mounting (6.6.6)**Fail** Offside Drag link end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Fail** Power steering component(s) leaking from a failed seal steering box (2.3.3b)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings floor (6.1.B.2)**Fail** Offside Front Stub axle has excessive vertical movement between stub axle and axle beam (2.5.A.1a)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Fail** Offside Drag link end ball joint has excessive play (2.2.B.1f)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)



MOT #14

2014-11-17 14:56

MOT test number

727031024358

Result

✓ Passed

- Advice

Offside Front Brake pipe slightly corroded (3.6.B.2c)
- Advice

Offside Rear Shock absorber has a slightly worn bush (2.7.4)
- Notice

Corrosion to parts of underside of vehicle
- Advice

Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)
- Advice

Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
- Notice

Oil leak

MOT #13

2013-11-07 16:37

MOT test number

705911613397

Result

✓ Passed

- Notice

Both front drive spheres leaking
- Notice

Underside of vehicle covered in mud
- Notice

O/s/f tyre low on inner edge



**MOT #12**

2013-11-07 09:53

**MOT test number**

668241013344

**Result****✗ Failed****Notice** Underside of vehicle covered in mud**Notice** O/s/f tyre low on inner edge**Fail** Nearside Front Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Notice** O/s/f brake pads getting low**Notice** Both front drive spheres leaking**Fail** Offside Front Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.2.C.1c)**Fail** Offside Front Radius arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #11**

2012-11-14 10:12

**MOT test number**

116829212323

**Result****✓ Passed****Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Oil leak**Notice** Underside of vehicle covered in mud

**MOT #10**

2012-11-14 08:54

**MOT test number**

737409412377

**Result**

✗ Failed

**Fail** Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Oil leak**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Underside of vehicle covered in mud**MOT #9**

2011-11-14 09:52

**MOT test number**

157178711370

**Result**

✓ Passed

**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Drag link end ball joint has slight play (2.2.B.1f)**Notice** Offside outer track rod end joint cover split/missing**MOT #8**

2010-10-19 11:46

**MOT test number**

802102690271

**Result**

✓ Passed

**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Notice** General corrosion to underside of vehicle**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Leak from rear axle**Advice** Offside Brake pipe slightly corroded (3.6.B.2c)

**MOT #7** 2009-11-10 13:54**MOT test number** 973734219335**Result** ✓ Passed**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #6** 2009-11-10 10:51**MOT test number** 934124919341**Result** ✗ Failed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2008-11-12 14:02**MOT test number** 864977718326**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

**MOT #4**

2008-11-12 09:02

**MOT test number**

284257418311

**Result****✗ Failed****Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Notice** Coolant leak**Fail** Offside Rear wheel bearing has excessive play (2.6.2)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #3**

2007-08-08 09:57

**MOT test number**

503690427257

**Result****✓ Passed****Advice** Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2

2006-07-27 11:29

MOT test number

160408506222

Result

✓ Passed

- Notice

Brake pedal anti slip wearing thinn
- Notice

Possible oil leak at offside rear hub
- Advice

Offside Seat belt damaged but not affecting the operation of the belt (5.2.2a)
- Notice

Minimal reserve travel on handbrake
- Advice

Offside Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Steering moderately heavy in operation
- Advice

Rear wheel bearing has slight play (2.6.2)
- Notice

Front brakes slightly out of balance
- Advice

Nearside Seat belt damaged but not affecting the operation of the belt (5.2.2a)
- Notice

Handbrake grabbing/juddering in operation
- Advice

Nearside Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice

Slight play in steering box
- Advice

Nearside Front Shock absorber has a light misting of oil (2.7.3)



MOT #1 2006-07-21 09:47

MOT test number 893272206249

Result ✗ Failed

**Advice** Nearside Seat belt damaged but not affecting the operation of the belt (5.2.2a)

**Fail** Lower Steering column universal joint has excessive play (2.1.5)

**Notice** Slight play in steering box

**Advice** Offside Rear rear brake grabbing slightly (3.7.A.5b)

**Advice** Nearside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)

**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**Advice** Rear wheel bearing has slight play (2.6.2)

**Notice** Possible oil leak at offside rear hub

**Fail** Nearside Front Upper Steering pivot point has excessive play (2.2.B.1g)

**Notice** Minimal reserve travel on parking brake

**Advice** Offside Seat belt damaged but not affecting the operation of the belt (5.2.2a)

**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)

**Advice** Offside Front Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

**Advice** Front wheel bearing has slight play (2.5.A.3c)

**Fail** Offside Front Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

**Notice** Handbrake grabbing/juddering in operation



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	K54LEU
Plate since	2024-03-29
Current registration	K54LEU
Plate since	2024-03-29

More info >





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	1992-08-01
Last registration	2021-09-02
Complete history	<a href="#">See info</a>



Registration #1	1992-08-01	10 mi
Registration #2	2006-07-21	208.004 mi
Registration #3	2006-07-27	208.192 mi
Registration #4	2007-08-08	218.997 mi
Registration #5	2008-11-12	229.481 mi
Registration #6	2008-11-12	229.482 mi
Registration #7	2009-11-10	236.893 mi
Registration #8	2009-11-10	236.895 mi
Registration #9	2010-10-19	244.845 mi
Registration #10	2011-11-14	254.090 mi
Registration #11	2012-11-14	263.874 mi
Registration #12	2013-05-20	263.874 mi
Registration #13	2013-05-20	263.874 mi
Registration #14	2013-05-20	263.874 mi
Registration #15	2013-05-20	263.874 mi
Registration #16	2013-05-20	263.874 mi
Registration #17	2013-05-20	263.874 mi
Registration #18	2013-05-20	263.874 mi
Registration #19	2013-05-20	263.874 mi
Registration #20	2013-05-20	263.874 mi
Registration #21	2013-05-20	263.874 mi
Registration #22	2013-05-20	263.874 mi

More info >



Additional information

Fuel delivery	Direct Injection
Engine number	11L17336A